GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001.

No. F.6/DFS/MS/EH/2021/SZ/ 88

Dated: 5/4/2/

FIRE SAFETY CERTIFICATE

Certified that the **M/s Spinns Restaurant** is running at ground floor only, building is comprised of ground plus two upper floors at G-2A & G-2B, Sonia PVR Complex, Vikas Puri, New Delhi-110018, owned/ occupied by M/s Spinns Restaurant. Sonia PVR Complex building was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/2018/SZ/27 dated 02/01/2018. The building was re-inspected by the officers concerned of this department on 19/02/2021 in the presence of Sh. Ramesh (Sr.Manager) and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (at ground floor only) is fit for occupancy class Group "D" Assembly building w.e.f. the date of issue of this certificate for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 subject to the conditions printed overleaf.

Issued on.....at New Delhi.

(Sunil Chawdhary) Dy. Chief Fire Officer

Copy to:-

- D.H.O, West Zone, S.D.M.C, Public Health Department, Vishal Enclave, Rajouri Garden, New Delhi-110027
- 2. The Manager, M/s Spinns Restaurant, G-2A & G-2B, Ground Floor Only, Sonia PVR Complex, Vikas Puri, New Delhi-110018.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

1		M/s Spinns Restaurant, G-2A & G-2B, Ground Floor Only, Sonia							
		PVR Complex, Vikas Puri, New Delhi-110018. G+2 upper floors but restaurant running at ground floor only							
	2. Building comprised of :	G+2 upper floors but restaurant running at ground floor only Group D (Assembly Building)							
	3. Type of Occupancy : 4. Type of Case :	Renewal							
	5. Details of Previous NOC :	F6/DFS/MS/EH/2018/SZ/27 dated 02/01/2018							
		N/A 19/02/2021 A.D.O. R.K. Yadav							
	7. Date of inspection :								
	8. Name of Inspecting Officers :								
	9. Name and designation of officers	of the production of the produ							
	From the building side : Sh. Ramesh (Sr.Manager)								
	10. Year of Construction :	2011							
	11. Applicant's letter No.			09377 dated 08/02/202					
S.	Minimum Standards on fire prevention	and fire	Requirement		Remarks				
No.	safety U/R 33			site	MR/NMR				
1.	Access to building				*				
	2 1 111	1	Accessible (09 n	ntrs) 09 mtrs	MR				
	Road width		4.5 mtrs	Directly accessible	MR				
	Gate width		06 mtrs	from internal road	MR				
	Width of internal road			Provided	1.22				
2.	Number, Width, Type & Arrangement	of Exits							
		R.		(Res	taurant is at GF only)				
	a. Number of staircases								
	 Upper Floors 		N/A	N/A	N/A				
	Basements		N/A	N/A	N/A				
	b. Width of staircases		N/A	N/A	N/A				
	 Upper Floor 		14	N/A	N/A				
	Basements		N/A	N/A	IN/A				
	c. Protection of exits								
	Fire check door		N/A	N/A	N/A				
	 Pressurization 		N/A	N/A	N/A				
	d. No. of continuous staircases to		N/A	N/A	N/A				
	terrace		N/A	Opening in	N/A				
	e. Width of Corridor		14/71	hall					
	f. Door Size		02 M	2.0, 1.25 & 1.25 M	MR being old				
	1. Door Size			(including frames)	case				
3.	Compartmentation			2	(Restaurant is at				
٥.	Compartmentation				GF only)				
	Fire check door		N/A	N/A	N/A				
	 Sealing of electrical shafts 		N/A	N/A	N/A				
	 Fire Rating of shaft door 		20 CS 20	N/A	N/A				
	Water Curtain		N/A		TORREST SECTION TO SEC				
	• Fire Dampers		N/A	N/A	N/A				
	, , , , , , , , , , , , , , , , , , ,		N/A	N/A	N/A				
4.	Smoke Management System			(D	(CF or by)				
			DI/A		taurant is at GF only) N/A				
	Basements		N/A	N/A	IN/A				
			NI/A	N/A	N/A				
	Upper floors		N/A	IN/A	IV/A				
5.	Fire Extinguishers	-	0.137	D +1 1	MD				
	Total numbers		04 No.'s	Provided	MR				
	TypesIS marking		ABC/CO ₂	Tiovided	MR				
			ISI marke	d ISI marked	MR				
6.	First-Aid Hose Reels	151 market							
0.	THE TAIL HOSE INCEIN			(=====					
	Total numbers on ground floor		One	Provided	MR				
	Length of hose reel hose		30 mtrs	Provided	MR				
			5 mm	Provided	MR				
	Nozzle diameter								
	A to the detection and clarming								
	to the time detection and alermine	CVCTOIN							

	Type of detectors	N/A	N/A	N/A				
	 Location of Main Panel 	N/A	N/A	N/A				
	 Location of Repeater Panel 	N/A	N/A	N/A				
1 40	Alternate source of power	N/A	N/A	N/A				
	Hooters' Location	N/A	N/A	N/A				
8.	MOEFA	Required	Provided	MR				
9.	Public Address System	Required	Provided	MR				
10.	Automatic Sprinkler System	rant is at GF only)						
	Basement	N/A	N/A	N/A				
	Ground Floor	Required	Provided	MR				
	Sprinkler above false ceiling	N/A	N/A	N/A				
11.	Internal Hydrants (Restaurant is at GF only							
	Size of riser/down-comer	100 mm	Provided	MR				
	Number of hydrants	01 No.	Provided	MR				
	Hose Box	01 No.	Provided	MR				
12.	Yard Hydrants							
	Total number of hydrants	N/A	N/A	N/A				
*	Hose Box	N/A	N/A	N/A				
13.	Pumping Arrangements		mon with Sonia P					
15.	Ground Level	(com	mon with Soma P	vk Complex)				
	Discharge of main Pump	2280 LPM	Provided	MR				
	➤ Head of Main pump							
	Number of main pumps	70 mtrs	Provided	MR				
	> Jockey Pump out put	One	Provided	MR				
	> Jockey pump head	220 LPM	Provided	MR				
	Jockey pump nead	70 mtrs	Provided	MR				
	> Standby Pump out put	2280 LPM	Provided	MR				
	> Standby Pump Head	70 mtrs	Provided	MR				
	> Auto Starting/Manual Stopping	Required	Provided	MR				
	Dump House Access	Required	Provided	MR				
	Pump House AccessTerrace level							
	Discharge of pump	N/A	N/A	N/A				
	> Head of the pump	N/A	N/A	N/A				
	> Power Supply	N/A	N/A	N/A				
	➤ Auto Starting of pump	N/A	N/A	N/A				
14.	Captive Water Storage for fire fighting)						
	Underground tank capacity	130000	Provided	MR				
	> Draw-off connection	Required	Provided	MR				
	> Fire service inlet	Required	Provided	MR				
	> Access to tank	Required	Provided	MR				
	Overhead Tank capacity	10000	Provided	MR				
15.	Exit Signage.	Required	Provided	MR				
16.	Provision of Lifts.	Toquiru		nt is at GF only)				
10.	100 to 1 and the second of the	N/A	N/A	N/A				
	Pressurization of Lift ShaftPressurization of Lift lobby							
	Communication In lift Car	N/A N/A	N/A N/A	N/A N/A				
	Fireman's Grounding Switch							
	Lift Signage	N/A	N/A	N/A				
		N/A	N/A	N/A				
17.	Standby power supply	Required	Provided	MR				
18.	Refuge Area.		ALCOHOL: NEW YORK					
	➤ Total Area ➤ Location	N/A	N/A	N/A				
	Location	N/A	N/A	N/A				

	Detector System Panel	N/A	N/A	N/A
	 Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
-1-		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/EH/2018/SZ/27 dated 02/01/2018 renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended.

Signature of Inspecting Officer

Name:-R.K.Yadav

Designation:- Asstt. Divisional Officer

DO(South West) what about the file of comia for complex?

The properties of Some PUR Complex (Copy) to placed at C-25 is the file. and its Unlocking to who three years from the date fine doc. 21/10/2020. The inverse years from the date fine doc. 21/10/2020. The inverse less bounded please

DO(South West)

Do (April 1982)

Do (A