C-24 (-21

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

No: F.6/DFS/MS/SCHOOL/2021/ 3/

Dated:/ 7 / 4 /2021

FIRE SAFETY CERTIFICATE

Certified that the Blooming Public School, located at Rajendra Park, Rohtak Road, Nangloi, New Delhi comprised of **Ground plus Three upper floors**, was Granted FSC by this department Vide letter No. F6/DFS/MS/School/2016/1012 dated 10/06/2016. The premises was re-inspected by the officer concerned of this department on 23/03/2021 in the presence of Sh. Bhram Dev Dabas (Chairman)of the school and found that said school Building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular dated17/01/2005and that the building/premises is fit for occupancy class "Educational" Group -B as above with effect from 7/42/2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Dharampal Bhardwaj) Dy.Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Principal, Blooming Public School Rajendra Park, Rohtak Road, Nangloi, New Delhi.
- 2. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

Following fire safety directives must be adhered to:-

- 1. 1 All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

1	Name	e & Address of the Building	Blooming Dales Public School located at Rajendra Park, Rohtak Park, Rohtak Road, Nangloi, New Delhi				
2	Туре	of Occupancy	Group-B, "Educational Building" (School)				
3	Build	ing Comprised of	Ground plus three upper floors				
4	Type	of Case	Renewal				
5	Detail	ls of Previous NOC	F.6/DFS/MS/School/WZ/2016/1012 dated 10/06/2016				
6	Fire S	afety Directives Letter No	DOE Circular dated 17/01/2005				
7		of Inspection	23.03.2021				
8		of the Inspecting Officers	ADO Aman Kumar Lathar				
9		& Designation of Officers	Sh. Bhram Dev Dabas				
		the building side	Sii. Billaili Dev Dabas				
10	Year	of construction	2006				
11	Appli	cant letter No.	Email date 18/03/2021				
S. No		num standards on Fire Prevention ire Safety U/R 33	DOE Circular date 17/01/2015 Requirements	Provided at Site	Remarks MR/NMR (old case)		
1	Access to Building.						
	•	Road width	06 m	On main rohtak road	MR		
	•	Gate width	4.5 m	4.5 m	MR		
	•	Width of internal road	-N/A-	-N/A-	-N/A-		
2	Numb	per, width, type & arrangement		1771	11111		
	a) Number of Staircase						
	>	Upper floors	2	2	MR		
	>	Basement floor	-N/A-	-N/A-	-N/A-		
	b) Width of Staircase		-14/71	-1V/A-	-11/74		
	D	Upper floor	Old case	1.30 m & 1.110 m	MR(old case)		
	>	Basement floor	-N/A-				
	-) D		-IN/A-	-N/A-	-N/A-		
	c) Protection of exits Fire check door		27/4	27/4			
	A D	Pressurization	-N/A-	-N/A-	-N/A-		
	I) N		-N/A-	-N/A-	-N/A-		
3		o. of continuous staircase to	Old case	1	MR		
	e) Width of corridor		Old case	1.50 m	MR		
	f) Do	or size	Old case	1.0 m	MR		
3	Comp	partmentation.			11111		
	•	Fire check door.	-N/A-	-N/A-	-N/A-		
	•	Sealing of electrical shafts.	-N/A-	-N/A-	-N/A-		
	•	Fire rating of shaft door.	-N/A-	-N/A-	-N/A-		
	•	Water curtain	-N/A-	-N/A-	-N/A-		
	•	Fire dampers.	-N/A-	-N/A-	-N/A-		
4.	Smok	e Management system.	14/12	-1 1/1 1	-1 M LT-		
	•	Basement	-N/A-	-N/A-	-N/A-		
	•	Upper floors	-N/A-	-N/A-	-N/A-		
5.	Fire F	xtinguishers.	~ '' * *	-1 N/ LY-	-1 N/ Z\-		
	•	Total numbers	00	10 nos	MR		
	•	Types	08 nos ABC/CO ₂	Provided	MR		
	•	ISI Marking			MR		
6.	• ISI Marking ISI Marking Provided First Aid Hose Reels.						
	• Total numbers on each floor. 1 MR						

7	Automatic fire detection & alarming	system.					
	Type of detectors	-N/A-	-N/A-	-N/A-			
	• Location of Main Panel	-N/A-	-N/A-	-N/A-			
	Location of Repeater Panel	-N/A-	-N/A-	-N/A-			
	Alternate source of powerHooter's location	-N/A-	-N/A-	-N/A-			
	• Hooter's location	-N/A-	-N/A-	-N/A-			
8.	MOEFA	-N/A-	-N/A-	-N/A-			
9.	Public Address System	-N/A-	-N/A-	-N/A-			
10.	Automatic Sprinkler System	9					
	Basement.	-N/A-	-N/A-	-N/A-			
	• Upper floors	-N/A-	-N/A-	-N/A-			
	Sprinkler above false ceiling	-N/A-	-N/A-	-N/A-			
11.	Internal Hydrants.	1					
	Size of Riser / Down-comer	100 mm	100 mm	MR			
	 Number of Hydrant per floor 	1	1	MR			
	 Hose box. 	1	1	MR			
12.	Yard Hydrants.	1	1				
	Total number of hydrants.	-N/A-	-N/A-	-N/A-			
	Hose box.	-N/A-	-N/A-	-N/A-			
13.	Pumping arrangements.	1,11,1		1011			
	Ground Level						
	Ground Bever	-N/A-	-N/A-	-N/A-			
	Discharge of main pump.	-N/A-	-N/A-	-N/A-			
	Head of main pump.	-N/A-	-N/A-	-N/A-			
V	Number of main pumps.Jockey Pump output.	-N/A-	-N/A-	-N/A-			
	> Jockey Pump head.	-N/A-	-N/A-	-N/A-			
	Standby Pump output.	-N/A-	-N/A-	-N/A-			
	Standby Pump head.	-N/A-	-N/A-	-N/A-			
	Auto Starting/Manual stopping. Pump house access.	-N/A-	-N/A-	-N/A-			
	7 I ump nouse access.	-N/A-	-N/A-	-N/A-			
	Terrace Level	11/11	11/11	11/12			
	Discharge of pump.	450 LPM & 180 LPM	900 LPM & 180 LPM	MR			
	Head of pump.	40 m	40 m	MR			
	Power supply.	Required	Provided	MR			
	Auto starting of pump.	Required	Provided	MR			
14.	Captive water storage for firefightin	g.					
	 Underground tank capacity. 	-N/A-	-N/A-	-N/A-			
	Draw-off connection.	-N/A-	-N/A-	-N/A-			
	Fire Service Inlet.	Required	Provided	MR			
	Access to tank.	-N/A-	-N/A-	-N/A-			
ě	Overhead tank capacity.	Old case	5,000 ltrs	MR			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.		- I				
•	Pressurization of lift shaft.	-N/A-	-N/A-	-N/A-			
	 Pressurization of lift lobby. 	-N/A-	-N/A-	-N/A-			
	Communication in lift car.	-N/A-	-N/A-	-N/A-			
	• Fireman's switch.	-N/A-	-N/A-	-N/A-			
	Lift signage.	-N/A-	-N/A-	-N/A-			
17	Standby Power Supply	NI/A	NI/A	NI/A			

-N/A-	-N/A-
-N/A- -N/A- -N/A	-N/A- -N/A- -N/A- -N/A- -N/A-
	-N/A- -N/A-

The fire protection system provided in the building were randomly tested/ checked and found functional at the time of inspection. The shortcoming

issued F/6/DFS/MS/School/2019/7364 dated 11/12/2019 has been compiled by the building management.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no. F.6/DFS/MS/School/WZ/2016/1012 dated 10/06/2016, renewal under rule 37 of the

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name

: Aman Kumar Lather

Designation:

ADO (JWP)