GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2021 / 2 4 4

Dated: 04/ 05/2021

FIRE SAFETY CERTIFICATE

Certified that the M/s Hari Consolidated Pvt. Ltd. located at Plot. No. A- 64/3, industrial Area G. T. Karnal Road, Delhi-110033 comprised of basement+ mezz+ 01 upper floor owned/occupied by M/s Hari Consolidated Pvt. Ltd. issued Fire Safety Certificate for ground floor only by this department vide this office letter no. F6/DFS/MS/2018/WZ/1197 dated 23.05.2018. The premise was re-inspection by the officer concerned of this department on 15.04.2021 in presence of Sh. Raman Kr. Saluja (Owner) and observed that all the fire prevention and fire safety arrangements as provided found in good working condition, premises have thee for deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and building premises is fit for occupancy class G-2 "industrial building" for basement, ground, mezzanine, & one upper floor only with effect from Oxido School 2.1. for a period of three years, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 04/05/202). at New Delhi by

(Dharampal Bhardwaj) Dy. Chief Fire Officer Ph-011-25156707

ole la

Copy to:-

1. The Manager, Hari Consolidated Pvt. Ltd., Plot no A64/3, Industrial Area, G. T. Karnal Road, Delhi-110033.

Conditions for the validity of Fire Safety Certificate:

- All the means of escape/entry/exit shall be kept free from any obstruction.
- 2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3 All the staff members must know the correct method of operation of firefighting system.
- The owner / occupier shall submit a declaration **every year** in **Form "K"** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- 5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building: Hari Consolidated Pvt. Ltd., Plot no. A64/3., G.T K. Road, Industrial Area.

Delhi-110033.

2. Type of Occupancy : Industrial Building (Basement, Ground, Mazz. & first floor)

Type of Case 3.

: Renewal

Details of previous NOC

: F6/DFS/MS/2018/WZ/1197 Dated 23.05.2018

Fire Safety directives letter No

Date of inspection

: 15.04.2021

7. Name of the Inspecting Officers : ADO (RN)

8. Name and designation of officers

from the building side

: Sh. Raman Kumar Saluja / Owner

9. Year of Construction

: prior to 1983

10. Applicant's letter No.

: Online E-mail ID Dated- 09.04.2021

D M C (Drainage)

Provided at site

Remarks

Plot A	ea- 537sqm
S.no.	Minimum Standards on fire prevention and fire safety U/R 33
1	Aggest to building

	fire safety U/R 33	Bye Laws 1959	1 Tovided at Site	MR/NMR		
1	Access to building	1				
	Road width	6m	6m	MR		
	Gate width	Accessible	Directly Accessible	MR		
	Width of internal road	NA	NA	NA		
	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors	02	02	MR		
	Basements	02	02	MR		
	b. Width of staircases					
	Upper FloorsBasements	4'6" (1.37 m) each	1.37m each	MR		
		4'6" (1.37 m) each	1.37m each	MR		
	c. Protection of exits					
	Fire check door	Required	Provided	MR		
	Pressurization	NA	NA	NA		
	d. No. of continuous staircases to terrace	01	01	MR		
	e. Width of Corridor	NA	NA	NA		
	f. Door Size	1.0m	1.0m	MR		
3	Compartmentation.					
	Fire check door	Required	Provided	MR		
	Sealing of electrical shafts	Required	Provided	MR		
	Fire Rating of shaft door	Required	Provided	MR		
	Water Curtain	NA	NA	NA		
	Fire Dampers	NA	NA	NA		
	Smoke Management System.					
	Basements	12 a/c per hour	Axial Fan	MR		
	• Upper floors	12 a/c per hour	Natural Ventilated	MR		
	Fire Extinguishers					
	Total numbers	14nos	14nos	MR		
	• Types	ABC/CO2	ABC	MR		

	151 marking	ISI Marked		
	6 First-Aid Hose Reels.		Yes	MR
	Total numbers on each floor	Required		
	 Length of hose reel hose 		Provided	MR
	Nozzle diameter	30m	Provided	MR
	Automatic fire detection and alarming system	5mm	Provided	MR
	Type of detectors	Required		17/11
	 Location of Main Panel 	Ground Floor	Provided	MR
	 Location of Repeater Panel 	Each Floor	Provided	MR
	Alternate source of power		Provided	MR
	Hooters' Location	Required	Provided	MR
-	MOEFA MOEFA	Each Floor	Provided	MR
1	Tublic Address System.	Required	Provided	MR
1	Automatic Sprinkler System.	NA	NA	NA
	Basement	Required	Provided	
	Upper Floor	Required	Provided	MR
1	Sprinkler above false ceiling	NA		MR
1	internal riyurants	INA	NA	NA
	Size of riser/down-comer	Required	Provided	
	Number of hydrants per floorHose Box	Required	Provided	MR
12	Yard Hydrants	Required	Provided	MR
	Total number of hydrants		Tiovided	MR
	Hose Box	NA	NA	NA
10		NA	NA	NA
13	Pumping Arrangements.			INA
	Ground Level			
	Discharge of main Pump			
	Head of Main pump	1620 lpm	1620 lpm	MR
	Number of main pumps	60m	60m	MR
	> Jockey Pump out put	01	01	MR
	> Jockey pump head	180lpm	1801pm	MR
	Standby Pump out put	60m	60m	MR
	Standby Pump Head	1620 lpm	1620 lpm	MR
	Auto Starting/Manual stopping	60m Required	60m	MR
	Pump House Access	Required	Provided	MR
	Terrace level			
	Discharge of pump	900 lpm	900 lpm	MR
	➤ Head of the pump	40mtr		IVIK
	Power Supply	Required	40mtr	MR
	Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for fire fighting.	1	Provided	MR
	Underground tank capacityDraw-off connection	25,000 ltr	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
		Required	Provided	MR
15	Overhead Tank capacity Exit Signal	15,000 ltr	15,000 ltrs	MR
	Exit Signage.	Required	Provided	
16	Provision of Lifts.			MR

	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate issued vide this department letter of even no. 1197 dated 23.05.2018 under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name: - C.L. Meena Designation:- ADO/RN

As approved, F.T. letter is Patup For your singuature Pl.