

434

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**


No. F.6/DFS/MS/EH/SZ/2021/ 104

Dated. 20/04/2021

FIRE SAFETY CERTIFICATE

Certified that **M/s Home (Unit of PVR Limited)** located at **3rd floor at Ambience Mall**, Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070 was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/2018/SZ/1041 dated 14/05/2018. The restaurant premise was re-inspected by the officer concerned of this department on 12/04/2021 in the presence of Mr. Ashish (Manager) & Mr. Amit Tyagi and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy **Class D "Assembly Building"** (Restaurant at 3rd floor) as above with effect from 20/04/2021 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 20/04/2021 at New Delhi by


(Sunil Chawdhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to: -

1. The Joint C.P (Lic) 1st Floor, PS Defence Colony, New Delhi 110049.
2. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi- 110016.
3. M/s Home (Unit of PVR Limited) located at 3rd floor at Ambience Mall, Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

1	Name & Address of the Building	M/s Home (A Unit of PVR Ltd.,) Formerly Mistral Restt. 3 rd floor at Ambience Mall, Plot No. 2, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070		
2	Type of Occupancy	Assembly Building "Group-D" Restaurant		
3	Building Comprised of	Three tier Basement, Ground + 03 upper floors		
4	Type of Case	Renewal		
5	Details of Previous NOC	F6/DFS/MS/EH/2018/SZ/1041 dated 14/05/2018		
6	Fire Safety Directives Letter No	F.6/DFS/MS/Mall/2020/SZ/56 Dated 21/01/2020 (Ambience Mall NOC)		
7	Date of Inspection	12/04/2021		
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Ashish (Manager) & Mr. Amit Tyagi		
10	Year of construction	2008	Restaurant running at 3 rd Floor in Ambience Mall building.	
11	Applicant letter No.	Gmail dated 17/03/2021		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR
1	Access to Building. FSC No.F.6/DFS/MS/Mall/2020/SZ/56 Dated 21/01/2020 of Ambience Mall			
	• Road width	Restaurant	As above	MR
	• Gate width	within Mall	As above	N/A
	• Width of internal road	NA	As above	N/A
2	Number, width, type and arrangements of exits.			
	a. Number of Staircase	Provided & Maintained by Ambience Mall		
	• Upper floors	02 Nos	As above	MR
	• Basement floor	N/A	As above	N/A
	b. Width of Staircase	Provided & Maintained by Ambience Mall		
	• Upper floors	Required	As above	MR
	• Basement floor	N/A	As above	N/A
	c. Protection of exits	Provided & Maintained by Ambience Mall		
	• Fire check door	Required	As above	MR
	• Pressurization	N/A	As above	N/A
	d. No. of continuous staircase to terrace	Required	As above	MR
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	Required	1.50 m	NMR
3	Compartmentation.	Provided & Maintained by Ambience Mall		
	• Fire check door.	Required	As above	MR
	• Sealing of electrical shafts.	N/A	As above	N/A
	• Fire rating of shaft door.	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	N/A
4.	Smoke Management system.	Provided & Maintained by Ambience Mall		
	• Basement	N/A	As above	N/A
	• Upper floors	Required	Exhaust fans provided	MR
5.	Fire Extinguishers.			
	• Total numbers	12 Nos	12 Nos.	MR
	• Types		ABC-04, W.CO ₂ -02	MR
	• ISI Marking	ISI marked	Provided	MR
6.	First Aid Hose Reels.	Provided & Maintained by Ambience Mall		
	• Total numbers on each floor.		One in Restaurant	MR
	• Length of hose-reel hose.	Hose Reel	30m	MR
	• Nozzle Diameter		5mm	MR

7	Automatic Fire Detection and Alarming system. (Provided & Maintained by Ambience Mall)			
	• Type of detectors	Required	Smoke & Heat	MR
	• Location of Main Panel	Required	As above	MR
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	Required	As above	MR
	• Hooter's location	Required	As above	MR
8.	MOEFA	Required	As above	MR
9.	Public Address System	Required	As above	MR
10.	Automatic Sprinkler System			
	Provided & Maintained by Ambience Mall			
	• Basement	Required	As above	MR
	• Upper floors	Required	Provided in Restt.	MR
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.			
	Provided & Maintained by Ambience Mall			
	• Size of Riser/Down-comer	Required	As above	MR
	• Number of Hydrant per floor	Required	As above	MR
	• Hose box.	Required	As above	MR
12.	Yard Hydrants.			
	Provided & Maintained by Ambience Mall			
	• Total number of hydrants.	N/A	As above	N/A
	• 2. Hose box.	N/A	As above	N/A
13.	Pumping arrangements.			
	Provided & Maintained by Ambience Mall			
	• Ground Level			
	➤ Discharge of main pump.	4500 LPM	As above	MR
	➤ Head of main pump.	70 mtr	As above	MR
	➤ Number of main pumps.	Two	As above	MR
	➤ Jockey Pump output.	4500 LPM	As above	MR
	➤ Jockey Pump head.	70 mtr	As above	MR
	➤ Standby Pump output.	4500 LPM	As above	MR
	➤ Standby Pump head.	70 mtr	As above	MR
	➤ Auto Starting / Manual Stopping.	Required	As above	MR
	➤ Access to pump house	Required	As above	MR
	• Terrace Level	Provided & Maintained by Ambience Mall		
	➤ Discharge of pump.	N/A	N/A	N/A
	➤ Head of pump.	N/A	N/A	N/A
	➤ Power supply.	N/A	N/A	N/A
	➤ Auto starting of pump.	N/A	N/A	N/A
14.	Captive water storage for Fire Fighting.			
	Provided & Maintained by Ambience Mall			
	• Underground tank capacity.	5,00,000 Ltrs	As above	MR
	➤ Draw-off connection.	Required	As above	MR
	➤ Fire Service Inlet.	Required	As above	MR
	➤ Access to tank.	Required	As above	MR
	• Overhead tank capacity.	20,000 Ltrs	As above	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	Provided & Maintained by Ambience Mall			
	• Pressurization of lift shaft.	N/A	N/A	N/A
	• Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided (DG Set)	MR
18.	Refuge Area			
	Provided & Maintained by Ambience Mall			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19.	Fire Control Room.			
	Provided & Maintained by Ambience Mall			

	<ul style="list-style-type: none"> Flow Switch Panel. PA system Panel. Battery backup Building floor plan 	N/A	As above	N/A
		N/A	As above	N/A
		N/A	As above	N/A
		N/A	As above	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any :	N/A	As above	N/A

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2018/SZ/1041 dated 14/05/2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

The copy of email was not received by the undersigned.

However, case is being forwarded please.

Signature of the Inspecting Officer
 Name: Rajesh Kumar
 Designation: ADO / BCP

RK
12/04/2021

DO (SD)

RK
12/04/21

DO (SD)

[Signature]

F.T.

ADO/BCP

As approved, F.T. letter is put up for your signature pl.

10/4
19/04/2021

DO (SD)
[Signature]

M.S. *[Signature]*