GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/2021/ School/ 3,37

Dated: 19./04/2021

FIRE SAFETY CERTIFICATE

Certified that the **Bal Mandir Public School** located at **Pushpa Bhawan**, **Arakshan Road**, **Pahar Ganj**, **New Delhi** comprises of **Ground** + **03 Upper floors**, **the said school is running at Ground floor only** owned/occupied by Bal Mandir Public School was granted FSC by this department vide letter No. **F6/DFS/MS/School/2018/NDZ/600 dated 06/04/2018**. The premises was re-inspected by the officer concerned of this department on 12-04-2021 in the presence of Mrs. Indra Verma and found that school have deemed complied with the fire prevention and fire safety requirements in accordance with **Circular No. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01/03/2011** issued by Director of Education and the building premises is fit for occupancy of class **Group B** "**Educational Building**" **Sub-Div. B-I** with effect from ------2016 for a period of **three years** subject to compliance of the conditions mentioned below:

Issued on 19 04 2021 at New Delhi by.

(Dr.S.K. Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- The Principal,
 Bal Mandir Public School at Pushpa Bhawan, Arakshan Road, Pahar Ganj,
 New Delhi.
- 2. Director of Education, Govt. of NCT, Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. This FSC is valid for school at ground floor only.

Bhawan, Arakashan Road, Pahar Ganj, New Delhi. Educational Group B-I, Gr. + 03 Upper floors, 2. Type of occupancy:-School running at Ground Floor Only Renewal 3. Type of case:-No. F6/DFS/MS/School/2018/NDZ/600 4. Details of previous FSC:dated 06/04/2018. 5. Fire safety directives No.-N/A 6. Date of inspection:-12/04/21 Sh. Ravinder Singh (ADO/CC) 7. Name of the inspecting officer:-8. Name & designation of officer Mrs. Indra Verma From the building side:-9. Year of construction:-Old e- mail < balmandirschoolpganj@gmail.com 10. Applicant's letter No:dated 24.03.21 Old Case Requirement Provided at site Remarks Minimum Standards on fire S.No. Exiting fire safety Prevention and fire safety U/R MR/NMR arrangements Access to Building 1. 1) Road width 06 mtr. 06 mtr. MR NA 05 mtr. 2) Gate width Required NA NA NA 3) Width of internal road Number, Width Type & Arrangement of Exits 2. A. Number of staircases N/A N/A N/A 1. Upper floors N/A N/A 2. Basements N/A B. Width of staircase N/A N/A N/A 1. Upper floors N/A N/A N/A 2. Basements C. Protection of exits N/A N/A N/A 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous staircase to terrace MR E. Width of corridor 1.25 mtr. 1.25 mtr. MR 1.25 mtr. 1.25 mtr. F. Door size Compartmentation 3. N/A N/A 1) Fire check door N/A N/A N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A 4) Water curtain N/A N/A N/A N/A N/A 5) Fire Dampers Smoke Management System 4. N/A N/A N/A 1) Basements N/A N/A N/A 2) Upper floors Fire Extinguishers 5. MR 04 Nos. 02 Nos. 1) Total numbers

INSPECTION REPORT

1. Name & address of the building:-

Bal Mandir Public School at Pushpa

	(a) (E)	ABC	C & CO2	ABC	C, CO2 & W.CO2	MF		
	2) Types		narked	Pro	ovided	MF	2	
	3) ISI marking	1011						
6.	First-Aid Hose Reel 1) Total number of each N/A			N/	A	N/.	A	
	1)Total number of each	14/13						
	floor 2) Length of hose reel hose	N/A		N/	A	N/		
	3) Nozzle diameter	N/A		N/	A	N/	Α	
	Automatic Fire Detection & A							
7	1) Type of detectors	1	N/	'A	N			
	2) Location of main panel	N/A		N/	'A		/A	
	3) Location of repeater panel	N/A		N	'A		/A	
	4) Alternate source of power	N/A		N	/A		/A	
	5) Hooter's Location	N/A		N.	/A		/A	
0		N/A		N/A		N/A		
8.	MOEFA Public Address System	N/A		N	/A	N	/A	
9.	Public Address System							
10.	Automatic Sprinkler System 1) Posement N/A		4	N/A		N/A		
	1) Dascillett			N/A		N/A		
	2) Upper floors	N/		N/A		N	I/A	
	3) Sprinkler above false	1 4/ 2						
	ceiling			1904			V .	
11.	Internal Hydrants 1) Size of riser/down-comer N/A		A	N/A		N/A		
12.	1) Size of riser/down-comer		N/A		N/A		N/A	
	2) Number of Hydranes per							
		floor Note how Note		N	J/A	1	I/A	
	3) Hose box							
	Yard Hydrants		'A	I	V/A		V/A	
	1) Total number of hydrants	N		1	V/A	1	V/A	
	2) Hose box	14/	71		W 1			
13.	Pumping Arrangement		N/A		N/A	(le	N/A	
	1) Ground level		N/A		N/A		N/A	
	a) Discharge of main		11/11			101 101 101	N. C.	
	pump	n	N/A		N/A		N/A	
	b) Head of main pum	umn	N/A		N/A		N/A	
	c) Number of main p	N/A		N/A		N/A		
	d) Jockey pump out p	N/A	K.	N/A		N/A		
	e) Jockey pump nead	e) Jockey pump head		N/A			N/A	
	f) Stand by pump ou	ad	N/A		N/A N/A		N/A	
	g) Stand by pump head		N/A		N/A		N/A	
	h) Auto starting/Manual		14/11					
	stopping							
	2) Terrace level	N/A		N/A		N/A		
	a) Discharge of pum	N/A		N/A		N/A		
		b) Head of pump			N/A		N/A	
	c) Power supply	Power supply			N/A	1	N/A	
	d) Auto starting of p							
14	Captive Water Storage for Fire Fighting 1) Under ground tank N/A				N/A		N/A	
	1) Under ground tan	ıK.	IN/A				1 12	
	capacity							



	a) Draw-off connection	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	c) Access to tank	N/A	N/A	N/A		
	d) Over head tank capacity	N/A	N/A	N/A		
15.	Exit Signage.	N/A	N/A	N/A		
16.	Provision of Lifts.			2		
	a) Pressurization of lift shaft	N/A	N/A	N/A		
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	c) Communication in lift car	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	e) Lift signage	N/A	N/A	N/A		
17.	Stand by Power Supply	N/A	N/A	N/A		
18.	Refuge Area	N/A	N/A	N/A		
	Total area location	N/A	N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A		
	a) Detector system panel	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	e) Building floor plan	N/A	N/A	N/A N/A		
20.	Special Fire Protection System for Protection of special Risk, if any:					

The fire protection system provided in the school building were tested, checked at random and found functional at the time of inspection. Further, it is also to inform that other school naming Nav Shakti Sr. Secondary School, is also running in this building from first to third floor which does not have FSC from this department.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F6/DFS/MS/School/2018/NDZ/600 dated 06/04/2018, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended for approval please.

Signature of the Inspecting Officer

Name:- Ravinder Singh Designation :- A. D.O. (CC)