GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001**

No F6 / DFS / MS / School/2021/ 3 6 4

Dated: 10/5/2021

FIRE SAFETY CERTIFICATE

Certified that the M.C Primary Co-ed School located at Gopal Nagar, Kewal Park, Azadpur, Delhi-110033 comprised of Ground floor only owned/occupied by M.C Primary Co-ed School was granted FSC by this department vide letter no. No.F6/DFS/MS/SCHOOL/2018/WZ/747 dated 20.04.2018. The premises was re-inspected by the officer concerned of this department on 09.04.2018 in presence of Smt. Laxmi Sharma (Incharge) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class Group B Educational with effect from for a period of three years, subject to compliance of the conditions mentioned below:

(Dharampal Bhardwaj) Dy. Chief Fire Officer Ph.-011-25156707

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.

2. The Principal, M.C Primary Co-ed School, Gopal Nagar, Delhi-110033.

Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

All the staff members must know the correct method of operation of firefighting system.

The owner / occupier shall submit a declaration every year in Form "K" provided in the first available The form is 2010. Fire Service Rules of Delhi schedule http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

Name & address of the building 1. : M.C Primary Co-ed School, Gopal Nagar, Delhi-110033. 2. Type of Occupancy :Educational 3. Type of Case :Renewal (Ground floor only) 4. Details of previous NOC :F6/DFS/MS/School/2018/WZ/747 Dated: 20.04.2018 Fire Safety directives letter No 5. : Director of Education Circular dated 01.03.2011 6. Date of inspection : 16.04.2021 7. Name of the Inspecting Officers : ADO (RN) Name and designation of officers from the building side : Smt. Laxmi Sharma (Incharge) 9. Year of Construction : 2000 10. Applicant's letter No. : Online E-Mail ID dated: 13.04.2021 Plot Area- 490 m2 No of class rooms –06 nos. Covered Area: 342 m2 No of students---145nos. Minimum Standards on fire prevention and **NBC** Provided at site Remarks fire safety U/R 33 Requirement MR/NMR 1 Access to building Road width 06m 08m MR Gate width 4.5m 2.5m x02 MR(old case) Width of internal road NA NA NA 2 Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors NA NA NA Basements NA NA NA b. Width of staircases Upper Floors NA NA NA Basements NA NA NA c. Protection of exits Fire check door NA NA NA Pressurization NA NA NA d. No. of continuous staircases to terrace NA NA NA e. Width of Corridor NA NA MR f. Door Size 1 m 1m MR 3 Compartmentation. Fire check door NA NA NA NA NA Sealing of electrical shafts NA Fire Rating of shaft door NA NA NA Water Curtain NA NA NA Fire Dampers NA NA NA 4 Smoke Management System. 12 a/c per hour Basements NA NA Upper floors 12 a/c per hour NA NA . 5 Fire Extinguishers Total numbers 02nos 02nos MR ABC/Co2 ABC-02 MR Types ISI marking ISI Marked Provided MD

| | First-Aid Hose Reels. | | NA | NA |
|-----|---|----------|-------|----------|
| 6 F | Total numbers on each floor | NA | | NA |
| | Length of hose reel hose | NA | NA | |
| | Nozzle diameter | NA | NA | NA |
| - | Automatic fire detection and alarming system. | | NA | NA |
| 7 | Type of detectors | NA | NA | NA |
| | Location of Main Panel | NA | NA | NA |
| | Location of Repeater Panel | NA | | NA |
| | Alternate source of power | NA | NA | |
| | Hooters' Location | NA | NA | NA |
| | | NA | NA | NA |
| 8 | MOEFA | | | |
| 9 | Public Address System. | | | |
| 10 | Automatic Sprinkler System. | NA | NA | NA NA |
| | Basement | NA | NA | NA NA |
| | Upper Floor | NA | NA | NA |
| | Sprinkler above false ceiling | | | |
| 11 | Internal Hydrants | NA | NA | NA |
| | Size of riser/down-comer Section 1.1 Section 1.1 | NA | NA | NA |
| | Number of hydrants per floorHose Box | NA | NA | NA |
| | | | | |
| 12 | Yard Hydrants. | NA | NA | NA |
| | Total number of hydrants | | NA | NA |
| | Hose Box | NA | , 147 | |
| 12 | Pumping Arrangements. | | | |
| 13 | Lumburg 1411 | | | |
| | Ground Level | | N/A | N/A |
| | Discharge of main Pump | N/A | : | |
| | Head of Main pump | N/A | N/A | N/A |
| | > Number of main pumps | N/A | N/A | N/A |
| | Jockey Pump out put | NA | NA | NA |
| | > Jockey pump head | NA NA | NA | NA |
| | Standby Pump out put | | N/A | N/A |
| | > Standby Pump Head | N/A | | N/A |
| | > Auto Starting/ Manual stopping | N/A | N/A | |
| | > Pump House Access | N/A | N/A | N/A |
| | Terrace level Discharge of nump | | | |
| | Discharge of pumpHead of the pump | NA | NA | NA |
| | - Clv | NA | NA | NA |
| | a f numn | NA | NA | NA |
| | Auto Starting of pump | | NA | NA |
| | | NA | IVA | |
| 1. | 4 Captive Water Storage for fire fighting. | | NA | NA |
| 1. | Underground tank capacity | NA | | NA |
| | > Draw-off connection | NA | NA | NA NA |
| | > Fire service inlet | NA | NA | NA NA |
| | > Access to tank | NA | NA | |

| | Overhead Tank capacity | NA | NA | NA | | |
|----|--|-----|-----|-----|--|--|
| 5 | Exit Signage. | NA | NA | NA | | |
| 16 | Provision of Lifts. | | | | | |
| | Pressurization of Lift Shaft | N/A | N/A | N/A | | |
| | Pressurization of Lift lobby | N/A | N/A | N/A | | |
| | Communication In lift Car | N/A | N/A | N/A | | |
| | Fireman's Grounding Switch | N/A | N/A | N/A | | |
| | Lift Signage | N/A | N/A | N/A | | |
| 17 | Standby power supply | N/A | N/A | N/A | | |
| 18 | Refuge Area. | | | | | |
| | > Total Area | N/A | N/A | N/A | | |
| | > Location | N/A | N/A | N/A | | |
| 19 | Fire Control Room | | | | | |
| | Detector System Panel | N/A | N/A | N/A | | |
| | Flow Switch Panel | N/A | N/A | N/A | | |
| | PA System Panel | N/A | N/A | N/A | | |
| | Batter backup | N/A | N/A | N/A | | |
| | Building Floor Plans | N/A | N/A | N/A | | |
| 20 | Special Fire Protection Systems for Protection of special Risks, if any: | N/A | N/A | N/A | | |

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Director of Education Circular, the FSC issued vide letter of even no.747 dated 20.04.2018 renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended

Signature of the Inspecting Officer Name :- Rajesh Kumar

Designation:- ADO/RN

As approved, F.T. letter is futup for your singuatur 1.