GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6 DFS/MS/School/2021/WZ/ 374

Dated: | 0 | 572 |

Delhi Fire Ser

FIRE SAFETY CERTIFICATE

Certified that The Great India Educational Society located at Plot no. 2, Meera Bagh A- Block, Near Meera Bhawan, Paschim Vihar, New Delhi comprised of Basement, Stilt, Upper Ground, 1st & 2nd floor was inspected by the officer concerned of this department on 15/04/2021 in presence of Mr. Rahul (Manager) of the school and found that said school building have complied with the fire prevention and fire safety arrangements in accordance with rule 33 of Delhi Fire Service, 2010 and that the school building is fit for occupancy class "Education Building" Group—B, as above with effect from for period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 10 21 at New Delhi by

Copy to: -

- 1. The Authorised Signatory, The Great India Educational Society located at Plot no. 2, Meera Bagh A- Block, Near Meera Bhawan, Paschim Vihar, New Delhi.
- 2. The Directorate of Education, Old Secretariat, GNCT of Delhi, New Delhi-110006

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

1	Name &	& Address of the Building	A-Block, Near Meera Bhawan, Paschim Vihar, New Delhi-			
2	Type of	f Occupancy	Group-B, "Educational Building" (School)			
3	7 1	g Comprised of	Basement, Stilt, Upper Ground, 1 st & 2 nd floor			
4	Type of		New			
5		of Previous NOC	Nil			
6		fety Directives Letter No	F.6/DFS/MS/BP/2016/318 dated 07/12/2016			
7		Inspection	15/04/2021			
8		of the Inspecting Officers	ADO Aman Kumar Lathar			
9		& Designation of Officers	Mr. Rahul (Manager)			
		e building side	2016			
10		Construction	2016			
11		ant letter No.	Email dated 19/03/2021			
S. No		im standards on Fire Prevention e Safety U/R 33	NBC Requirements	Provided at Site	Remarks MR/NMR	
1	Access	to Building.				
	•	Road width	6 m	13 m	MR	
		Gate width	4.5 m	4.5 m	MR	
	•	Width of internal road	-N/A-	-N/A-	-N/A-	
2	Numb	er, width, type & arrangement	of exits.			
	a) Nu	mber of Staircase				
	>	Upper floors	02 nos	02 nos	MR	
	>	Basement floor	02 nos	02 nos	MR	
	b) Wi	dth of Staircase				
	>	Upper floor	$1.50 \times 1, 1.35 \times 1$	1.60 m × 2	MR	
	>	Basement floor	$1.50 \times 1, 1.35 \times 1$	1.60 m × 2	MR	
	c) Pro	tection of exits				
1	>	Fire check door	Required in basem	nent Provided	MR	
	>	Pressurization	-N/A-	-N/A-	-N/A-	
	,	of continuous staircase to	One	One	MR	
		dth of corridor	1.50 m	1.90 m	MR	
	f) Do	or size	1.0 m	1.25 m	MR	
3	Comp	artmentation.				
	•	Fire check door.	-N/A-	-N/A-	-N/A-	
	•	Sealing of electrical shafts.	-N/A-	-N/A-	-N/A-	
	•	Fire rating of shaft door.	-N/A-	-N/A-	-N/A-	
	•	Water curtain	-N/A-	-N/A-	-N/A-	
	•	Fire dampers.	-N/A-	-N/A-	-N/A-	
4.	Smoke	Management system.	*			
	•	Basement	Required	Provided	MR	
	•	Upper floors	-N/A-	-N/A-	-N/A-	
5.	Fire E	Fire Extinguishers.				
		Total numbers	12 nos	16	MR	
	•	Types	ABC/CO ₂	Provided	MR	
		ISI Marking	ISI Marking	Provided	MR	
6.	First A	Aid Hose Reels.				
	•	Total numbers on each floor.	One	Provided 02 nos	MR	
	•	Length of hose-reel hose.	30 m	30 m	MR	
			0			

	7	Automatic fire detection & alarming system.			
		Type of detectors	-N/A-	-N/A-	-N/A-
1		 Location of Main Panel 	-N/A-	-N/A-	-N/A-
		Location of Repeater Panel	-N/A-	-N/A-	-N/A-
		Alternate source of power	-N/A-	-N/A-	-N/A-
		Hooter's location	-N/A-	-N/A-	-N/A-
-	8.	MOEFA	-N/A-	Provided	-N/A-
	9.	Public Address System	-N/A-	-N/A-	-N/A-
+	10.	Automatic Sprinkler System	14/11	11/11	14/11
-	200	Basement.	Required in Basement	D 111	MD
		• Upper floors	and stilt floor	Provided	MR
1		 Sprinkler above false ceiling 	-N/A-	-N/A-	-N/A-
			-N/A-	-N/A-	-N/A-
	11.	Internal Hydrants.			
		Size of Riser / Down-comer	-N/A-	100 mm	-N/A-
		Number of Hydrant per floorHose box.	-N/A-	1	-N/A-
		Tiose box.	-N/A-	1	-N/A-
	12.	Yard Hydrants.			
-		Total number of hydrants.	-N/A-	-N/A-	-N/A-
		Hose box.	-N/A-	-N/A-	-N/A-
-	13.	Pumping arrangements.			
-		Ground Level			
		Discharge of main pump.	2280 LPM	Provided	MR
		Head of main pump.	70 m	Provided	MR
1		Number of main pumps.	One	One	MR
		> Jockey Pump output.	180 LPM	Provided	MR
		Jockey Pump head.	40 m	Provided	MR
+		Standby Pump output.	2280 LPM	Provided	MR
		> Standby Pump head.	70 m	Provided	MR
1		Auto Starting/Manual stopping.Pump house access.	Required	Provided	MR
			Required	Provided	MR
		• Terrace Level	0001701	D 11.1	
		Discharge of pump.Head of pump.	900 LPM	Provided	MR
		Head of pump.Power supply.	40 m	Provided	MR
		> Auto starting of pump.	Required	Provided	MR
	11		Required	Provided	MR
	14.	Captive water storage for firefighting.			
		• Underground tank capacity.	1,00,000 ltrs	Provided	MR
		Draw-off connection.Fire Service Inlet.	-N/A-	-N/A-	-N/A-
		Access to tank.	-N/A-	-N/A-	-N/A-
		Overhead tank capacity.	-N/A-	-N/A-	-N/A-
			15,000 ltrs	20,000 ltrs	MR
	15.	Exit Signage.	Required	in Provided	MR
	16.	Provision of Lifts. Two lifts are provided basement to upper floors			
		Pressurization of lift shaft.	-N/A-	-N/A-	-N/A-
		Pressurization of lift lobby. Communication in lift communication in lift communication.	-N/A-	-N/A-	-N/A-
		Communication in lift car.Fireman's switch.	-N/A-	-N/A-	-N/A-
		• Lift signage.	Required	Provided	MR
			Required	Provided	MR
	17	Standby Power Supply	Required	Provided	MR

0					
18.	Refuge A	rea	-N/A-	-N/A-	-N/A-
	• T	otal area	-N/A-	-N/A-	-N/A-
		ocation	-14/11		
19.		itrol Room.	-N/A-	-N/A-	-N/A-
	• D	etector System Panel.	-N/A-	-N/A-	-N/A-
		low Switch Panel.	-N/A-	-N/A-	-N/A-
		A system Panel. Battery backup	-N/A-	-N/A-	-N/A-
	· H	Building floor plan	-N/A-	-N/A-	-N/A-
	-			-N/A-	-N/A-
20.	Special	Fire Protection System for	-N/A-	-14/11	
	the Pro	tection of special Risk, if any.			

Note: Two lift provided in basement found sealed with brick wall.

The Fire protection systems provided in the premises were checked / operated at random and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 37 of the Delhi Fire Service Rules 2010.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

: Aman Kumar Lathar

ADO (JWP) Designation:

DO (WD)