GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6 / DFS / MS / 2021 / 380

1

Dated: 20 / 05/2021

FIRE SAFETY CERTIFICATE

Certified that the Yash Vidya Public School located at Pepsi Road, Harit Vihar, Sant Nagar, Burari, Delhi-110084 comprised of Ground and 03 upper floors owned/ occupied by Yash Vidya Public School was issued Fire Safety Certificated vide this office letter no. F-6/DFS/MS/2018/1380 dated 13.06.2018 (ground + two upper floors) The premise was reinspected by the officer concerned of this department on 16.04.2021 in the presence of Mr. Dilawar Singh (Chairmen) and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under Educational "Group B" with effect from .20.05.2021. for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on .. 20 05 20 21 ... at New Delhi

Director Ph:-011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi – 110054.

2. The Principal, Yash Vidya Public School, Pepsi Road, Harit Vihar, Sant Nagar, Burari, Delhi-110084..

Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building : Yash Vidya Public School, Pepsi Road, Harit Vihar, Sant Nagar, Burari,

Delhi-110084.

2. Type of Occupancy

: Educational

3. Type of Case

: Add/Alt (Ground+03 Upper floors)

4. Details of previous NOC

: F-6/DFS/MS/2018/1380 dated 13/06/2018 (Ground+02 upper floor)

5. Fire Safety directives letter No

: NBC Part-4

6. Date of inspection

: 16.04.2021

7. Name of the Inspecting Officers

: ADO (RN)

8. Name and designation of officers

from the building side

: Mr. Dilawar Singh (Chairmen)

9. Year of Construction

: 2003, 2006 & 2019

10. Applicant's letter No.

: letter no. YVPS/Fire Certificate/2021-22/01 dated 01.04 2021

	Area-2500 m2 Covered Area:1804 m2 Minimum Standards on fire prevention and		class rooms –27nos, str				
	fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR			
1	Access to building						
	Road width	6m	6 m	MR			
	• Gate width	4.5m	04m x2	MR (old case			
	Width of internal road	NA	NA	NA			
2	Number, Width, Type & Arrangement of Exit	S		- A			
	a. Number of staircases			10			
	Upper Floors	02	02	MR			
	Basements	NA	NA	NA			
	b. Width of staircases						
	Upper Floors	1.50m	1.78m & 1.50m	MR			
	Basements	NA	NA	NA			
	c. Protection of exits						
	Fire check door	NA	NA	NA			
	Pressurization	NA	8				
	d. No. of continuous staircases to terrace	02	NA 02	NA MR			
	e. Width of Corridor	NA	NA NA				
	f. Door Size	1 m & 1.2 Mtr for 3 rd floor	1.12 m & 1.2 m	NA MR			
3	Compartmentation.						
	Fire check door	NA	NA	NA			
	Sealing of electrical shafts	NA	NA	NA			
	Fire Rating of shaft door	NA •	NA	NA			
	Water Curtain	NA	NA	NA			
	Fire Dampers	NA	NA	V 2010.1849			
	Smoke Management System.	IVA	INA	NA			
	Basements	12 a/c per hour	NA	NA			
	• Upper floors	12 a/c per hour	Natural Ventilation	MR			
i.	Fire Extinguishers						
	Total numbers	12 nos	14 nos	MR			
	• Types	ABC/Co2	ABC-12 / Co2- 2	MR			
	ISI marking	ISI Marked	Yes	MR			

	First-Aid Hose Reels.	01	01	MR		
	Total numbers on each floor		30m	MR		
	• Length of hose reel hose	30m		MR		
	Nozzle diameter	5mm	5mm	IVIIC		
	Automatic fire detection and alarming system.	NA	NA *	NA		
	Type of detectors	NA	NA	NA		
	Location of Main Panel	NA	NA	NA		
	Location of Repeater Panel		NA	NA		
	Alternate source of power	NA				
	Hooters' Location	NA	NA	NA		
	MOEFA	NA	NA	NA		
	Public Address System.	, NA	NA	NA		
	Automatic Sprinkler System.	•				
	Basement	NA	NA	NA NA		
	VI Elean	NA	NA	NA NA		
	folio gailing	NA	NA	INA		
			- I			
	Internal Hydrants • Size of riser/down-comer	100mm	100mm	MR		
	 Size of riser/down-comer Number of hydrants per floor 	01	01	MR		
	Hose Box	01	01	MR		
	Yard Hydrants.					
2		NA	NA	NA		
	Total number of hydrants	NA	NA	NA		
	Hose Box	INA		2		
3	Pumping Arrangements.					
3						
	Ground Level		N/A	N/A		
	> Discharge of main Pump	N/A				
	➤ Head of Main pump	N/A	N/A	N/A		
	> Number of main pumps	N/A	N/A	N/A		
	> Jockey Pump out put	. N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put		N/A	N/A		
	Standby Pump Head	N/A		N/A		
	Auto Starting/ Manual stoppingPump House Access	N/A	N/A			
	Terrace level	N/A	N/A	N/A		
	> Discharge of pump	450lpm	450lpm	MR		
	➤ Head of the pump	40m	40m	MR		
	> Power Supply	Required	Provided	MR		
	> Auto Starting of pump	Required	Provided	MR		
14	Captive Water Storage for fire fighting					
14		NA	NA	NA		
	Underground tank capacity	NA	NA	NA		
	> Draw-off connection	NA NA	NA	NA		
	> Fire service inlet	NA NA	NA	NA		
	> Access to tank	. INA		1.00		
	Overhead Tank capacity	10,000 ltrs	10,000ltrs	MR		

- X

16	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
7	Standby power supply	N/A	N/A	N/A		
8	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
9	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Director of Education Circular / NBC Part 4, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. 1380 dated 13.06.2018 (ground + 02 upper floors).

Signature of the Inspecting Officer

Name: - C.L. Meena

Designation:- ADO/RN

As approved F.T. letter is Putup For your