GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/School/2021/ 330

Dated: 16/4/21

FIRE SAFETY CERTIFICATE

Certified that the Govt Girls Sr.Sec.School, at Mandoli Ext. Delhi-110093 comprised of ground plus three upper floors (New Building block) owned/occupied by Govt. Girls Sr.Sec.School was issued FSC vide letter No. F6/DFS/MS/School/2018/NDZ/448 Dated 19/03/18 (New Building blocks). The school building was re-inspected by the officer concerned of this department in the presence of Mr.Sanjay Tyagi, Estate Manager of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and observed that the school building is fit for occupancy class "B" 'Educational Building' for ground plus three upper floor with effect from 16.19. In for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, subject to conditions, printed overleaf.

Note:- This Fire Safety Certificate does not cover the Old building blocks for which shortcomings were issued earlier vide letter No. F6/DFS/MS/School/2017/226 dated 24/01/17.

(**Dr.S.K.Tomar**)

Dy. Chief Fire Officer

To.

The Principal, Govt.Girls Sr.Sec School, Mandoli Ext., Delhi-110093

Copy:-

The Dy. Director of Education, B- Block, Yamuna Vihar, Delhi-110053

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

1. Name & address of the building

2. Building is comprised of

3. Type of Occupancy

4. Type of Case

5. Details of Previous NOC letter

Fire Safety direction letter No

7. Date of Inspection

8. Name of the Inspecting officers

9. Name and designation of Officer from the building side

10. Year of Construction

11. Applicant's letter No

: Govt.Girls Sr.Sec.School, Mandoli Ext., Delhi-110093

: Ground plus three upper Floors (New Building)

: Educational

: Renewal : F6/DFS/MS/School/2018/NDZ/448 Dt.19/03/2018

: NBC Part-IV

: 23/03/21

: ADO Mehmood

: Mr. Sanjay Tyagi (Estate Manager)

: 2017

: E-mail Dated 10/03/2021

	Minimum Standards on Fire	NBC	Provided at Site	Remarks MR/NMR				
r.	Prevention and Fire Safety U/R33	Requirement						
0.	Access to Building							
1		06 mtr.	18 mtr.	MR				
	Road width	4.5 mtr	4.5 mtr					
	Gate width	N/A	N/A	N/A				
	Width of internal road	nent of Exits						
)2	Width of internal road Number, Width, Type and Arrangement of Exits							
	a. Number of Staircases		02 nos.	MR				
	Upper floor	02 nos.	N/A	N/A				
	• Basement	N/A	1 1 1					
	B. Width of Staircases	4 50 matr	1.75 mtr each.	MR				
	Upper floor	1.50 mtr. N/A	N/A	N/A				
	Basement	N/A						
	c. Protection of Exits	N/A	N/A	N/A				
	Fire check door	N/A	N/A	N/A				
	Pressurization	01 nos	01 nos.	MR				
	d. No. of Continuous Staircases	011105	1 9					
	to Terrace	1.50 mtr.	1.72 mtr.	MR				
	e. Width of Corridor	01 mtr.	01 mtr.	MR				
	f. Door Size	OT mu.						
	Compartmentation.		B	N/A				
03		N/A	N/A	N/A				
	Fire check door	N/A	N/A	N/A				
	Sealing of electrical shafts	N/A	N/A	N/A				
	Fire rating of shaft door	N/A	N/A	N/A				
	 Water curtain 	N/A	N/A	14//				
	Fire dampers							
04	Smoke Management System.	N/A	N/A	N/A				
	Basement	N/A	N/A	N/A				
	 Upper floor 	1977						
05.	= Camichore	*	20 nos.	MR				
00	Total numbers	12 nos.	170 100	MR				
		ABC /CC	2	MR				
	TypesIS marking	ISI marke	ed 151 market					

() -

0

)6	First-Aid-Hose Reels.			\$1 V					
	Total numbers on each floor	01 nos	01 nos	MR					
	 Length of hose reel hose 	30 mtr	30 mtr.	MR					
	Nozzle diameter	5 mm	05 mm	MR					
)7	Automatic Fire Detection and Alarming S	ystem.							
	= C. I. I. along	N/A	N/A	N/A					
	I of main nanol	N/A	N/A	N/A					
	if to	N/A	N/A	N/A					
	All de la contract of power	N/A	N/A	N/A					
	 Alternate source of power Hooter's location 	N/A	N/A	N/A					
08	MOEFA	N/A	N/A	N/A					
09	Public Address System.	N/A	N/A	N/A					
10	Automatic Sprinkler System.								
10		N/A	N/A	N/A					
	Basement	N/A	N/A	N/A					
	upper floor	N/A N/A	N/A	N/A					
	sprinkler above false ceiling	IN//A	14// \						
11	Internal Hydrants		244	A I / A					
	size of riser/down-comer	N/A	N/A	N/A					
	 Number of hydrants per floor 	N/A	N/A	N/A					
	Hose box	N/A	N/A	N/A					
12	Yard Hydrants.								
	Total number of hydrants	N/A	N/A	N/A					
	Hose box	N/A	N/A	N/A					
13	Pumping Arrangements.								
	> Ground Level								
	Discharge of main pump	N/A	N/A	N/A					
	Head of main pump	N/A	N/A	N/A					
	Number of main pumps	N/A	N/A	N/A					
	Jockey pump out put	N/A	N/A	N/A					
	 Jockey pump head 	N/A	N/A	N/A					
	Standby pump out put	N/A	N/A	N/A					
	Standby pump head	N/A	N/A	N/A					
	Auto starting /manual stopping	N/A	N/A	N/A					
	Pump house access	N/A	N/A	N/A					
	> Terrace Level								
	Discharge of pump	450 lpm	450 lpm	MR					
	Discharge of partie	40 mtr	Provided	MR					
	Head of the pump	Required	Provided	MR					
	Power supply	Required	Provided	MR					
	Auto starting of pump								
14									
	Fighting.	NI/A	N/A	N/A					
	 Underground tank capacity 	N/A	N/A N/A	N/A					
	 Draw-off connection 	N/A	N/A N/A	N/A					
	 Fire service inlet 	N/A Paguired	Provided	MR					
	Access to tank	Required	Provided	MR					
	Overhead tank capacity	10,000 ltrs	Provided	MR					
15	Exit Signage.	Required	FIOVIDED	1411					

16	Provision of Lifts.						
	Pressurization of lift shaft	N/A	N/A	N/A			
 Pressurization of lift lobby Communication in lift car Firemen's grounding switch Lift signage 		N/A	N/A	N/A			
	 Firemen's grounding switch 	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
17	Standby Power Supply	N/A	N/A	N/A			
18	Refuge Area.						
	Total area	N/A	N/A	N/A			
	 Location 	N/A	N/A	N/A			
19	Fire Control Room						
	Detector system panel	N/A	N/A	N/A			
	Flow switch panel	N/A	N/A	N/A			
	PA system panel	N/A	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
	Building floor plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of Special Risks, if Any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rule, it is recommended to issue Fire Safety Certificate.

Signature of the Inspecting Officer

Name

:- Mehmood

Designation

:- A.D.O (T.Pur)

Recd. m 5/4/4

Dyefo(NDZ) 2, Pl. ensure file is pur up noon after signature.

DO(ED)

A DOCTO)
Sis, I of Cot Julia pul my for Lignerton Abane

James

J

M.S.Cell