C\54

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2021/SZ/ 10 6

Dated: 21/04/2021

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s Orient Tavern Restaurant (A Unit of Triumph Resorts Pvt. Ltd, 7 & 8, CSC, DDA Market, First Floor, Sector-D, Pocket – IV, Vasant Kunj, New Delhi 110070 comprised of ground plus one upper floors. The restaurant running at First floor only of the building have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 15/03/2021 in the presence of Mr. Amit Mehta and that the premise is fit for occupancy class Group-D Assembly (Eating House) with effect from 22 / 04 /2021 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 29 / 04 /2021 at New Delhi by

tul Garg) Director

Copy to: -

1. The Joint Comm. of Police (Lic.), First floor, P.S. Defence Colony, New Delhi-110049

2. The DHO, (South Zone), SDMC, Public Health Department, Aurobindo Marg, Green Park, New Delhi-110016.

3. M/s Orient Tavern Restaurant (A Unit of Triumph Resorts Pvt. Ltd, 7 & 8, CSC, DDA Market, Sector-D, Pocket – IV, Vasant Kunj, New 110070.

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	INSPECTIO	N REPORT			
1	Name & Address of the Building	M/s Orient Tavern Restaurant (A Unit of Triumph Resorts Pvt. Ltd, 7 & 8, CSC Sector-D, Pocket – IV, Vasant Kunj, New Delhi.			
	Type of Occupancy			t Floor)	
2		Group—D-4 Assembly (Restaurant at 1st Floor) Ground + One upper floor			
3	Building Comprised of	New New			
4	Type of Case				
5	Details of Previous NOC	Nil Cir.No.F.6/DFS/EH/MS/ 2005/718 dated 04/04/2005			
6	Fire Safety Directives Letter No	15/03/2021	14131 20031 110 dated 0		
7	Date of Inspection				
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)			
9	Name & Designation of Officers Mr. Amit Mehta				
10	from the building side Year of construction	1996			
10	Applicant letter No.	Outdoor diary no 11622 dated 04/03/2021			
11					
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	BBL-1983/NBC Part IV-1983	Provided at Site	Remarks MR/NMR	
1	Access to Building.				
1	Road width	4.5 mtr	Provided	MR	
	Gate width	N/A	N/A	N/A	
	Width of internal road	N/A	N/A	N/A	
	Number, width, type & arrangement of ex				
2		ALLO.			
	m) Number of Staircase			MD	
	> Upper floors.	02 No's	02 Nos	MR	
	Basement floor.	N/A	N/A	N/A	
	n) Width of Staircase			1.00	
	> Upper floors	Required	1.33 mtr each	MR	
	> Basement floor	N/A	N/A	N/A	
	o) Protection of exits				
	> Fire check door	N/A	N/A	N/A	
	> Pressurization	N/A	N/A	N/A	
	p) No. of continuous staircase to terrace	Required	Provided	MR	
	q) Width of corridor	N/A	N/A	N/A	
	r) Door size	Two exit	1.65 & 1.05 mtr	MR	
3	Compartmentation.				
	Fire check door.	N/A	N/A	N/A	
	Sealing of electrical shafts.	N/A	N/A	N/A	
	T: C1-0-1	N/A	N/A	N/A	
	Fire rating of shart door. Water curtain	N/A	N/A	N/A	
		N/A	N/A	N/A	
4	• Fire dampers.	- 11.4			
4	Smoke Management system.	10 1000	3.7/4	NT/A	
	Basement	12 ACPH	N/A	N/A	
	Upper floors	12 ACPH	Provided	MR	
5	Fire Extinguishers.				
	Total numbers	05 Nos	05 Nos	MR	
	• Types	ABC/CO ₂	ABC & CO ₂	MR	
L. ALE	ISI Marking	ISI marked	Provided	MR	
6	First Aid Hose Reels.				
3	Total numbers on each floor.	One	Provided	MR	
	Tonath of hose real hose	30m	Provided	MR	

7	Automatic fire detection & alarming syst	em.		
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	N/A	N/A	N/A
10	Automatic Sprinkler System		1	
	Basement	N/A	N/A	N/A
	 Ground floor & upper floor 	Required	Provided	MR
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.		1	14/21
	Size of Riser/Down-comer	100 mm	Provided	MR
	 Number of Hydrant per floor 	One	Provided	MR
	Hose box.	One	Provided	MR
12	Yard Hydrants.			WILL
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.	11111	1771	IN/A
	Ground Level			
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A N/A
	Number of main pumps.	N/A	N/A	N/A
	> Jockey Pump output.	N/A	N/A	N/A
	> Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	> Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
	Terrace Level			
	Discharge of pump.Head of pump.	450 & 225 LPM	450 & 225 LPM	MR
	Power supply.	40m	Provided	MR
	> Auto starting of pump.	Required	Provided	MR
	Tuto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.			
	Underground tank capacity.	N/A	N/A	N/A
	Draw-off connection.	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	5,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.		11011000	IVIIC
	Pressurization of lift shaft	N/Á	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
Parameter (Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area		vel-strafficm 4 2 2 2	
	Total area	N/A	N/A	N/A
- 35k%	• Location	1771	4+74	
		N/A	N/A	N/A

19	Fire Control Room.			
	Detector system panel.	N/A	N/A	N/A
	Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A
	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

Pl. Spk about applicability of
Fire safety Measures.

Live

Signature of the Inspecting Officer
Name: - Rajesh Kumar
Designation: - ADO/BCP

DO (SD)

- Spoken with ADO (Bel)

It was submitted that restaurant was in Existence since 1996 and Fire safety measures have been checked our pre reprisements of that time. Submitted please.

Difory!

1. Is it new case?

2. Sph on door size

3. what is the capacity

af o. n. tank on per requirement