C33

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/Assembly/SZ/2021/103

Dated: 30/04/2021

## **FIRE SAFETY CERTIFICATE**

Certified that Banquet Hall pertaining to M/s Saav Hospitality situated at Plot No 2, Shambhu Dayal Marg, Near Okhla NSIC Metro Station, New Delhi comprised of three triple height banquet halls running at ground floor only was issued FSC by this department vide letter No F6/DFS/MS/Assembly/SZ/2018/402 dated 13/03/2018. The premise was re-inspected by the officer concerned of this department on 02/04/2021 in the presence of Ms. Monica and observed that the said building have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class-D "Assembly Building" as above with effect from 20/04/2021 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 30 / 04 /2021 at New Delhi by

(Sunil Chawdhary) Dy. Chief Fire Officer (SZ) Delhi Fire Service

Copy to: -

1. The Dy. Health Officer, South MCD, Lajpat Nagar, Central Zone, Delhi-110024

2. The Joint commissioner of Police (Lic) 1<sup>st</sup> floor, P. S Defence Colony, New Delhi- 110049

3. The Authorized Signature, M/s Saav Hospitality, Plot No 2, Shambhu Dayal Marg, Near Okhla NSIC Metro Station, New Delhi- 110020

## Conditions for the validity of Fire Safety Certificate: =

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

		INSPECTIO	ON REPORT	TELL STATE OF THE			
1	Name & Ac	ldress of the Building	M/s Saav Hospitality, Plot no 2, Shambhu Dayal				
	**		Marg, Near Okhla NSIC Metro Station, New Delhi				
2	Type of Oc	cupancy	Assembly 'Group-D' (Banquet Hall)				
3	Building co	mprised of	Three triple height banquet hall running at Ground				
			floor only				
4	Type of Ca	se	Renewal				
5	Details of F	revious NOC	F6/DFS/MS/Assembly/SZ/2018/402 dated 13/03/2018				
6	Fire Safety	Directives Letter No	F6/DFS/MS/BP/2018/951dated 08/03/2018				
7	Date of Ins	pection	02/04/2021				
8	Name of th	e Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)				
9		esignation of Officers	Ms. Monica				
	from the bu						
10	Year of cor	struction	2018		×		
11	Applicant letter No. Gmail dated 25-03-2021						
S. No.	Minimum standards on Fire Prevention		NBC / UBBL- Remar		Remarks		
D. 110.		afety U/R 33	Requirement	Provided at Site	MR/NMR		
1	Access to I						
	Ro	ad width	12mtr	12 m	MR		
		e width	NA	N/A	N/A		
	Wi	dth of internal road	NA	N/A	N/A		
2	Number,	width, type & arrangement of e	xits				
	a. Numbe	er of Staircase					
	Up	per floors	N/A	N/A	N/A		
	Ba	sement floor	-NA-	N/A	N/A		
	b. Width	of Staircase					
		per floors	-NA-	N/A	N/A		
		sement floor	-NA-	N/A	N/A		
		ion of exits		NT/1	77/4		
		e check door	-NA-	N/A	N/A		
		ssurization	-NA-	N/A	N/A		
		continuous staircase to terrace	Required 2 mtr	01 Nos Provided	MR MR		
	e. Width	of corridor	2 mtr & 1 mtr	Provided	MR		
2			2 31101 00 1 11101	Trovidod	IVIIC		
3	Compartn				1 3 800		
		e check door.	Required	Provided	MR		
		lling of electrical shafts.	-NA-	N/A	N/A		
		e rating of shaft door.	-NA-	N/A	N/A		
		ter curtain	-NA-	N/A N/A	N/A N/A		
4		e dampers. nagement system.	-NA-	IN/A	IN/A		
7	SHIPAC IVIA	nagement system.					
		sement	-NA-	N/A	N/A		
		per floors	12 ACPH	Exhaust fan Provided	MR		
5	Fire Extin		20 3	22.27.2	N/D		
		al numbers	20 no's ABC /W	22 No's	MR		
	• Ty		CO2/co2	ABC, Co2 &WCo2	MR		
	• ISI	Marking	ISI marked	Provided	MR		
6	First Aid I	lose Reels.					
		tal numbers on each floor.	06 Nos	Provided	MR		
		ngth of hose-reel hose.	30m	Provided	MR		
	• No	zzle Diameter	5mm	Provided	MR		
7	Automatic	fire detection & alarming system.		A-BA			
	• Ty	pe of detectors	-NA-	NA	-NA-		
		cation of Main Panel	-NA-	-NA-	-NA-		

	Location of Repeater Panel	-NA-	-NA-	-NA-		
	<ul> <li>Alternate source of power</li> <li>Hoofer's location</li> </ul>	-NA-	-NA-	-NA-		
		-NA-	-NA-	-NA-		
8	MOEFA	Required	Provided	MR		
9	Public Address System	Required	Provided	MR		
10	Automatic Sprinkler System					
	Basement	-NA-	-NA-	-NA-		
	Upper floors	-NA-	-NA-	-NA-		
	Sprinkler above false ceiling	-NA-	-NA-	-NA-		
11	Internal Hydrants.					
	Size of Riser/Down-comer	Required	100 mm	MR		
	Number of Hydrant per floor	Required	06	MR		
	Hose box.	Required	06	MR		
12	Yard Hydrants.	Required	00	IVIK		
	•	NIA	NTA.	NIA		
	Total number of hydrants.	-NA-	-NA-	-NA-		
13	Hose box.  Pumping arrangements.	-NA-	-NA-	-NA-		
13						
	Ground Level					
	Discharge of main pump.	-NA-	, -NA-	-NA-		
	Head of main pump.	-NA-	-NA-	-NA-		
	Number of main pumps.	-NA-	-NA-	-NA-		
	> Jockey Pump output.	-NA-	-NA-	-NA-		
	<ul><li>Jockey Pump head.</li><li>Standby Pump output.</li></ul>	-NA-	-NA-	-NA-		
	Standby Pump head.	-NA-	-NA-	-NA-		
	Auto Starting / Manual Stopping.	-NA-	-NA-	-NA-		
	Pump House Access	-NA-	-NA-	-NA-		
	Terrace Level		Emily I			
	Discharge of pump.	900 LPM	Provided	MR		
	Head of pump.	40 mtr	Provided	MR		
	Power supply.	Required	Provided	MR		
	Auto starting of pump.	Required	Provided	MR		
14	Captive water storage for Fire Fighting.					
	Underground tank capacity.	-NA-	-NA-	-NA-		
	> Draw-off connection.	-NA-	-NA-	-NA-		
	Fire Service Inlet.	-NA-	-NA-	-NA-		
	Access to tank.	-NA-	-NA-	-NA-		
	Overhead tank capacity.	25,000 Ltr	Provided	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
	Pressurization of lift shaft.	-NA-	-NA-	-NA-		
	<ul> <li>Pressurization of lift lobby.</li> </ul>	-NA-	-NA-	-NA-		
	<ul> <li>Communication in lift car.</li> </ul>	=NA=	=NA=	=NA=		
	• Fireman's switch.	-NA-	-NA-	-NA-		
	Lift signage.	-NA-	-NA-	-NA-		
17	Standby Power Supply	Required	Provided	MR		
18	Refuge Area	To the second second				
	Total area	-NA-	-NA-	-NA-		
	Location	-NA-	-NA-	-NA-		
	Doution	1111	142	1471		

19	Fire	Control Room.			
		Detector System Panel.	-NA-	-NA-	-NA-
		Flow Switch Panel.	-NA-	-NA-	-NA-
		PA system Panel.	-NA-	-NA-	-NA-
		Battery backup	-NA-	-NA-	-NA-
		Building floor plan	-NA-	-NA-	-NA-
20	# JR 2	cial Fire Protection System for the tection of special Risk, if any:	-NA-	-NA-	-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/Assembly/SZ/2018/402 dated 13/03/2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting officer Name: S.K. Dug Designation: DO/SD

Signature of the Inspecting Officer

Name: Rajesh Kumar Designation: ADO (BCP)

BO (58)

Dy. CFO (SZ

F. J. pleased

As approved, F=1. Fettel is post-p for your

syndure Pl.

Dr. Chols 2

M. S. cell