

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6 DFS/MS/School/2021/SZ/ 39

Dated: 18 / 06 / 2021

FIRE SAFETY CERTIFICATE

Certified that **Tagore International School**, located at **Paschimi Marg, Vasant Vihar**, **New Delhi 110057** comprised of Total 04 Blocks interconnected, One Block, B+ G+ 2 Upper floor (Basement is sealed by School Management), One Block, G+ 2 upper floor & Two Blocks, G+ 3 upper Floors was issue Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2018/SZ/743 dated 20/04/2018 for total 04 interconnected blocks comprised of two blocks are ground plus two upper floors & two blocks are ground plus three upper floors. The said premise was re-inspected by officer concerned of this department on 08/06/2021 in presence of Shefalee Gupta (Principal) of the school and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and the building is fit for occupancy class "**Educational Building Group – B"** with effect from 18 / 06 / 2021 for a period of **Three years** in accordance with rule 36 unless renewed under rule37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules 2010.

Issued on 18/06/2021 at New Delhi by

(Sunil Chawdhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to: -

- 1. The Principal, Tagore International School, Paschimi Marg, Vasant Vihar, New Delhi 110057
- 2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 2. All the staff members must know the correct method of operation of firefighting system.
- 3. This certificate cannot be treated as regularization of unauthorized construction, if any.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

MIS

1	Name & Address of the Building	TION REPORT Tagore International School, Paschimi Marg,			
		Vasant Vihar, New Delhi –110057			
2	Type of Occupancy	Educational, Group-B (School)			
3	Building Comprised of	Total 04 Blocks interconnected, One Block, B-			
		+ 2 Upper flo	+ 2 Upper floors (Basement is sealed by Sch		
		Management),	One Block, G+2 uppe	er floor & T	
4	Type of Case	Diocks, G+3 up	per Floors.	1001 66 1	
5	Details of Previous NOC	Renewal	The second secon	The second secon	
	Details of Flevious NOC	F.6/DFS/MS/School/2018/SZ/743 dated 20-04-			
6	Fire Safety Directives Letter No	2018			
7	Date of Inspection	Nil			
8	Name of the Inspecting Officers	08/06/2021			
9	Name & Designation of Officers	Sh. Rajesh Kumar ADO (BCP)			
	from the building side	Shefalee Gupta (Principal)			
10	Year of construction	2007			
11	Applicant letter No.		10.6 10.00		
S. No.	Minimum standards on Fire Prevention	Gmail dated 08/			
	and Fire Safety U/R 33	Requirements	Provided at Site	Remark	
1	Access to Building.	requirements		MR/NM	
	Road width	6 mtr	D '11		
	Gate width	4.5 mtr	Provided	MR	
	 Width of internal road 	-NA-	Provided -NA-	MR	
2	Number, width, type & arrangement of ex	ite	-INA-	-NA-	
	a) Number of Staircase	1163.			
	Upper floors.	Required	05 Nos		
	Basement floor.	-NA-		MR	
	b) Width of Staircase	-IVA-	-NA-	-NA-	
-	▶ Upper floors	1.50 / 0.75 mtr	1.10	-	
		1.30 / 0.75 mm	1.18, 1.20, 0.92,	MR	
	Basement floor		1.25, 1.20 m	14114	
	c) Protection of exits	-NA-	-NA-	-NA-	
:-	Fire check door				
	> Pressurization	Required	Provided	MR	
		-NA-	-NA-	-NA-	
		Required	01 Nos	MR	
	e) Width of corridor f) Door size	1.5 mtr	Provided	MR	
3	Compartmentation.	1m	Provided	MR	
	• Fire check door.				
		-NA-	-NA-	-NA-	
	Scaring of electrical shalts.	-NA-	-NA-	-NA-	
The state of the s	Fire rating of shaft door.Water curtain	-NA-	-NA-	-NA-	
	Fire dampers.	-NA-	-NA-	-NA-	
4	Smoke Management system.	-NA-	-NA-	-NA-	
	Basement	20 100			
		30 ACPH	-NA-	-NA-	
5	• Upper floors	12 ACPH	-NA-	-NA-	
5	Fire Extinguishers.			I	
	Total numbers		30 Nos	MR	
	• Types	ISI marked	CO2 + ABC	MR	
	ISI Marking		Provided	MR	
	First Aid Hose Reels.	1	TITAINE	13/E RC	

-	Total numbers on each floor.		01 No at each floor	MR
	 Length of hose-reel hose. 	Hose-reel	30m	MR
	Nozzle Diameter		5mm	MR
			Jiiiii	11110
7	Automatic fire detection & alarming system.	-NA-	-NA-	-NA-
	Type of detectors	-NA-	-NA-	-NA-
	Location of Main Panel	-NA-	-NA-	-NA-
	Location of Repeater Panel	-	-NA-	-NA-
	 Alternate source of power 	-NA-		-NA-
	Hooter's location	-NA-	-NA-	
8	MOEFA	-NA-	-NA-	-NA-
9	Public Address System	-NA-	-NA-	-NA-
10	Automatic Sprinkler System	274	NIA	-NA-
	Basement	-NA-	-NA-	-NA-
	Upper floors	-NA-	-NA-	
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11	Internal Hydrants.) (D)
	Size of Riser/Down-comer	100 mm	Provided	MR
	 Number of Hydrant per floor 	01	Provided	MR
	Hose box.	01	Provided	MR
12	Yard Hydrants.			
	 Total number of hydrants. 	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13	Pumping arrangements.			
	Ground Level		*	
	Discharge of main pump.	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level			1
	Discharge of pump.	450 LPM x 4	Provided	MR
	➤ Head of pump.	40 m	Provided	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.			· · ·
	 Underground tank capacity. 	-NA-	-NA-	-NA
	Draw-off connection.	-NA-	-NA-	-NA
	Fire Service Inlet.	-NA-	-NA-	-NA
	Access to tank.	-NA-	-NA-	-NA
	 Overhead tank capacity. 	20,000 Ltr	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of lift shaft.	-NA-	-NA-	-NA
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA
	Communication in lift car.	-NA-	-NA-	-NA
	Fireman's switch.	-NA-	-NA-	-NA
	Lift signage.	-NA-	-NA-	-NA
17	Standby Power Supply	-NA-	-NA-	-NA
18	Refuge Area			
2.7%				-NA

	Location	-NA-	-NA-	-NA-
19	Fire Control Room.			
	 Detector system panel. Flow switch panel. PA system panel. Battery backup. Building floor plan. 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any.	-NA-	-NA-	-NA-

The fire protection system provided in the building / premises were test checked at random and found functional at the time of inspection.

During the course of visit it is observed that there is an existing basement under, ground plus two upper floors, Nursery Block, which was found, sealed / Closed by school management. The undertaking in this regard is enclosed at opposite of file.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F.6/DFS/MS/School/2018/SZ/743 dated 20/04/2018, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of Inspecting Officer Name: Sh. Rajesh Kumar

Design:

ADO (BCP)

Et pleust.

4, F.T. lettel ei -