GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/School/2021/ NDZ/ 35

Dated: 03 05 2021

FIRE SAFETY CERTIFICATE

Certified that the Lovely Rose Public School located at C-9, Yamuna Vihar, Delhi 110053, comprised of ground plus two upper floors only owned/occupied by Lovely Rose Public School was issued FSC vide letter no. F6/DFS/MS/School/2017/NDZ/1069 dated 20/07/17. The school building was re-inspected by the officer concerned of this department on 19/04/21 in the presence of Mrs. Meenakshi shah Principal of the school and observed that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular letter no. 262–362 dated 17/01/2005 issued by Director of Education and found that the school building is fit for occupancy class "B" 'Educational Building' for Ground plus two upper floors only with effect from 0.3 ... 0.5 ... 0.5 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

Issued on $03 \mid 05 \mid 2021$ at New Delhi by

(Dr.S.K.Tomar)
Dy. Chief Fire Officer

To,

The Principal Lovely Rose Public School, C-9, Yamuna Vihar, Delhi 110053

Copy:

The Dy. Director of Education, B–Block, Yamuna Vihar, Delhi-110053

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form `J` [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

- 1. Name & address of the building
- 2. Building is comprised of
- 3. Type of Occupancy
- 4. Type of Case
- 5. Details of Previous NOC letter
- 6. Fire Safety directive letter No.
- 7. Date of Inspection
- 8. Name of the Inspecting officers
- 9. Name and designation of Officer from the building side
- 10. Year of Construction
- 11. Applicant's letter No

- : Lovely Rose Public Secondary School, C-9, Yamuna Vihar, Delhi-110053
- : Ground plus two upper floors
- : Educational
- : Renewal
- : F6/DFS/MS/School/2017/NDZ/1069, dt.-20/07/17
- : 262 362 dated 17/01/2005 (Director of Education)
- : 19/04/2021
- : ADO Mehmood
- : Mr. Meenakshi Shah(Principal)
- : 1988
- : E-mail Dt.09/04/2021

	Minimum Standards on Fire	Circular	Provided at Site	Remarks MR/NMR				
r. Io.	Prevention and Fire Safety U/R33	Requirement						
1	Access to Building.							
1		06 mtrs.	06 mts.	MR				
	 Road width 		4.5 mtrs	MR				
	 Gate width 	4.5 mtrs N/A	N/A	N/A				
	 Width of internal road 							
)2	Number, Width, Type and Arrangement of Exits.							
	a. Number of Staircases	00 No	02 No.	MR				
	Upper floor	02 No.	N/A.	N/A				
	Basement	N/A	1.50 mtr.&0.90 mtr	MR				
	b. Width of Staircases	1.50 mtr. 1.50 mtr.	1.50 mtr.&0.90 mtr	MR (old				
	 Upper floor 			accepted)				
	* *	N/A	N/A	N/A				
	 Basement 	N/A	N/A	N/A				
	c. Protection of exits	N/A	N/A	N/A				
	 Fire check door 	N/A	N/A	N/A				
	 Pressurization 	01 No.	01 No.	MR				
	d. No. of Continuous Staircases	01110.	* B 6					
	to Terrace	1.50 mtr.	1.50 mtr.&1.0 mtr.	MR				
	e. Width of Corridor	01 mtr.	1.16 mtr.	MR				
	f. Door Size	OT THE		Accepted as				
	I No. of doors in class room	02 Nos.	01 No.	no. of student less than 40				
	3 Compartmentation.							
03		N/A	N/A	N/A				
	Fire check door	2.1.4	N/A	N/A				
	 Sealing of electrical shafts 	N/A	N/A	N/A				
	 Fire rating of shaft door 	N/A	N/A	N/A				
	 Water curtain 	N/A	N/A	N/A				
	Fire dampers System	19/73						
04	Smoke Management System.	21/4	N/A	N/A				
-	 Basement 	N/A	N/A	N/A				
	 Upper floor 	N/A	14/7	×				
0				MR				
	Tatal numbers	11 nos.	11 nos.	MR				
	1 20 20 20 20 20 20 20 20 20 20 20 20 20	ABC /CO		MR				
	TypesIS marking	ISI marke	d ISI marked	IVIIX				

06	First-Aid-Hose Reels.						
	Total numbers on each floor	01 no.	01 no.	MR			
	Length of hose reel hose	30 mtr.	30 mtr.	MR			
	Nozzle diameter	05 mm	05 mm	MR			
07	Automatic Fire Detection and Alarming System.						
	Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	Location of repeater panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter's location	N/A	N/A	N/A			
08	MOEFA	Required	Provided	MR			
09	Public Address System.	Required	Provided	MR			
10	Automatic Sprinkler System.	N/A	N/A	N/A			
	Basement	N/A	N/A	N/A			
	upper floor	N/A	N/A	N/A			
	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants	IN/A	IN/A	14//			
	size of riser/down-comer	100 mm	100 mm	MR			
	Number of hydrants per floor	01 no.	01 no.	MR			
	Hose box	01 no.	01 no.	MR			
12	Yard Hydrants.		3				
	Total number of hydrants	01 no.	01 no.	MR			
	Hose Box	01 no.	01 no.	MR			
13	Pumping Arrangements.	N/A	N/A	N/A			
	➢ Ground Level	N/A	N/A	N/A			
	Discharge of main pump	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	180 lpm	180 lpm	MR			
	 Jockey pump head 	40 mtr.	40 mtr.	MR			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump head	N/A	N/A	N/A			
	Auto Starting /Manual stopping	N/A	N/A	N/A			
	Pump house access	N/A	N/A	N/A			
	> Terrace Level						
	Discharge of pump	450 lpm	450 lpm	MR			
	Head of the pump	40 M	40 M	MR			
	Power supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for Fire Fighting.						
8	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	 Overhead tank capacity 	5,000 ltrs.	5,000 ltrs.	MR			
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.			_			
	Pressurization of lift shaft	N/A	N/A	N/A			
	Pressurization of lift lobby	N/A	N/A	N/A			
	Communication in lift car	N/A	N/A	N/A			
	Firemen's grounding switch	N/A	N/A	N/A			
	Lift signage	N/A	N/A	N/A			

1)

	Andrew Control of the	N/A	N/A	N/A
17	Standby Power Supply	INIA		
18	Refuge Area.			N/A
	Total area	N/A	N/A	
		N/A	N/A	N/A
	 Location 	5		
19	Fire Control Room			N/A
		N/A	N/A	
	Detector system panel	N/A	N/A	N/A
	 Flow switch panel 	N/A	N/A	N/A
	 PA system panel 	N/A	N/A	N/A
	Battery backup Building floor plans		N/A	N/A
		N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of Special Risks, if any:	N/A	N/A	

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the circular letter no. 262-362 dated 17/01/2005 issued by Director of Education, it is recommended to renew Fire Safety Certificate.

Signature of the Inspecting Officer

Name

:- Mehmood

Designation :- A.D.O (T.P.)

Recd on 28/4/2

Dy.CFO(NDZ)

8-T Julian purt up for Sugastan blean

Januard

m.s.(e1)