## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

F.6/DFS/MS/EH/SZ/2021/113 No.

Dated 34/06/2021

## **FIRE SAFETY CERTIFICATE**

Certified that M/s Diva Restaurant, (A Unit of RIGA Foods LLP) M-8, Greater Kailash-II, M-Block Market, New Delhi 110048 comprised of Basement, Ground & Three Upper Floors but the restaurant is running on Ground & 1st Floor only was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/EH /SZ /2018/1416 dated 18/06/2018. The restaurant premise was re-inspected by the officer concerned of this department on 21/06/2021 in the presence of Mr. Amit Singh (Manager) of the restaurant and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" Restaurant as above with effect from ...../......2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 24 / 06 / 2021 at New Delhi by

(Sunil Chawdhary) Dy. Chief Fire Officer (SZ) **Delhi Fire Service** 

Copy to: -

y to: -The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi.

M/s Diva Restaurant, (A Unit of RIGA Foods LLP) M-8, Greater Kailash-II, M-Block Market, New Delhi 110048

## Conditions for the validity of Fire Safety Certificate: -

All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

All the staff members must know the correct method of operation of fire fighting system.

The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

1	Name & Address of the Building	M/s Diva Restaurant, (A Unit of RIGA Foods LLP) M-8, Greater Kailash-II, M-Block Market, New 'Delhi 110048			
2	Type of Occupancy	Group-D Assembly Building.			
3	Building Comprised of	Basement, Groun	Basement, Ground + Three upper floors		
4	Type of Case	Renewal			
5	Details of Previous NOC	F.6/DFS/MS/EH	/SZ /2018/1416 dated	18/06/2018	
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	21/06/2021			
8	Name of the Inspecting Officers	Sh. Rajesh Kuma	ur ADO (BCP)		
9	Name & Designation of Officers	Mr. Amit Singh (Manager)			
	from the building side				
10	Year of construction	1978 Restt. at ground, 1 <sup>st</sup> floor of the bldg.			
11	Applicant letter No.	Online No. 2021060913708 dated 09/06/2021			
C N		2005circular/Rule Provided at Site Remarks			
S. No.	Minimum standards on Fire Prevention		I TO THE WE DIE	Remarks	
	and Fire Safety U/R 33	35(6)requirement		MR/NMR	
1	Access to Building.				
	Road width	Accessible	Provided	MR	
	Gate width	(4-5m)	N/A	N/A	
	Width of internal road	N/A			
		N/A	N/A	N/A	
2	Number, width, type & arrangement of ex	cits.			
	a) Number of Staircase				
	Upper floors.	02 Nos	03 Nos	MR	
	Basement floor.	N/A	Not part of Restt.	N/A	
	b) Width of Staircase				
	> Upper floors	Required	1.1m, 1.1m, 0.8m	MR (old case)	
	➢ Basement floor	N/A	N/A	N/A	
	c) Protection of exits				
	Fire check door	N/A	N/A	N/A	
	Pressurization	N/A	N/A	N/A	
	d) No. of continuous staircase to terrace	N/A	N/A	N/A	
	e) Width of corridor	N/A	N/A	N/A	
	f) Door size	2 exits	1.05 m & 0.95 m	MR (old case)	
3	Compartmentation.				
	Fire check door.	N/A	N/A	N/A	
	Sealing of electrical shafts.	N/A	N/A	N/A	
		N/A	N/A	N/A	
	Fire rating of shaft door.  Water curtain	N/A	N/A	N/A	
	Water curtain	N/A N/A	N/A N/A	N/A	
4	• Fire dampers.	IN/A	IN/A	IN/A	
4	Smoke Management system.				
	Basement	30 ACPH	N/A	N/A	
	Upper floors	12 ACPH	Exhaust Fans Provided	d MR	
5	Fire Extinguishers.				
	Total numbers	08 Nos	08 Nos	MR	
	Types		ABC-06 & CO <sub>2</sub> -		
	ISI Marking	ABC/CO <sub>2</sub>	02	MR	
	- 101 Marking	ISI marked	Provided	MR	
6	First Aid Hose Reels.				
TANK.	Total numbers on each floor.	One at each	Provided	MR	
	Length of hose-reel hose.	30m	Provided	MR	
1 1	Nozzle Diameter	5mm	Provided	MR	

वितरित हो तो कृपया लौटाएँ :

	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8 1	MOEFA	Required	Provided	MR
	Public Address System	N/A	N/A	N/A
	Automatic Sprinkler System			=
10 7	Basement	N/A	N/A	N/A
	Ground floor & above floor	Required	Provided	M/R
	Sprinkler above false ceiling	N/A	N/A	N/A
11 I	Internal Hydrants.		-	
	Size of Riser/Down-comer	N/A	N/A	N/A
	Number of Hydrant per floor	N/A	N/A	N/A
57	Hose box.	N/A	N/A	N/A
12	Yard Hydrants.			
12	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.	1111		
10	Ground Level			
	<ul><li>Discharge of main pump.</li></ul>	N/A	N/A	N/A
postana angene da proposido	<ul><li>Head of main pump.</li></ul>	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
_		IN/A	IVA	14/71
-	Terrace Level     Discharge of pump	450LPM	450 LPM	MR
	<ul><li>Discharge of pump.</li><li>Head of pump.</li></ul>	430LPM	Provided	MR
	Power supply.		Provided	MR
	<ul><li>Auto starting of pump.</li></ul>	Required NA	Provided	NA
4.4		INA INA	Flovided	1471
14	Captive water storage for fire fighting.	N/A	N/A	N/A
	<ul> <li>Underground tank capacity.</li> <li>Draw-off connection.</li> </ul>	N/A	N/A	N/A
	Fire Service Inlet.		N/A	N/A
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	N/A	Provided	MR
		5,000 Ltrs		
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	% T / A	NT/A	N/A
	Pressurization of lift shaft.	N/A	N/A N/A	N/A N/A
	Pressurization of lift lobby.	N/A N/A	N/A .	N/A
	Communication in lift car.	N/A N/A	N/A N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
4 /94	Lift signage.  Standby Boycon Symphy		Provided	MR
17	Standby Power Supply	Required	Flovided	IVIIX
18	Refuge Area			
	Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room.			
	Detector system panel.	N/A	N/A	N/A

	Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A
	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/EH /SZ /2018/1416 dated 18/06/2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Designation: ADO (BCP)

DO (SD)

on leave 1 Ft. plinte

A CONTRACTOR OF THE PARTY OF TH

As approved, f.T.

Hottoe

er prohip to

your synature 91.

23/6

Dy chold

M. S Cell