GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2021/SZ/

Dated: 25 06/2021

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of The Tangra Project (A Unit of A Sirius Hospitality Enterprise Pvt. Ltd., Unit No 154 & 159 Ground Floor, DLF Avenue, Saket, New Delhi 110017 comprised of Three tires basement, ground and seven upper floors have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 10/06/2021 in the presence of Mr. Jitin Sahni and that the premises is fit for occupancy class "Group—D Assembly" (Restaurant at Ground floor only) with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on <u>\$5</u> / <u>06</u> /2021 at New Delhi by

Atul Garg) Director

Copy to: -

- 1. The Dy. Health Officer, SDMC, Public Health Department, Green Park, Aurobindo Marg, New Delhi 110016. (MHA Portal 2021030611023 dated 13.03.2021)
- 2. The Joint Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi–110049
- 3. M/s The Tangra Project (A Unit of A Sirius Hospitality Enterprise Pvt. Ltd., Unit No 154 & 159 Ground Floor, DLF Avenue, Saket, New Delhi 110017

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

1. Name & address of the building : The Tangra Project (A Unit of A Sirius Hospitality Enterprise Pvt. Ltd., Unit No 154 & 159 Ground Floor, DLF Avenue, Saket

New Delhi 110017

2. Type of Occupancy : Assembly (Ground floor only)

3. Type of Case : New Case

4. Details of previous NOC : Nil (DLF Mall FSC even no 1832 dated 23.09.2019)

5. Fire Safety directives letter No : Nil

6. Date of inspection : 10.06.2021

7. Name of the Inspecting Officers : Dy. CFO (SZ) & ADO (BCP) 8. Name and designation of officers

9. from the building side : Mr. Jitin Sahni

10. Year of Construction/conversion : 2008

11. Applicant's letter No. : MHA Portal 2021030611023dated 13.03.2021

	Minimum Standards on fire prevention and fire safety U/R 33	UBBL/NBC-2016 requirements	Provided at site	Remarks MR/NMR			
1	Access to building						
	Road width	09m	12m approx	MR			
	Gate width	. NA	NA	NA			
	Width of internal road	NA	NA	NA			
	Number, Width, Type & Arrangement of Exits	(Restaurant at	GF only)				
	a. Number of staircases						
	Upper Floors	NA	NA	NA			
	Basements	NA	NA	NA			
	b. Width of staircases						
	Upper Floors	NA	NA	NA.			
	Basements	NA	NA	NA			
	c. Protection of exits						
	Fire check door	NA	NA	NA			
	Pressurization	NA	NA	· NA			
	d. No. of continuous staircases to terrace	NA	NA	NA			
	e. Width of Corridor	NA	NA NA	NA			
	f. Door Size	02 Exits	2 m & 1.50 m	MR			
	Compartmentation.						
	Fire check door	NA	NA	NA			
	Sealing of electrical shafts	NA	NA	NA			
	Fire Rating of shaft door	NA	NA	NA			
	Water Curtain	NA	NA	NA			
	Fire Dampers	NA	NA	NA			
	Smoke Management System.						
	Basements	30 a/c per hour	NA	NA			
	Upper floors (Ground Floor)	12 a/c per hour	Provided	MR			
	Fire Extinguishers						
	Total numbers	04nos	5nos	MR			
	• Types	ABC/Co2	ABC-4	MR			
	ISI marking	Yes	Co2-1 Yes	MR			
	First-Aid Hose Reels.Common with Mall						
	Total numbers on each floor	01	Provided near restt.	MR			
	Length of hose reel hose	30m	Provided	MR			

	Nozzle diameter	JIIIII	11011000	LVAR.			
7 A	Automatic fire detection and alarming system.						
	Type of detectors	NA	NA	NA			
	Location of Main Panel	NA	NA	NA			
		NA	NA	NA			
	Location of Repeater Panel	NA	NA NA	NA			
	Alternate source of power	NA	NA	NA			
	Hooters' Location		,	,			
	MOEFA	Required NA	Provided NA	MR NA			
	Public Address System. NA NA NA Automatic Sprinkler System.						
		NA	NA	NA			
	BasementUpper Floor(Ground floor)	NA NA	NA NA	NA.			
	Sprinkler above false ceiling						
ar various projection and the second		NA	NA	NA			
1 I	Internal HydrantsCommon with Mall						
	Size of riser/down-comer	100mm	Provided near restt.	MR			
	Number of hydrants per floor Head Park	01	Provided	MR			
_	Hose Box	. 01	Provided	MR			
2	Yard Hydrants.	D.T.A.	NA	NA			
	Total number of hydrants	NA					
	Hose Box	NA	NA	NA			
3 1	Pumping Arrangements. Common with Mall						
	Ground Level						
The state of the s	Discharge of main Pump	4500 lpm	4500 lpm	MR			
	➤ Head of Main pump	88m	88m	MR			
	Number of main pumps	02	02	MR			
	Jockey Pump out put	5 m 5 m 5 m	180 lpm	MR			
	> Jockey pump head	180 lpm 88m	88m	MR			
	Standby Pump out put	4500 lpm	4500 lpm	MR			
		88m	88m	MR			
	Standby Pump Head						
	Auto Starting/ Manual stopping	Required	Provided	MR			
	Pump House Access	Required	Provided	MR			
	Terrace level		27/2	114			
	Discharge of pump	N/A	N/A	N/A N/A			
	► Head of the pump	N/A N/A	N/A N/A	N/A			
	> Power Supply			1 11 11 11			
	Auto Starting of pump	N/A	N/A	N/A			
14	Captive Water Storage for fire fighting.	Common with M	all				
14	Underground tank capacity	5,00,000ltr.	Provided	MR			
		Required	Provided	MR			
	Draw-off connection	Required	Provided	MR			
and the second	Fire service inlet	Required	Provided	MR			
	> Access to tank	30,000 ltrs	Provided	MR			
	Overhead Tank capacity		8				
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.	N/A	N/A	N/A			
	Pressurization of Lift Shaft	N/A N/A	N/A	N/A			
	Pressurization of Lift lobby						
	Communication In lift Car	NA	NA	NA			
	Fireman's Grounding Switch	NA	NA	NA			
	Lift Signage	NA	NA	NA			

17	Standby	power supply	DT/A	1 37/			
18	Refuge A	rea.	N/A	N/A	N/A		
	Total Ages						
		Total Alea	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
19	Fire Control Room						
	•	Detector System Panel	N/A	N/A	N/A		
		Flow Switch Panel	N/A				
		PA System Panel	IVA	N/A	N/A		
	•		N/A	N/A	N/A		
	•	Batter backup	N/A	N/A			
-		Puilding Elean Di	1771	IN/A	N/A		
	Dunding 1 1001 Flails	N/A	N/A	N/A			
20	Special Fi Protection	re Protection Systems for of special Risks, if any:	NA NA	NA	NA		

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly DFA is put up for approval and signature please.

Signature of the inspection officer

Name: Sh. Sunil Chawdhary Designation: Dy. CFO (SZ)

Signature of the Inspecting Officer Name: - Sh. Rajesh Kumar

Designation: - ADO/BCP

As approved, F.t. Letter in public Jour soynation BI