C-37

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/SZ/2021/122

Dated. 2.9./.6../2021

## **FIRE SAFETY CERTIFICATE**

Certified that M/s Burger king Restaurant, located at Shop No 2 & 3, 2<sup>nd</sup> Floor, Select City Walk Mall, A-3, District Centre, Saket, New Delhi- 110017 running at 2nd floor in Select City Walk Mall was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/EH/2018/SZ/1155 dated 21/05/2018. The restaurant premise was re-inspected by the officer concerned of this department on 16/06/2021 in the presence of Mr. K. K Jain and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class Group -A "Assembly Building" Restaurant as above with effect from 2.9./...6...2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 29/6/2021 at New Delhi by

(Sunil Chawdhary) Dy. Chief Fire Officer (SZ) Delhi Fire Service

0/090

Copy to: -

1. The Joint C.P (Lic) 1st Floor, PS Defence Colony, New Delhi 110049.

2. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi-110016.

3. M/s Burger king Restaurant, located at Shop No 2 & 3, 2<sup>nd</sup> Floor, Select City Walk Mall, A-3, District Centre, Saket, New Delhi- 110017

## **Conditions for the validity of Fire Safety Certificate: -**

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

	Name & Address of the Building	M/s Burger king Restaurant, Shop No 2 & 3, 2 <sup>nd</sup> Floor, Select City Walk Mall, Saket, New Delhi- 110017				
?	Type of Occupancy	Group-D Assembly Building. (Restaurant)				
	Building Comprised of	03 tier Basements, Ground + 07 Upper Floors				
	Type of Case	Renewal				
	Details of Previous NOC	F6/DFS/MS/EH/2018/SZ/1155 dated 21/05/2018				
5	Fire Safety Directives Letter No	F.6/MS/DFS/BP/2006/1141 dated 15/05/2006 &				
)	Fire Salety Directives Letter No	F.6/MS/DFS/BP/2016/	299 dated 23/11/2017 for Mall			
7	Date of Inspection	16/06/2021				
3	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)				
)	Name & Designation of Officers	ne & Designation of Officers Mr. K. K Jain				
	from the building side	and or consists as				
10	Year of construction	2020 Restt located at 2 <sup>nd</sup> floor of Mall bldg				
11	Applicant letter No.		1302568 dated 26/04/2021			
S.	Minimum standards on Fire Prevention and	Circular dated	Provided at Site	Remarks		
No.	Fire Safety U/R 33	04/04/2005		MR/NMR		
		Requirements				
1	Access to Building. (Select City	Walk Mall - F.6/DFS/MS/Mall/2021SZ/171 Dt. 15/03/2021)				
	Road width	Restt. within	Provided by Mall	MR		
	Gate width	DLF	N/A	N/A		
	Width of internal road	Promenade Mall	N/A	N/A		
2	Number, width, type & arrangement of exits.					
	Number of Staircase		tained by Select City Wal	-		
	Upper floors.	Restt within Mall	As above	MR		
	Basement floor.	N/A	N/A	N/A		
	Width of Staircase	Provided & Maintained by Select City Walk, Saket				
	Upper floors	Restt within Mall	As above	MR		
	Basement floor	N/A	N/A	N/A		
	Protection of exits	Provided & Main	tained by Select City Wa			
	Fire check door	Restt within Mall	As above	MR		
	Pressurization	Restt within Mall	As above	MR		
	No. of continuous staircase to terrace	Restt within Mall	-NA-	MR		
	Width of corridor	N/A	N/A	N/A		
	Door size	02 required	Provided	MR		
3	Compartmentation.	Provided & Main	tained by Select City Wa	lk, Saket		
	Fire check door.	Restt within Mall	As above	MR		
	Sealing of electrical shafts.	Restt within Mall	As above	MR		
	Fire rating of shaft door.	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	Fire dampers.	N/A	N/A	N/A		
4	Smoke Management system.	Provided & Main	ntained by Select City Wa	alk, Saket		
	Basement	30 ACPH	N/A	N/A		
	Upper floors	12 ACPH	Exhaust Fans Provided	MR		
5	Fire Extinguishers.					
	Total numbers	Required	10 Nos	MR		
	Types	ABC/CO <sub>2</sub>	ABC & CO <sub>2</sub>	MR		
	ISI Marking	Required	Provided	MR		
6	First Aid Hose Reels.		ntained by Select City W	alk, Saket		
0	Total numbers on each floor.	One near Restt	As above	MR		
~	Length of hose-reel hose.	30m	As above	MR		
	Nozzle Diameter	5mm	As above	MR		
7	Automatic fire detection & alarming system		nintained by Select City V			
7		Required	Smoke & heat	MR		
	Type of detectors	Required	As above	MR		

एस सा सी (इंडिस) ६००

	Location of Repeater Panel	Required	As above	MR	
	Alternate source of power	Required	As above	MR	
	Hooter's location	Required	As above	MR	
	MOEFA	Required	As above	MR	
	Public Address System	N/A	As above	MR	
0	Automatic Sprinkler System	Provided & Mai	ntained by Select City	Walk, Saket	
	Basement	Required	As above	MR	
	Upper floor	Required	Provided	MR	
	Sprinkler above false ceiling	N/A	N/A	N/A	
1	Internal Hydrants.	Provided & Maintained by Select City Walk, Saket			
	Size of Riser/Down-comer	Required	As above	MR	
	Number of Hydrant per floor	One near Restt	As above	MR	
	Hose box.	One near Restt	As above	MR	
2	Yard Hydrants.	Provided & Ma	intained by Select City	Walk, Saket	
	Total number of hydrants.	N/A	As above	N/A	
	Hose box.	N/A	As above	N/A	
13	Pumping arrangements.	Provided & Ma	intained by Select City	Walk, Saket	
	Ground Level	Common pumping arrangements for entire bldg			
	Discharge of main pump.	4500 LPM	As above	MR	
	Head of main pump.	88m	As above	MR	
	Number of main pumps.	02 Nos.	As above	MR	
	Jockey Pump output.	180 LPM	As above	MR	
	Jockey Pump head.	88m	As above	MR	
	Standby Pump output.	4500 LPM	As above	MR	
	Standby Pump head.	88m	As above	MR	
	Auto Starting/Manual Stopping.	Required	As above	MR	
	Pump house access.	Required	As above	MR	
	Terrace Level	1			
	Discharge of pump.	450 LPM	As above	MR	
	Head of pump.	40 m	As above	MR	
	Power supply.	Required	As above	MR	
	Auto starting of pump.	Required	As above	MR	
14	Captive water storage for fire fighting.	Provided & Ma	aintained by Select Cit	ty Walk, Saket	
1.1	Underground tank capacity.	Required	5,00,000 ltrs	MR	
	Draw-off connection.	Required	Provided	MR	
15	Fire Service Inlet.	Required	Provided	MR	
	Access to tank.	Required	Provided	MR	
	Overhead tank capacity.	Required	30,000 Ltrs	MR	
	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.		laintained by Select Ci	ty Walk, Saket	
16	Pressurization of lift shaft.	N/A	As above	N/A	
	Pressurization of lift lobby.	N/A	As above	N/A	
	Communication in lift car.	N/A	As above	N/A	
	Fireman's switch.	N/A	As above	N/A	
	Lift signage.	N/A	As above	N/A	
17	Standby Power Supply	Required	Provided	MR	
18	Refuge Area				
10	Total area	N/A	N/A	N/A	
19	Location	N/A	N/A	N/A	
	Fire Control Room.	A CONTRACTOR OF THE CONTRACTOR	Maintained by Select C		
		N/A	As above	N/A	
	Detector system panel.	N/A	As above	N/A	
	Flow switch panel.  PA system panel.	N/A	As above	N/A	
	Battery backup.	N/A	As above	N/A	
	DALICI V DAVNUD.	1 1 1 / 1 1	A AD MUUTU	1	

एस सी सी (झंड्या) किसाने

20	Special Fire Protection System for the	N/A	As above	N/A
	Protection of special Risk, if any.		1	

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2018/SZ/1155 dated 21/05/2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Rajesh Kumar

Designation: ADO / BCP

DO (SID)

24/06

Difo(sh)

M. F. T. pleast

As approved above, F.T. letter is but up for Kind perusal approval/Sign for

28/6/21

DCFo(\$z)

M.S. COL