FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE [Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No.F6/DFS/MS/SZ/2021/ 291

Dated: 29/06/2021

FIRE SAFETY CERTIFICATE

Certified that the G+5 Building, Near Domestic Terminal 1D Building, IGI Airport, New Delhi-110037, comprised of Ground & Five Upper Floors only owned / occupied by Delhi international Airport (P) Limited, was granted Fire Safety Certificate by this department vide letter No. F6/DFS/MS/E/SZ/2018/2320 dated 12/10/2018. The premises was re-inspected by the officer concerned of this department on 14/06/2021 in the presence of Sh. Vinod Kumar (Head Fire & Safety GMR) and observed that all the Fire prevention and Fire Safety arrangements provided in the premises found in good working condition. The premises have therefore, deemed complied with rule 33 of the Delhi Fire Service rules, 2010 and that the building / premises is fit for occupancy Class "Business" (Group-E) with effect from 29 / 66/2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions under 38 of the Delhi Fire Service rules, 2010.

Issued on .. 23/06/2021 at New Delhi by.

(ATUL GARG)

Copy to:-

1. Sh. P. Hrishikesan, Head Airport Rescue & Fire Fighting, New Udaan Bhawan, Terminal-3, IGI Airport, New Delhi-110037.

2. The Executive Vice President, DIAL, New Udaan Bhawan, Terminal-3, IGI Airport, New Delhi-110037.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape / entry / exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.

3. Any loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of fire fighting system.

5. This Fire Safety Certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3. of UBBL-2016), if any.

6. This certificate cannot be treated in any case for regularizations of unauthorized construction.

7. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".

8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building: G+5 Building, Near Domestic Terminal 1D Building, IGI Airport, New Delhi-110037.

2. Type of Occupancy

: Business Building (Group – E)

3. Type of Case

: Renewal (Ground & 5 Upper Floors)

4. Details of previous NOC

:F6/DFS/MS/E/SZ/2018/2320 dated 12/08/2018

5. Fire Safety directives Letter No.: NIL.

6. Date of inspection

: 14/06/2021

7. Name of the Inspecting Officers: A.D.O. (S.J.)

8. Name and designation of Officer

from the building side

: Sh. Vinod Kumar (Head Fire & Safety GMR) :2010

9. Year of Construction

S	Applicant's letter received through Minimum standards on fin	ign email <u>ID-Hrishik</u>	esan.P@gmrgroup	in dated 13	/04/2021	
N	prevention and fire safety	11111010	NOC Provid		Remark	
	U/R 33	Requiremen	nts site		MR/NM	
1.					TATTO TATA	
	Road width	9 m			3	
	Gate width	NA	Provided	1	MR /	
	Width of internal ro	NA NA	NA		VA	
2.	Number, width, Type & An	oad 6m	Provided	N	ИR	
	a. Number of staircase	its				
	Upper floors	2				
6	Basements		Provide	d	MR	
	b. Width of staircases	NA	NA		NA	
	Upper floors	4.50	Sac an			
	Basements	1.50 m	Provided		MR	
	c. Protection of exits	NA	NA		NA	
	• Fire check door				1	
	Pressurization	Required	Provided	M	R	
	d. No of continuous	NA	NA	NA		
	staircase to terrace	Required	2	MF	3	
	e. Width Of Corridor	NA				
	f. Door Size	NA	NA	NA		
3.	Compartmentation	100	NA	NA		
	 Fire check door 	Required				
	 Sealing of electrical 	Required	Provided	MR		
-	shafts	Required	Provided	MR	MR	
	 Fire Rating of shaft door 	1 hour	Duanit			
-	 Water Curtain 	NA	Provided	MR	2 ₁₂ 2	
_	 Fire Dampers 	NA	NA	NA	×	
	Smoke managements System		NA	NA		
	 Basements 	NA	N.O.			
	 Upper floors 	12 ACPH	NA N	NA		
	Fire Extinguishers		M.V. Provide	d MR		
	 Total numbers 	Required	36	AAD		
	Types	ABC/CO ₂ /WCO2		MR		
	 ISI marking 	ISI	12/12/12	MR		
			Provided	MR		

		/	4-20	
6.	First – Aid Hose Reels	1 (a) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c		
	 Total numbers on each floor 	2	Provided	MR
	Length of hose reel hose	30 Mtr.	30 Mtr.	MR
	 Nozzle diameter 	5 mm	5 mm	MR
7.	Automatic fire detection and	alarming system		
	Type of detector	Smoke & Heat	Provided	MR
	 Location of Main Panel 	Ground Floor	Provided	MR
8.	 Location of Repeater Panel 	Required	FCC	MR
	Alternate source of power	Required	Provided	MR
	 Hooters' Location 	Required	All Areas	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			IVIIV
	• Basements	NA	NA	NA
	 Upper Floor 	Required	Provided /	MR
	 Sprinkler above false 	Required	Provided	MR
11.	ceiling			1000
11,	Internal Hydrants			
	Size of riser/down- comer	100 mm	Provided	MR
	 Number of hydrants per floor 	2	Provided	MR
	 Hose Box 	2	Provided	MR
12.	Yard Hydrants			
	 Total number of hydrants 	4	Provided	MR
	 Hose Box 	4	Provided	MR
13.	Pumping Arrangements			
•	Ground Level			
•	Discharge of main pullip	2280 LPM	Provided	MR
	panip	70 m	Provided	MR
	- things of main painps	2	Provided	MR
<u> </u>	pump out put	280 LPM x 2	Provided	MR
	- control pump mead	70m /	Provided	MR
<u> </u>	amp out put	2280 LPM	Provided	MR
	- turing I drip I lead	70m	Provided	MR
	Auto Staring/Manual stopping	Required	Provided	MR
>		Required	Provided	
•	Terrace level	ricquired	Provided	MR
>	Discharge of pump	900 LPM /	Provided	840
>	Head of the pump	40 m	Provided	MR
>		Required	Provided	MR
>	Auto starting of pump	Required	Provided	MR
			Tovided	MR
		Sold		

एम सी सी (डांड्या) किस्

	· VIPOI						
14.	Captive water Storage for fire fighting						
,	 Under Ground tank 	2,50,000 ltr		Provided	MR		
	capacity						
	> Draw of connection	Required		Provided	MR		
	Fire service inlet	Required Required 10,000 ltr		Provided	MR		
	Access to tank			Provided	MR		
	Overhead Tank capacity			Provided	MR		
15	Exit Signage	Required		Provided	MR		
16.	Provision of Lifts	Trovided			1711		
	Pressurization of Lift Shaft	NA NA			NA		
	Pressurization of lift lobby	NA	NA NA		NA		
	Communication in lift Car	NA	NA		NA		
	Fireman's Grounding Switch	Required	Pro	vided	MR		
	➤ Lift Signage	Required	Pro	vided	MR		
17.	Standby power supply	Required	Pro	vided	MR		
18.	Refuge Area			2			
	> Total area	N/A	N/A N/A		N/A		
	> Location	N/A	N/A	1	N/A		
19.	Fire control room		,				
	Detector system panel	Required Required Required Required		Provided	MR		
2	> Flow Switch Panel			Provided	MR		
	> PA System Panel			Provided	MR		
	> Battery backup			Provided	MR		
	Building Floor Plans	Required		Provided	MR		
20.	Special Fire Protection	NA		NA	NA		
	Systems for Protection of			in the second se			
	special Risks, if any;			a To a div			
	· · · · · · · · · · · · · · · · · · ·						

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/E/SZ/2018/2320 dated 12/08/2018 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer Name : Ashok Kumar Jaiswal

Designation: A.D.O. (S.J.)