

C-25

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

NEW DELHI- 110001


No.F6/DFS/MS/School/2021/SZ/ 425

Dated: 2/7/21

FIRE SAFETY CERTIFICATE

Certified that the Govt. Sarvodaya Bal Vidyalaya No-3, Tilak Nagar, New Delhi-110018., Comprised of ground plus three upper floors (New Block) owned/occupied by Govt. Sarvodaya Bal Vidyalaya have complied with the fire prevention and fire safety requirements in accordance with the rule 33 of the Delhi Fire Service Rules 2010 and verified by the officer concerned of this department on 17/06/2021 in the presence of Smt. Nutan Sharma (Vice-Principal) of the school and that the school building is fit for occupancy class B 'Educational Building' for with effect from 2/7/21.... for a period of **three** years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on.....2/7/21.....at New Delhi by


(Anil Garg)
Director
Delhi Fire Service
ofeq.

Copy to:-

1. The Principal, Govt. Sarvodaya Bal Vidhyalaya No-3,
Tilak Nagar, New Delhi--110018.
2. Director of Education, GNCT of NCT of Delhi, Old Secretariat.

Following fire safety directives must be adhered to:-

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building : Sarvodaya Bal Vidyalaya No-3, Tilak Nagar, New Delhi-110018.
2. Building is comprised of : Ground plus three upper Floors (New Block)
3. Type of Occupancy : Educational
4. Type of Case : New
5. Details of Previous NOC : Nil
6. Fire Safety direction letter No : NBC Part-IV
7. Date of Inspection : 17/06/2021
8. Name of the Inspecting Officers: : ADO R.K. YADAV
9. Name of the designation of Officer
from the building side : Smt. Asha (Principal)
10. Year of Construction : 2020
11. Applicant's letter No : No.54(SPS School) PWD Edu. Sub-Divn M1-1(N)2021-22/39 Date 06/04/2021

S.No	Minimum Standards on fire prevention and fire safety requirements U/R 33	Requirement	Provided at Site	Remarks MR/NMR	
1	Access to building				
	Road width	6 m	06 m	MR	
	Gate width	4.5 m	05 m	MR	
	Width of internal road	N.A.	N.A.	N.A.	
2	Number, Width, Type and Arrangement of Exits				
	a. Number of Staircases	Upper Floor	02 no.	02 no.	MR
		Basement	N.A.	N.A.	N.A.
	B. Width of Staircases	Upper Floor	N.A.	N.A.	N.A.
		Basement	1.50 m	1.80 m each	MR
	c. Protection of exits	Fire check door	N.A.	N.A.	N.A.
		Pressurization	N.A.	N.A.	N.A.
	e. No. of continuous staircases to terrace	02 no.	02 no.	MR	
	g. Width of Corridor	Upper Floor	1.50 m	1.60 m	MR
		Basement	1.20 m	1.30m	MR
3	Compartmentation.				
	Fire check door	N.A.	N.A.	N.A.	
	Sealing of electrical shafts	N.A.	N.A.	N.A.	
	Fire rating of shaft door	N.A.	N.A.	N.A.	
	Water curtain	N.A.	N.A.	N.A.	
	Fire Dampers	N.A.	N.A.	N.A.	
4	Smoke Management System.				
	Basement	N.A.	N.A.	N.A.	
	Upper floor	Required	Natural Ventilation	MR	

14	Captive Water Storage for Fire Fighting.			
	Underground tank capacity	N.A.	N.A.	N.A.
	Draw-off connection	N.A.	N.A.	N.A.
	Fire service inlet	N.A.	N.A.	N.A.
	Access to tank	N.A.	N.A.	N.A.
	Overhead Tank capacity	10,000 ltrs	10,000 ltrs	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of Lift Shaft	N.A.	N.A.	N.A.
	Pressurization of Lift lobby	N.A.	N.A.	N.A.
	Communication in lift car	N.A.	N.A.	N.A.
	Firemen's grounding switch	N.A.	N.A.	N.A.
	Lift Signage	N.A.	N.A.	N.A.
17	Standby power supply	N.A.	N.A.	N.A.
18	Refuge Area.			
	Total area	N.A.	N.A.	N.A.
	Location	N.A.	N.A.	N.A.
19	Fire Control Room			
	Detector system panel	N.A.	N.A.	N.A.
	Flow switch panel	N.A.	N.A.	N.A.
	PA system panel	N.A.	N.A.	N.A.
	Batter backup	N.A.	N.A.	N.A.
	Building Floor Plans	N.A.	N.A.	N.A.
20	Special Fire Protection systems for protection of special Risks, if any:	N.A.	N.A.	N.A.

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards of fire prevention and fire safety measures under rule 35 of the Delhi Fire Service Rules 2010 it is recommended to grant Fire Safety Certificate.

R. K. Yadav
22/6/2021

Signature of the Inspecting Officer
Name R K YADAV
Designation ADO (JKP)

DO(South West)

K. J. K.
23/06/2021

Dy. Chf. (S2)

24/6

NFO

Kamp

FIR

2021

