0-23

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No.F6/DFS/MS/School/NDZ/2021/ 465

Dated:-

9 /07/2021

## FIRE SAFETY CERTIFICATE

Certified that the Rajkiya Sarvodaya Kanya/Bal Vidyalaya, No. 2 located at Mandiwali, Delhi-92 comprised of Ground + 01 Upper floor, owned/occupied by Rajkiya Sarvodaya Kanya/Boys Vidyalaya, was granted FSC by this department vide letter No. F6/DFS/MS/School/NDZ/2018/1062 dated 15/05/2018. The premises was re-inspected by the officer concerned of this department on 02/07/2021 in the presence of the Mr. Vibhav Parshad (Principal), Mr. Vijay Shankar (Estate Manager) & Mr. Divakar Bhadol and found that school have deemed complied with the fire prevention and fire safety requirements in accordance with Circular No. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01/03/2011 issued by Director of Education and the building premises is fit for occupancy of class Group B "Educational Building" Sub-Div. (B-I) Gr. + 1 only with effect from ------2/------2021 for a period of three years, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

(Dr. S.K. Tomar) Dy. Chief Fire Officer Delhi Fire Service

7270 mer

Copy to:-

1. The Dy. Director of Education, D-Block, Anand Vihar, Delhi-91.

 The Principal (Ist Shift & IInd Shift), Rajkiya Sarvodaya Kanya/Bal Vidyalaya, East Vinod Nagar, Delhi-91. Kanya School Id:- 1002023, Bal School Id:- 1002367

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

## INSPECTION REPORT

1. Name & address of the building:- Rajkiya Sarvodaya Kanya/Bal Vidyalaya, No. 2 located at Mandiwali, Delhi-92

Kanya School Id:- 1002023, Bal School Id:- 1002367

2. Type of occupancy:- Educational Group

Gr.+01 Upper Floor

3. Type of case:- Renewal

F6/DFS/MS/School/NDZ/2018/1062 dated

4. Details of previous NOC:- F6/DFS/MS 15/05/2018

Circular dated 01.03.2011

5. Fire safety directives No.-6. Date of inspection:-

02/07/2021

7. Name of the inspecting officer:-

Sh. Manoj Kumar Sharma (ADO/LN)

8. Name & designation of officer From the building side:-

Mr. Vibhav Parshad (Principal), Mr. Vijay Shankar (Estate Manager) & Mr. Divakar Bhadol

9. Year of construction:-

1982 email dated 18/06/2021.

10. Applicant's letter No:-

Old Case Remarks Provided at site Requirement Minimum Standards on fire S.No. MR/NMR Circular Prevention and fire safety U/R 33 Access to Building 1. MR 06 mtr. 06 mtr. 1) Road width NA NA NA 2) Gate width NA NA NA 3) Width of internal road Number, Width Type & Arrangement of Exits 2. A. Number of staircases MR 03 nos. 03 nos. 1. Upper floors N/A N/A N/A 2. Basements B. Width of staircase MR 1.5 mtr. each 1.5 mtr 1. Upper floors N/A N/A N/A 2. Basements C. Protection of exits N/A N/A N/A 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous staircase to terrace MR 1.5 mtr. 1.5 mtr E. Width of corridor MR 1.0 mtr. 1.0 mtr. F. Door size Compartmentation 3. N/A N/A N/A 1) Fire check door N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers Smoke Management System 4. N/A N/A N/A 1) Basements N/A N/A N/A 2) Upper floors Fire Extinguishers 5. MR 19 Nos. 15 Nos. 1) Total numbers MR ABC, CO2 ABC & CO2 2) Types

	3) ISI marking	Required	Provided	MR			
5.	First-Aid Hose Reel						
	1)Total number of each floor	N/A	N/A	N/A			
	2) Length of hose reel hose	N/A	N/A	N/A			
	3) Nozzle diameter	N/A	N/A	N/A			
7.	Automatic Fire Detection & Alarming System						
	1) Type of detectors	N/A	N/A	N/A			
	2) Location of main panel	N/A	N/A	N/A			
	3) Location of repeater panel	N/A	N/A	N/A			
	4) Alternate source of power	N/A	N/A	N/A			
	5) Hooter's Location	N/A	N/A	N/A			
8.	MOEFA	N/A	N/A	N/A			
9.	Public Address System	N/A	N/A	N/A			
10.	Automatic Sprinkler System						
	1) Basement	N/A	N/A	N/A			
	2) Upper floors	N/A	N/A	N/A			
	3) Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
	1) Size of riser/down-comer	N/A	N/A	N/A			
	2) Number of hydrants per	N/A	N/A	N/A			
	floor			1000			
	3) Hose box	N/A	N/A	N/A			
12.	Yard Hydrants						
	1) Total number of hydrants	N/A	V/A N/A				
	2) Hose box	N/A	N/A	N/A			
13.	Pumping Arrangement			*			
	1) Ground level	N/A	N/A	N/A			
	a) Discharge of main pum	p N/A	N/A	N/A			
	b) Head of main pump	N/A	N/A	N/A			
	c) Number of main pump	N/A	N/A	N/A			
	d) Jockey pump out put	N/A	N/A	N/A			
	e) Jockey pump head	N/A	N/A	N/A			
	f) Stand by pump output	N/A	N/A	N/A			
	g) Stand by pump head	N/A	N/A	N/A			
	h) Auto starting/Manual stopping	ng N/A	N/A	N/A			
	2) Terrace level						
	a) Discharge of pump	N/A	N/A	N/A			
	b) Head of pump	N/A	N/A	N/A			
	c) Power supply	N/A	N/A	N/A			
	d) Auto starting of pump	N/A	N/A	N/A			
14.	Captive Water Storage for Fire Fighting						
	1) Under ground tank capacity	N/A	N/A	N/A			
	a) Draw-off connection	N/A	N/A	N/A			
	b) Fire service inlet	N/A	N/A	N/A			
	c) Access to tank	N/A	N/A	N/A			
	d) Over head tank capacity	N/A	N/A	N/A			

w

सरकार का उद्यम

15.	Exit Signage.	N/A	N/A	N/A
16.	Provision of Lifts.		1111	14/21
K-	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for	or Protection of spec	cial Risk, if any:	N/A

The fire protection system provided in the school building were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F6/DFS/MS/School/NDZ/2018/1062 dated 15/05/2018, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name :- M.K. Sharma Designation: - ADO (LN)

Dy.CFO/NDZ

f.t. letter is put up for kig

mscell

