GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/Motel/SZ/2021/ 330

Dated: 15/07/2021

FIRE SAFETY CERTIFICATE

Certified that the Motel Building in the name & style of M/s Belmond Hotel Pvt Ltd., situated at Khasra No. 5, 6, 7, 8, 9, 10, 11 & 14, Village Sahoorpur, Satbari New Delhi - 110037 comprised of department vide issued FSC this by floor has and Ground F6/DFS/MS/Motel/SZ/2017/1808 Dated 13/12/2017. The premise was re-inspected by the officer concerned of this department on 08/07/2021in the presence of Sh. Mandeep Singh (Director) and found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010and that the building is fit for occupancy Group A "Residential (Motel) Building" with effect 15/07 2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

(Sunil Chawdhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to:-

1. The Joint Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049

2. Sh. Mandeep Singh (Director), M/s Belmond Hotel Pvt Ltd., situated at Khasra No. 5, 6, 7, 8, 9, 10, 11 & 14, Village Sahoorpur, Satbari New Delhi – 110037

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.

5. This fire safety certificate may not in any way be treated as regularization of unauthorized

construction, if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT 1. Name & address of the building : Motel Building, Ms Belmond Hotel Pvt Ltd., (Earlier Known as Exotic Motel) Khasra No. 5,6,7,8,9,10,11,& 14, Village Sahoorpur, Satbari New Delhi-37 Type of Occupancy : Group A "Residential" (Motel) Building [Basement + G. Floor] 3. Type of Case : Renewal 4. Details of Previous NOC : F6/ DFS/ MS/Motel/ SZ /2017/1808 Dated 13/12/2017 5. Fire Safety directives letter No : F6/DFS/GH/BP/2005/313 Dated 15/02/2005 6. Date of inspection : 08/07/2021 7. Name of Inspecting Officer : Sh. Rajesh Kumar ADO (BCP) 8. Name and designation of officers 9. From the building side : Mr. Mandeep Singh (Director) 10. Year of Construction : 2005-08 11. Applicant's letter No : Gmail dated 08/07/2021 S. Minimum Standards on fire prevention and Provided at site **Old NOC** Remarks No. fire safety U/R 33 Requirement MR/NMR Access to building 1. Road width 9m Provided . MR 5_m Provided Gate width MR 6m Provided MR Width of internal road 2. Number, Width, Type & Arrangement of Exits d. Number of staircases Upper Floors -NA--NA--NA-Basements 7 Nos Provided MR e. Width of staircases Upper Floor -NA--NA--NA-2.73m, 1.45m, 1.39m, 1.5m MR(old case) 1.43m 1.44m, 1.48m, **Basements** & 2.43m (Bi-Furcated) f. Protection of exits Fire check door Required Provided MR Pressurization -NA--NA--NAd. No. of continuous staircases to terrace Required Five MR Width of Corridor Required Provided MR f. Door Size 1m 1 m (Final Exit) MR 3. Compartmentation Fire check door Required Provided MR Sealing of electrical shafts Required Provided MR Fire Rating of shaft door Required Provided MR Water Curtain -NA--NA--NA-Fire Dampers -NA--NA--NA-4. Smoke Management System 30 ACPH **Basements** Provided MR Upper floors 12 ACPH Natural ventilation MR 5. Fire Extinguishers Total numbers 40 Nos Provided MR ABC/W.Co₂/Co₂ **Types** 10/10/06 Nos MR IS marking ISI Yes MR 6. First-Aid Hose Reels Total numbers on each floor Required 04 Nos MR Length of hose reel hose 30m Provided MR 5mm Nozzle diameter Provided MR 7. Automatic fire detection and alarming system Type of detectors NA Provided NA Location of Main Panel NA Ground Floor NA Location of Repeater Panel -NA-

त्तारत हा ता कृषया लाटाए

NA

-NA-

~~~	Alternate source of power	NA	Provided	NA			
	<ul> <li>Hooters' Location</li> </ul>	Required	All Floors	MR			
3.	MOEFA	Required	Provided	MR			
).	Public Address System	Required	Provided	MR			
0.	Automatic Sprinkler System     Basement Required Provided						
		Required	Provided	MR			
	<ul><li>Upper Floors</li><li>Sprinkler above false ceiling</li></ul>	Required	Provided	MR			
11.	Internal Hydrants	-NA-	-NA-	-NA-			
	Size of riser/down-comer	100mm	Provided	MD			
	Number of hydrants per floor	4 Nos	Provided	MR MR			
	Hose Box	4 Nos	Provided	MR			
12.	1 1 1 TOVICE						
	Total number of hydrants	NA	14 Nos	NA			
	Hose Box	NA	14 Nos	NA NA			
13.	Pumping Arrangements	1471	14 1105	INA			
	Ground Level						
	Discharge of main Pump	2280 LPM	Provided	MR			
	➤ Head of Main pump	60m	Provided	MR			
	Number of main pumps	One	Provided	MR			
	Jockey Pump out put	180 LPM	Provided				
	Jockey pump head	60m		MR			
	Standby Pump out put		Provided	MR			
	Standby Pump Head	2280 LPM	Provided	MR			
	Auto Starting/Manual Stopping	60m	Provided	MR			
	Pump House Access	Required	Provided	MR			
	•	Required	Provided	MR			
	Terrace level		14.				
	Discharge of pump	900LPM	Provided	MR			
	<ul><li>Head of the pump</li><li>Power Supply</li></ul>	40m	Provided	MR			
	<ul><li>Auto Starting of pump</li></ul>	Required	Provided	MR			
	ratio stating of pump	<ul> <li>Required</li> </ul>	Provided	MR			
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	1,00,000 Ltrs	Provided	MR			
	Draw-off connection	Required	Provided	MR			
		Required	Provided	MR			
	<ul><li>Fire service inlet</li><li>Access to tank</li></ul>	Required	Provided	MR			
	Overhead Tank capacity	30,000 Ltrs	50,000 ltrs	MR			
15.	Exit Signage.	Required	•				
16.	Provision of Lifts.  Required Provided MR						
	D : : OXIO SI O						
	<ul><li>Pressurization of Lift Shaft</li><li>Pressurization of Lift lobby</li></ul>	-NA-	-NA-	-NA-			
	Communication In lift Car	-NA-	-NA-	-NA-			
	Fireman's Grounding Switch	-NA-	-NA-	-NA-			
	• Lift Signage	-NA-	-NA-	-NA-			
		-NA-	-NA-	-NA-			
7.	Standby power supply	Required	Provided	MR			
8.	Refuge Area.						
	> Total Area	-NA-	-NA-	-NA-			
	Location	-NA-	-NA-	-NA-			
9.	Fire Control Room						
	Detector System Panel     -NA-     -NA-						
	Flow Switch Panel	-NA-	-NA-	-NA-			
	PA System Panel						
		-NA-	-NA-	-NA-			
	<ul> <li>Battery backup</li> </ul>	NA	NIA	NTA			

N133

F		•	Building Floor Plans	-NA-	-NA-	-NA-
	20.	Speci	f any:	-NA-		

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 531 dated 04/03/2021.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/Motel/ SZ /2017/1808 Dated 13/12/2017, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Rajesh Kumar Designation: ADO / BCP

DONO- on Leave

Dy child

A DO (BCP)

As approved, F.T. tettel

F.T. tettel in faith for ?

townstore Pl

1317

Dyckir

all