FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No.F6/DFS/MS/EH/SZ/2021/ \(\) 33

Dated: 14/7/21

- 11

## FIRE SAFETY CERTIFICATE

Certified that the M/s Puriob Grill A Unit of Lite Bite Foods Pvt. Ltd. located at Shop No.-3, Ground Floor, World Mark-1, Aerocity, IGI Airport, New Delhi-110037, comprised of Three tier Basement, Ground, Six Upper Floors & Terrace Floor owned / occupied by M/s Punjab Grill A Unit of Lite Bite Foods Pvt. Ltd., was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/EH/2018/SZ/2665 dated 10/12/18. The premises was reinspected by the officer concerned of this department on 03/07/2021 in the presence of Sh. Arun Negi (Manager) and observed that all the Fire prevention and Fire Safety arrangements provided in the premises found in good working condition. The premises have therefore, deemed complied with rule 33 of the Delhi Fire Service rules, 2010 and that the building / premises is fit for occupancy Class Assembly "Restaurant" (Group-D) with effect from 14/7 /2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliant of conditions under 38 of the Delhi Fire Service rules, 2010.

Issued on ... 1.4/7/21... at New Delhi by.

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (S.Z.).

Copy to:-

1. Authorized Signatory, M/s Punjab Grill A Unit of Lite Bite Foods Pvt. Ltd., Shop No.-3, Ground Floor, World Mark-1. Aerocity. IGI Airport, New Delhi-110037.

2. Joint Commissioner of Police (Lie.), 1st Floor, Police Station, Defence Colony, New Delhi-110024.

010 16

## Conditions for the validity of Fire Safe y Certificate:

1. All the means of escape / entry / exat shall be kept free from any obstruction.

2. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.

3. Any loss of life or property due to non- functional fire safety measure shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of fire fighting system.

5. This Fire Safety Certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3. of UBBL-2016), if any.

6. This certificate cannot be treated having case for regularizations of unauthorized construction.

7. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this (sub rule 4.5) months prior to its expiry".

8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is a milable on VWW.dfs.Delhigovt.nic.in.

Covered area of the restaurant is 185m<sup>2</sup> and as per NBC (Part-IV) the no. of occupants comes out to be Approx. 103 (185/1.8=102.77). Thus capacity of restaurant is 103 persons which is covered under DFS Act 2007, Rules 2010. Subsequently inspection of Eating House is carried out as per NBC (Part-IV).

1. Name & address of the building: M/s Punjab Grill A Unit of Lite Bite Foods Pvt. Ltd., Shop No.-3, Ground Floor, World Mark-1, Asset No-11, Aerocity, IGI Airport, New Delhi-110037.

2. Type of Occupancy : Assembly (Group-D) (Eating House) Restaurant at ground floor only.

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/EH/2018/SZ/2665 dated 10/12/18

5. Fire Safety directives Letter No.: F6/DFS/MS/BP/2017/Hotel/368 dated 21/02/2017 6. Date of inspection : 03/07/2021

7. Name of the Inspecting Officer: A.D.O. (S.J.)

8. Name and designation of Officer

Types

from the building side : Sh. Arun Negi (Manager)

9. Year of Construction : 2014

10		. 2017
10.A	applicant's letter	: MHA Id-2021061613923 dated 16/06/2021
C	Minimum standards on fire	1441111 d 2021001013923 dated 16/06/2021
D	Willimum Standards on fire	IIBBI / NBC 2016

S	Minimum standards on	~	: MHA I	1-20	)21061613			6/2021	
No			l .	UBBL / NBC-2016 Requirements Provide site			d at	Remarks	
140	prevention and fire safe U/R 33	ety	Requirem					MR/NMF	
1.	Access of building (Asset	Access of building (Asset No.11 NOC-F6/DFS/MS/Mixed/SZ/2021/0					datad	00/02/04	
	Road width		Restt located		Δς ΔΙ				
	Gate width		within Worldmark-1					MR NA	
	Width of international	al				As Above			
	road				, AS AL	·	NA		
2.	Number, width, Type &	umber, width, Type & Arrangements of exits							
	a. Number of staircases Provided & Maintained by Bldg. Mgmt.								
	<ul> <li>Upper floors</li> </ul>		NA As Above				NIA		
	<ul> <li>Basements</li> </ul>		NA	7.10000			NA NA		
	b. Width of staircas	ses	Provided & Maintained by Bldg. Mg			mt	NA		
	<ul> <li>Upper floors</li> </ul>		NA	NA As Above				IA.	
	<ul> <li>Basements</li> </ul>		NA			T.		IA IA	
	c. Protection of exi	ts	Provided 8		aintained b	V Bldg Ma	mt	IA	
30	<ul> <li>Fire check door</li> </ul>		NA		s Above	y Diag. IVIS	N.	Λ	
	<ul> <li>Pressurization</li> </ul>		NA		s Above			y, and the second	
	d. No of continuous		Required	Required As Abo			_	A	
	staircase to terrac	e					IV	IR	
	e. Width Of Corrido	or	NA	NA NA		N		4	
3.	f. Door Size			2m & 1.35m 2m		& 1.5m		R	
٥.	Compartmentation		Provided & Maintained by Bldg. Mgmt.			nt.			
	<ul> <li>Fire check door</li> </ul>		Required	As Above			MR		
	<ul> <li>Sealing of electrical shafts</li> </ul>		Required	As Above			MR		
	<ul> <li>Fire Rating of shaft d</li> </ul>	oor	Required	As	Above		M	D	
	<ul> <li>Water Curtain</li> </ul>		Required	As Above			MR MR		
	<ul> <li>Fire Dampers</li> </ul>		NA	As Above			NA NA		
4.	Smoke managements Sys	oke managements System Provided & Maintained by Bldg. I			v Bldg Ma	mt	1		
7	• Basements	NÄ			As Above		NA		
	<ul> <li>Upper floors</li> </ul>	Requ	uired		Smoke venting			NA	
5.	Fire Extinguishers				JJRC VC			MR	
	<ul> <li>Total numbers</li> </ul>		6		Provided		M/I	R	

ABC, CO<sub>2</sub> &

WCO<sub>2</sub>

M/R

ABC, CO<sub>2</sub>, Water

CO<sub>2</sub>

6.	First – Aid Hose Reels	Provide	Provided & Maintained by Bldg. Mgmt.				
	Total numbers on	1	a a ivialitali	As above	MR		
	<ul><li>each floor</li><li>Length of hose reel</li></ul>	30 Mtr.		As above	MR		
	hose			As above	IVIK		
7.	Nozzle diameter  Automotic Sur Let diameter	5 mm		As above	MR		
/.	Automatic fire detection and alarm		Provided & M				
2	<ul><li>Type of detector</li><li>Location of Main</li></ul>	N/A		Smoke & Hea			
	Panel	N/A	A.	Mezzanine Floor	N/A		
3	Location of Repeater Panel	· N/A		FCR at GF	N/A		
	Alternate source of power	N/A		Provided	NA		
	Hooters' Location	N/A		All Area	NA		
8.	MOEFA	Required	1	Provided	MR		
9.	Public Address System	NA	•	As above	NA		
10.	Automatic Sprinkler System	(Provided &	Maintained	by Bldg. Mgm	t.		
	• Basements	NA		As above	NA		
	<ul> <li>Upper Floor</li> </ul>	NA		As above	NA		
	Sprinkler above false ceiling	NA		As above	NA		
11.	Internal Hydrants (Provided &	Maintained	by Bldg. Mg	mt )			
8	Size of riser/down- comer	NA	7 - 180 1118	As above	NA		
	Number of hydrants per floor	NA		As above	NA		
	Hose Box	NA	NA As above		NA		
12.	Yard Hydrants (Provided & Ma	intained by	Bldg. Mgmt.		1111		
	<ul> <li>Total number of hydrants</li> </ul>	NA	As above		NA		
	<ul> <li>Hose Box</li> </ul>	NA	As above		NA		
13.	Pumping Arrangements (Provi	ded & Main	tained by Blo	lg. Mgmt.)			
•	Ground Level		.50				
-	Discharge of main pump	NA	2280 L	PM	NA		
	Head of main pump	NA	105m		NA		
	Number of main pumps	NA	2		NA		
	Jockey pump out put		180 LPI	M x 2	NA		
	Jockey pump head		105m		NA		
-	Standby Pump out put		2280 LI	PM	NA		
	Standby Pump Head		105m		NA		
	stopping /	NA	Provide	ed	NA		
-	1	NA	Provide	d .	NA		
•	Terrace level	450 LPM					
-				OOLPM	MR		
<u> </u>	pump	40m		ovided	MR		
7	T. P. J.	Required	Pi	rovided	MR		
	Auto starting of pump	Required		rovided	MR		
14.	Captive water Storage for fire  • Underground tank	fighting (Pro					
0	<ul> <li>Underground tank</li> </ul>	NA	1,50,0	00ltr	NA		

का उद्यम्।

		NIT				
15	Exit Signage	Signage Required Provided		MR		
16.	Provision of Lifts Prov	Bldg. Mgmt.				
	<ul><li>Pressurization of Lift Shaft</li></ul>	NA	As above	NA		
	Pressurization of lift lobby	NA	As above	NA		
	Communication in lift Car	NA	As above	NA		
	Fireman's Grounding Switch	NA	As above	NA		
	➤ Lift Signage	NA	As above	NA		
17.	Standby power supply	Required	Provided	MR		
18.	Refuge Area	Provided & Maintain	laintained by Bldg. Mgmt.			
	> Total area	N/A	550m <sup>2</sup>	N/A		
	> Location	N/A	6 <sup>th</sup> Floor	N/A		
19.	Fire control room (Provided & Maintained by Bldg. Mgmt.)					
	> Detector system panel	NA	As above	NA		
	> Flow Switch Panel	NA	As above	NA		
2	> PA System Panel	NA	As above	NA		
	Battery backup	NA	As above	NA		
	<ul><li>Building Floor</li><li>Plans</li></ul>	NA	As above	NA		
20.	Special Fire Protection	NA				
	Systems for Protection of					
	special Risks, if any;		200			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/EH/2018/SZ/2665 dated 10/12/18 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer : Ashok Kumar Jaiswal Name

Designation: A.D.O. (S.J.)

DO (SD) Place the I keport of Fisc in no world mark-I, Aerocity, on the file.

ADD(87)

ADD(87)

Worldmark - 1 (Asset No-11) has already been world mark - 1 (Asset No-11) has already been usual lugthis depth. Wide L. No. 09 / 08.03. 2021 and usual lugthis depth. Wide L. No. 09 / 08.03. 2021 and usual lugthis depth. Wide L. No. 09 / 08.03. 2021 and usual lugthis depth. Wide L. No. 09 / 08.03. 2021 and usual lugthis depth. Wide L. No. 09 / 08.03. 2021 and usual lugthis depth.