GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI – 110001

NO. F.6/DFS/MS/Hospital/SZ/2021/ 320

Dated / 3/07/2021

FIRE SAFETY CERTIFICATE

Certified that Surgical Block, Masjid Moth, AIIMS New Delhi, comprised of 3 tire basement, Ground plus eight upper floors have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service rules, 2010 and verified by officers concerned of this department on 02/07/2021 in the presence of Mr. Vasisth (HSCC) and that the building/premises is fit for occupancy class Institutional building Group—C as above with effect from for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire service rule 2010.

Issued on ---- at New Delhi by

Director

Delhi Fire Service

Copy to :-

1. The chief Architect NDMC, Palika Kendra, New Delhi- w.r.t. File No.-0044/11-OCC

2. Sh. Deepak Bhutale Ex. Engineer (C - III), Room No. 208- A, Admin Block, AIIMS, New Delhi-110029

Condition for the validation of Fire Safety Certificate :-

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times. As seen during inspection. Any loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi fire service 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. This Fire Safety Certificate may not be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner / occupier shall apply for renewal of this fire safety certificated to the director in Form 'the [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to it expiry.

0	INSPECT	ION REPORT				
1	Name & Address of the Building	lding Surgical Block, Masjid Moth, AIIMS, New Delhi.				
2	Type of Occupancy	Institutional building, "Group-C" (Hospital)				
3	Building Comprised of	3 Tier Basements, Ground + 8 upper floors.				
4 .	Type of Case	New				
5	Details of Previous NOC	N/A				
6	Fire Safety Directives Letter No	F.6/DFS/MS/BP/Hospital/2013/51 dated				
7	Data of Ingraction	15.04.2013 02-07-2021				
7 8	Date of Inspection Name of the Inspecting Officers	DCFO (SZ) & DO (SD)				
9	Name & Designation of Officers	C(India) Limited				
)	from the building side					
10	Year of construction	2021				
11	Applicant letter No.	Joint Online dated 30-06-2021				
S.	Minimum standards on Fire Prevention	NBC/BBL Provided at Site Remarks				
No.	and Fire Safety U/R 33	Requirement		MR/NMF		
1	Access to Building.		7 1 1) (D)		
	Road width	9m	Provided	MR		
	Gate width	6m	Provided	MR		
	Width of internal road	6m	Provided	MR		
2	Number, width, type & arrangement of	of exits.				
	a) Number of Staircase					
	Upper floors.	2 Nos	Provided	MR		
	Basement floor.	2 Nos	Provided	MR		
	b) Width of Staircase		3	1		
	> Upper floors	2m	Provided	MR		
	Basement floor	2m	Provided	MR		
	c) Protection of exits					
	Fire check door	Required	Provided	MR		
	Pressurization	NA	NA	NA		
	d) No. of continuous staircase to terrace	2 Nos	Provided	MR		
		2.40m	Provided	MR		
	e) Width of corridor	2.40m	Provided	MR		
	f) Door size	2111	Flovided	IVII		
3	Compartmentation.	D : 1	Provided	MR		
	• Fire check door.	Required		NA		
	• Sealing of electrical shafts.	Required	Provided			
	• Fire rating of shaft door.	Required	Provided	NA		
	Water curtain	NA	NA	NA		
	• Fire dampers.	Required	Provided	MR		
4.	Smoke Management system.		.5	_		
	Basement	30 ACPH	Provided	MR		
	• Upper floors	12 ACPH	Provided	MR		
5	Fire Extinguishers.					
	Total numbers	80 Nos	85 Nos	MR		
	• Types	ABC/W.CO2/CO2	Provided	MR		
	ISI Marking	ISI marked	Provided	MR		
(First Aid Hose Reels.	101 marked				
6		Two	Provided	MR		
	Total numbers on each floor.	572 31 30 318	Provided	MR		
	• Length of hose-reel hose.	30m				
	Nozzle Diameter	5mm	Provided	MR		

7	Automatic Fire detection & Alarming	system.		-
	Type of detectors	Smoke & Heat	Provided	MR
	Location of Main Panel	Ground floor	Provided	MR
	 Location of Repeater Panel 	-NA-	-NA-	-NA-
	Alternate source of power	Required	Provided	MR
	Hooter's location	All Areas	Provided	MR
8	MOEFA	Required	Provided	MR
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System	1		
	Basement	Required	Provided	MR
	• Upper floors.	Required	Provided	MR
	Sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants.	1		
	Size of Riser/Down-comer	150mm	Provided	MR
	Number of Hydrant per floor	2 Nos	Provided	MR
	Hose box.	2 Nos	Provided	MR
12	Yard Hydrants.	21103	1101100	IVIIX
	Total number of hydrants.	Required	5 Nos	MR
	Hose box.	Required	5 Nos	MR
13	Pumping arrangements.	Required	3 1108	IVIK
15	Ground Level			
	Discharge of main pump.	Hyd.=2280 LPM	Hyd.=2280 LPM	
	Disentings of main pump.	Spkr=2850 LPM	Spkr=2850 LPM	MR
	Head of main pump.	85m each	Provided	MR
	Number of main pumps.	2 Nos.	2 Nos.	MR
	Jockey Pump output.	280 & 180 LPM	Provided	MR
	Jockey Pump head.	85m	Provided	MR
	> Standby Pump output.	2850 LPM	Provided	MR
	Standby Pump head.	85m	Provided	MR
	Auto Starting/Manual Stopping.	Required	Provided	MR
	Pump house access.	Required	Provided	MR
	Terrace Level	1	1	
	Discharge of pump.	-NA-	-NA-	-NA-
	Head of pump.	-NA-	-NA-	-NA-
	Power supply.	-NA-	-NA-	-NA-
	Auto starting of pump.	-NA-	-NA-	-NA-
14	Captive water storage for fire fighting	•		
	Underground tank capacity.	2,00,000 Ltrs	Provided	MR
	Draw-off connection.	Required	Provided	MR
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	Required	Provided	MR
	 Overhead tank capacity. 	20,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of lift shaft.	Required	Provided	MR
	 Pressurization of lift lobby. 	Required	Provided	MR
	Communication in lift car.	Required	Provided	MR
	• Fireman's switch.	Required	Provided	MR
	• Lift signage.	Required	Required	MR
		~ 1		

18	Refuge Area				
	Total area	Required	100m ²	MR	
	Location	Required	6 th Floor	MR	
19	Fire Control Room.				
-	Detector system panel.	Required	Provided	MR	
	Flow switch panel.	Required	Provided	MR	
	PA system panel.	Required	Provided	MR	
	Battery backup.	Required	Provided	MR	
	Building floor plan.	Required	Provided	MR	
20	Special Fire Protection System for	LT / HT Panel separation with 2 hrs		MR	
	the Protection of Special Risk, if any.	fire rating wall. Fire extinguishers			
		near LT/HT Panel.			

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection. Keeping in view the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Sunil Chawdhary Name:

Designation: Dy. CFO (SZ)

Signature of the Inspecting Officer

Name:

S.K. Dua

Designation: DO (SD)

CFO (HQ)

F. 1. letter is full in for signature, please