GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/242

Dated: 22.07/2021

FIRE SAFETY CERTIFICATE

Certified that the ALL IZ WELL Guest House located at 4781, Main Bazar Pahar Ganj, New Delhi comprised of Basement (not used), Ground (Reception + Lobby + office + store + 03 guest rooms), 1st to 3rd floor (16 guest rooms at each floor) and terrace floor (Mumty, water tank & open terrace), total 51 guest rooms owned/occupied by ALL IZ WELL Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2018/NDZ/1389 dated 14/06/18. Now, The premises was re-inspected by the officer concerned of this department on 15/07/21 in the presence of Mr. Amardeep and found that the said guest house building having affidavit dated 09.12.2019 not to use any floor above third floor has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class- Residential, Sub Division-A-1 Ground (Reception + Lobby + office + store + 03 guest rooms), 1st to 3rd floor (16 guest rooms at each floor) total - 51 guest rooms only with effect from - 22 10 - for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below. Issued 22 07 2021 at New Delhi by. 0×10mm

(Dr. S.K. Tomar) Dr. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID no. 2021062214099 dated 22.06.21
- 2. The Commissioner, North MCD, Civic Centre, New Delhi
- 3. The Manager,

ALL IZ WELL Guest House 4781, Main Bazar Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

M/18

INSPECTION REPORT

1. Name & address of the building ALL IZ WELL Guest House at 4781, Main

Bazar Pahar Ganj, New Delhi

2. Type of occupancy:- Residential, Sub Division-A-1

Basement (not used), Ground (Reception + Lobby + office + store + 03 guest rooms), 1st to 3rd floor (16 guest rooms at each floor) and terrace floor (Mumty, water tank & open terrace), total 51 guest rooms And an affidavit dated 09.12.2019 not to use any floor

above third floor.

3. Type of case:- Renewal

4. Details of previous FSC:- No. F6/DFS/MS/GH/2018/NDZ/1389 dated

14/06/18

5. Fire safety directives No.- N/A

6. Date of inspection:- 15/07/21

7. Name of the inspecting officer:- Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer From the building side:-

9. Year of construction:-

10. Applicant's letter No:-

Mr. Amardeep

2013

2021062214099 dated 22 06.21 .

		_		Old Case	
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	N/A	09 mtr.	MR	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arr				
	A. Number of staircases				
	1. Upper floors	01 Nos.	01 Nos.	MR	
	2. Basements	02 Nos.	02 Nos.	MR	
	B. Width of staircase		1		
	1. Upper floors	1.50 mtr.	1.50 mtr.	MR	
	2. Basements	1.50 & 0.80	0.80 & 1.40 to	MR	
		mtr.	1.50 mtr.		
	C. Protection of exits				
	1. Fire check door	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance extended vide order dt. 29.06.2021	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	N/A	N/A	N/A	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	01 mtr.	01 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	Required	Provided	MR	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	30 ACPH	Exhaust fan	MR	
	2) Upper floors	12 ACPH	Natural	MR	

4/19

5.	Fire Extinguishers				
	1) Total numbers	20 Nos.	20 Nos.	MR	
	2) Types	ABC & CO2	ABC & CO2	MR	
	3) ISI marking	Required	Provided	MR	
6.	First-Aid Hose Reel	required	Trovided	IVIIC	
	1) Total number of eachfloor	01	01	MR	
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR	
	3) Nozzle diameter	05 mm	05 mm	MR	
7.	Automatic Fire Detection &			IVIIX	
	1) Type of detectors Co type b	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance extended vide order dt. 29.06.2021	
	2) Location of main panel	N/A	N/A	N/A	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	N/A	N/A	N/A	
	5) Hooter's Location	N/A	N/A	N/A	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	Required	Provided	MR	
10.	Automatic Sprinkler System		,		
	1) Basement	Required	Provided	MR	
	2) Upper floors	N/A	Provided	N/A	
	3) Sprinkler above false ceiling	N/A	N/A	N/A	
11.	Internal Hydrants		1		
- Y	1) Size of riser/down-comer	N/A	100 mm	N/A	
	2) Number of hydrants per floor	N/A	01	N/A	
	3) Hose box	N/A	01	N/A	
12.	Yard Hydrants				
	1) Total number of hydrants	N/A	N/A	N/A	
	2) Hose box	N/A	N/A	N/A	
13.	Pumping Arrangement		1 1 1		
	1) Ground level	N/A	N/A	N/A	
	a) Discharge of main pump	N/A	N/A	N/A	
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pump	N/A	N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output	N/A	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual stopping	N/A	N/A	N/A	
	2) Terrace level				
	a) Discharge of pump	900 & 450	900 & 450 LPM	MR	
	a) Discharge of pump	LPM			
			30 mtr.	MR	
	b) Head of pump c) Power supply	LPM 30 mtr. Required	30 mtr. Provided	MR MR	

14.	Captive Water Storage for Fire Fighting				
	Under ground tank capacity	N/A	N/A	N/A	
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	c) Access to tank	N/A	N/A	N/A	
	d) Over head tank capacity	50,000 ltr.	50,000 ltr.	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.				
	a) Pressurization of lift shaft	N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	Required	Provided	MR	
17.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
	Total area location	N/A	N/A	N/A	
19.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
	d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A	
20.	Special Fire Protection Syst Risk, if any:	N/A			

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/NDZ/1389 dated 14/06/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended up to third floor only.

Signature of the Inspecting Officer

Name: - Ravinder Singh

Designation: - ADO (CC)

As appointed par putup for