## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 243

Dated: .2.2 a 7.../2021

## FIRE SAFETY CERTIFICATE

Certified that the **Decent Guest House** located at 4711, **Shora Kothi**, **Pahar Ganj**, **New Delhi** comprised of Ground + 04 Upper floors, Ground floor (Reception + 01 guest room), 1<sup>st</sup> floor (05 guest rooms + 01 store), 2<sup>nd</sup> floor (06 guest rooms), 3<sup>rd</sup> floor (06 guest rooms at each floor) and 4<sup>th</sup> floor (02 guest rooms + hall), total 20 guest rooms owned/occupied by Decent Guest House was earlier granted FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2018/975 dated 09/05/18. Now, The premises was re-inspected by the officers concerned of this department on 15/07/21 in the presence of Mr. Sorabh and found that the said guest house building **having fourth floor not in use as per affidavit dated** 02.12.2019 has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class **Residential**, **Sub Division-A-1 Ground floor** (Reception + 01 guest room), 1<sup>st</sup> floor (05 guest rooms + 01 store), 2<sup>nd</sup> floor (06 guest rooms), 3<sup>rd</sup> floor (06 guest rooms) total 18 guest rooms only with effect from .22.07.221 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 22 07 2021 at New Delhi by.

(**Dr. S.K. Tomar**) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi Id 2021052213506 dated 22.05.21.
- 2. The Commissioner, North MCD, Civic Centre, New Delhi
- 3. The Manager,

Decent Guest House 4711, Sora Kothi, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

H/28

Name & address Cal 1

1. Name & address of the building Decent Guest House at 4711, Sora Kothi, Pahar Ganj, New Delhi

2. Type of occupancy:
Residential, Sub Division-A-1

Ground + 03 Upper floors (total 18 guest rooms)

Ground floor (Reception + 01 guest room), 1<sup>st</sup> floor
(05 guest rooms + 01 store), 2<sup>nd</sup> floor (06 guest rooms), 3<sup>rd</sup> floor (06 guest rooms at each floor) and

rooms), 3<sup>rd</sup> floor (06 guest rooms at each floor) and 4<sup>th</sup> floor (02 guest rooms + hall) not to use as per Affidavit Dated 02.12.2019

3. Type of case:- Renewal

4. Details of previous FSC:- F6/DFS/MS/GH/2018/NDZ/975 dated 09/05/18.

5. Fire safety directives No.6. Date of inspection:15/07/21

Name of the inspecting officers | Ch. P.

7. Name of the inspecting officer:8. Name & designation of officer

8. Name & designation of officer From the building side:-

9. Year of construction:-10. Applicant's letter No:-

Sh. Ravinder Singh (ADO/CC)

Mr. Sorabh 2002

2021052213506 dated 22.05.21.

110			Old Case
Prevention and fire safety U/R 33	Existing fire safety	Provided at site	Remarks MR/NMR
Access to Building	urungements		
1) Road width	N/A	06 mtr.	MR
2) Gate width	N/A	N/A	N/A
	N/A	N/A	N/A
Number, Width Type & Ari			
A. Number of staircases			
1. Upper floors	01 Nos.	01 Nos.	MR
2. Basements	N/A	N/A	N/A
B. Width of staircase			
1. Upper floors	0.80 mtr.	1.03 mtr.	MR
2. Basements	N/A	N/A	N/A
	N/A	N/A	N/A
	N/A	N/A	N/A
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	N/A	N/A	N/A
	N/A	N/A	N/A
	01 mtr.	01 mtr.	MR
Compartmentation			
1) Fire check door	N/A	N/A	N/A
2) Sealing of electrical shafts	N/A	N/A	N/A
	30 ACPH	N/A	N/A
2) Upper floors	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance extended vide order dt. 29.06.2021
	Access to Building  1) Road width 2) Gate width 3) Width of internal road Number, Width Type & Arr A. Number of staircases 1. Upper floors 2. Basements B. Width of staircase 1. Upper floors 2. Basements C. Protection of exits 1. Fire check door 2. Pressurization D. No. of continuous staircase to terrace E. Width of corridor F. Door size Compartmentation 1) Fire check door 2) Sealing of electrical shafts 3) Fire rating of shaft door 4) Water curtain 5) Fire Dampers Smoke Management System 1) Basements	Access to Building  1) Road width 2) Gate width N/A 3) Width of internal road N/A Number, Width Type & Arrangement of Example	Prevention and fire safety U/R 33   Existing fire safety arrangements

				1
5.	Fire Extinguishers			
	1) Total numbers	10 Nos.	10 Nos.	MR
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel	1	Trovided	TVIIX
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &	Alarming Syst	tem	IVIK
	1) Type of detectors CO type	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance extended vide order dt. 29.06.2021
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System		1.0.1404	IVII
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling	S. Sameson Sou		13721
11.	Internal Hydrants		,	
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per floor	N/A	N/A	N/A
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants			
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
3.	Pumping Arrangement		1, ,	11/12
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	N/A	N/A
	pump		- 1/2 2	1771
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			,
	2) Terrace level			
	a) Discharge of pump	180 LPM	180 LPM	MR
	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR

4.	Captive Water Storage for F	ire Fighting	1	DT/A
	Under ground tank     capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
c)		N/A	N/A	N/A
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
17.	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
100	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Sys Risk, if any:	stem for Prote	ction of special	N/A

The fire protection systems provided in the building were randomly tested, checked and

found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/NDZ/975 dated 09/05/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended up to third floor.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

DO (CD)

As ertopourer eri put up fortain and ergoghow Po