GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHTPLACE

NEW DELHI- 110001

No.F6/DFS/MS/Hotel/SZ/2021/ 2 0

Dated: 16/7/21

FIRE SAFETY CERTIFICATE

Certified that the Hotel S.K.Premium Park (A Unit of JMD Abode & Banquets Pvt. Ltd.), 1-B, Sub District Centre, Hari Nagar, New Delhi-110064, comprised of lower basement, upper basement ground plus eight upper floors with service floor having Guest rooms, Restaurant & party halls owned/occupied by A Unit of JMD Abode & Banquets Pvt. Ltd was granted FSC vide letter no. No. F6/DFS/MS/Hotel/2017/SZ/838 dated 09/06/17. The Hotel building was re-inspected by the officer concerned of this department on 05/07/2021 in the presence of Sh. Rohit Kumar and found that the hotel building have deemed complied with the fire prevention and fire safety requirements in accordance with the rule 33 of Delhi Fire Rules 2010 that the building is fit for occupancy Group the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Delhi Fire Service

To.

The Manager, Hotel S.K.Premium, Park, 1-B, Sub District Centre, Hari Nagar, New Delhi-110064. Copy to:-

The Addl. Commissioner of Police, 1st Floor, Licensing Unit, Police Station, Defence Colony, New Delhi. Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry

1. Name & address of the building

2. Building is comprised of

3. Type of Occupancy

4. Type of Case

5. Details of Previous FSC letter

6. Fire Safety direction letter No

7. Date of Inspection8. Name of the Inspecting officers

9. Name and designation of officer from the building side

10. Year of construction

11 Applicant's letter No

: Hotel S.K.Premium Park, 1-B,Sub District Centre, Hari Nagar, New Delhi-110064.

: 2 Basement, Ground+8 upper floors

: Residential (Guest House)

: Renewal

: F6/DFS/MS/Hotel/2017/SZ/838 dated 09/06/17

: F6/DFS/MS/BP/Hotel/2010/461dated 15/02/10

: 05/07/2021

: ADO R.K. Yadav

: Sh. Rohit Kumar

: 2010

: Nil dated-15/06/2021

Sr N	Minimum Standards on Fire Prevention and Fire Safety U/R33	Requirement		marks R/NMR			
0.							
1	Access to Building.	18 m	18 m	MR			
	 Road width 		05 m	MR			
	 Gate width 	05 m	06 M	MR			
	 Width of internal road 	06 M	00 101				
2	Number, Width, Type and Arrangement of Exits.						
	a. Number of Staircases	00 N	02 Nos.	MR			
	Upper floor	02 Nos.	02 Nos	MR			
	Basement	02 Nos	02 1103				
	B. Width of Staircases • Upper floor	Old case	1.25 m & 1.30 m	MR			
	Basement	Old case	1.25 m & .1.30 m	MR			
	c. Protection of Exits		Provided	MR			
	Fire check door	Required		MR			
	Pressurization	Required	Provided	MR			
	d. No. of Continuous Staircases to	01 No.	01 No.	-			
	Terrace	1.5 m	1.5, 2.05 & 2.10 m	MR			
	e. Width of Corridor	1.0 m	.77m	Old			
	f. Door Size	1.0		accepted			
	t taken						
3		Required	Provided	MR			
	 Fire check door Sealing of electrical shafts 	Required	Provided	MR			
	• Sealing of electrical sharts	N/A	N/A	N/A			
	Fire rating of shaft doorWater curtain	N/A	N/A	N/A			
	Vyater curtain Fire dampers	N/A	N/A	N/A			
1	Smoke Management System.						
4	_	Required	Exhaust ducts provided	d MR			
	BasementUpper floor	Required	Provided	MR			
5.				N .			
5.	Total numbers at each floor	10 nos.	Provided	MR			
		ABC /CO ₂	Provided	MR			
	 Types 	ISI marked	Provided	MR			

06	First-Aid-Hose Reels.	* ************************************				
	Total numbers on each floor	2 No	D- 11			
	Length of hose reel hose	30 m	Provided	MR		
	Nozzle diameter	05 mm	Provided	MR		
07						
	 Type of detectors 	Required	Provided	MR		
	 Location of main panel 	N/A	N/A	N/A		
	 Location of repeater panel 	N/A	N/A	N/A		
	 Alternate source of power 	N/A	N/A	N/A		
-	Hooter's location	N/A	N/A	N/A		
80	MOEFA	Required	Provided	MR		
09	Public Address System.	Required	Provided			
10	Automatic Sprinkler System.	. toquilou	Trovided	MR		
	Basement	Required	Provided	MD		
	 upper floor 	Required	Provided	MR		
	sprinkler above false ceiling	Required	Provided	MR		
11	Internal Hydrants	roquileu	riovided	MR		
	size of riser/down-comer	150 mm	150 mm	MR		
	 Number of hydrants per floor 	02 No.	02 No.	MR		
10	Hose box	02 No.	02 No.	MR		
2	Yard Hydrants.			IVIIX		
	Total number of hydrants	04 No.	. 04 No.	MR		
10	Hose box	04 No.	04 No.	MR		
13	Pumping Arrangements.	,				
	Ground Level					
	 Discharge of main pump 					
	 Head of main pump 	2850 LPM	2850 LPM	MR		
	 Number of main pumps 	108 M	108 M	MR		
1	 Jockey pump out put 	180 LPM	180 LPM	MR		
	 Jockey pump head 	70 M	70 M	MR		
	 Standby pump out put 	2850 LPM	2850 LPM	MR		
	 Standby pump head 	108 M	108 M	MR		
	 Auto starting /manual stopping 	Required	Provided	MR		
	Pump house accessTerrace Level	Required	Provided	MR		
1	Discharge of pump	NI/A	N 1/A	1 11/0		
	Head of the pump	N/A N/A	N/A	N/A		
	Power supply	N/A N/A	N/A	N/A		
	Auto Starting of pump	N/A N/A	N/A N/A	N/A N/A		
1	Captive Water Storage for Fire Fighting.	11//	INA	IN/A		
-	Underground tank capacity	2 00 000 14	Drovida	N. A.D.		
	 Draw-off connection 	2,00,000 ltrs	Provided	MR		
	Fire service inlet	Required	Provided	MR		
	Access to tank	Required	Provided	MR		
	The same state of the same sta	Required	Provided	MR		
5	Overhead Tank capacity Exit Signage.	20,000 Ltrs	Provided	MR		
	Exit Olyllage.	Required	Provided	MR		

6	Provision of Lifts.						
	Pressurization of Lift Shaft inting of Lift lobby	Required Required	Provided Provided	MR MR			
	 Pressurization of Lift lobby Communication in lift car Firemen's grounding switch 	Required Provided Required Provided Required Provided		MR MR			
				MR			
	Lift Signage Standby power supply	Required	Provided	MR			
17 18	Refuge Area.						
	Total area Location	Required N/A	Provided N/A	MR N/A			
19	Fire Control Room						
	 Detector system panel Flow switch panel PA system panel 	Required	Provided Provided	MR MR			
		Required Required	Provided	MR			
	Battery backupBuilding Floor Plans	Required	Provided HT & LT Panel are	MR MR			
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	protected by DCP fire extinguisher				

The building was issued shortcomings vide letter no. F6/DFS/MS/2021/01 dated 04/01/2021. The same were checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire required under the rules the FSC was issued vide letter no. F6/DFS/MS/Hotel/2017/SZ/838 dated 09/06/17 renewal under the Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010 is recommended.

Signature of the Inspecting Officer

Name

:- R.K.Yadav

Designation: ADO(Janakpuri)

DO(South West)

108/07/2021

Dy cho (\$2)

PD. spant

ADO OFF.

Spaken

A12)5

Kapp

