GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

Dated: / 9 / 7 /2021

FIRE SAFETY CERTIFICATE

Issued on ./....... at New Delhi by.

(Dharampal Bhardwaj) Dy.Chief Fire Officer Ph:-011-25156707

11-2515670 b/ c W

Copy to:-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 54.

2. The Principal, Mata Ram Rakhi Sanatam Dharam Saraswati Shishu Mandir located at C-105, Mahendru Enclave, Delhi-110033

Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3 All the staff members must know the correct method of operation of firefighting system.

4 The owner / occupier shall submit a declaration **every year** in **Form "K"** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

DCTION REPORT 1. Name & address of the building : Mata Ram Rakhi Sanatam Dharam Saraswati Shishu Mandir, C-105, Mahendru Enclave, Delhi-110033. Type of Occupancy : Educational (Ground floor only) 3. Type of Case : Renewal 4. Details of previous NOC : F6/DFS/MS/School/2018/WZ/1254 Dated: 29.05.2018 Fire Safety directives letter No : Director of Education Circular dated 01.03.2011 Date of inspection : 08.07.2021 Name of the Inspecting Officers : ADO (RN) 8. Name and designation of officers from the building side : Smt. Harshi Dua (Incharge) 9. Year of Construction : 1989 10. Applicant's letter No. : Online E-mail I.D Dated- 01.07.2021 Plot Area- 810 sq.y Covered Area: 477 sq.y Minimum Standards on fire prevention and class rooms -08nos students – 223nos Circular of Provided at site fire safety U/R 33 Remarks Director of MR/NMR Education 1 Access to building Road width 06m 06m MR Gate width 4.5m 2.85m Width of internal road MR(old case) NA 2 Number, Width, Type & Arrangement of Exits NA NA a. Number of staircases Upper Floors NA NA Basements NA b. Width of staircases NA NA NA Upper Floors NA NA Basements NA NA NA c. Protection of exits NA Fire check door NA NA NA NA Pressurization NA NA d. No. of continuous staircases to terrace NA NA NA e. Width of Corridor NA NA NA f. Door Size 1 m 1 m MR 3 Compartmentation. Fire check door NA NA Sealing of electrical shafts NA NA NA NA Fire Rating of shaft door NA NA Water Curtain NA NA Fire Dampers NA NA NA NA NA 4 Smoke Management System. Basements 12 a/c per hour NA NA Upper floors 12 a/c per hour Natural Ventilated MR 5 Fire Extinguishers Total numbers

मा (इाड्या)

14	Captive Water Storage for fire fighting.			
	Underground tank capacity	NA	NA	NA
	> Draw-off connection	NA	NA	NA
	➢ Fire service inlet	NA	NA .	NA
	> Access to tank	NA	NA	NA
	Overhead Tank capacity	NA	NA	NA
15	Exit Signage.	N/A	N/A	N/A
16	Provision of Lifts.			
	Pressurization of Lift Shaft	N/A	N/A	N/A
	 Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup Byilding Floor Plans	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. 1254 dated 29.05.2018.

09/07/202

Signature of the Inspecting Officer

Name:-C.L. Meena Designation:- ADO/RN

As approved, F.T. letter is but up for your conquater