(-52

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2021/SZ/ / 1/2

Dated: 19/7/2021

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s Nukkad Café and Bar (A Unit of flying sparrow hospitality Pvt Ltd). Shop no C-23-24 SDA Market, Safdarjung Development Area, New Delhi-110016 comprised of ground floor only have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 08/07/2021 in the presence of Mr. Sandeep Yadav (Manager) and that the premises is fit for occupancy class "Group—D Assembly" with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 19/1/2021 at New Delhi by

(ATUL GARG)
DIRECTOR

Copy to: -

-

- 1. The Dy. Health Officer, SDMC, Public Health Department, Green Park, Aurobindo Marg, New Delhi 110016.
- 2. The Joint Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049
- 3. M/s Nukkad Café and Bar (A Unit of flying sparrow hospitality Pvt Ltd). Shop no C-23-24 SDA Market, Safdarjung Development Area, New Delhi-110016

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	Name & Address of the Building	M/s Nukkad Café and Bar (A Unit of flying sparrow hospitality Pvt Ltd). Shop No C-23&24 SDA Market, Safdarjung Development Area, New Delhi			
2	Type of Occupancy	Group-D Assembly Building.			
3	Building Comprised of	Ground floor only			
4	Type of Case	New			
5	Details of Previous NOC	Nil			
6	Fire Safety Directives Letter No	Nil ·			
7	Date of Inspection	08/07/2021			
8	Name of the Inspecting Officers	Dy. CFO (SZ) & ADO (BCP)			
9	Name & Designation of Officers	Sh. Sandeep Yac	dav (Manager)		
	from the building side				
10	Year of construction	and the size and			
11	Applicant letter No.	Gmail dated 01/07	7/2021		
S. No.	Minimum standards on Fire Prevention	UBBL/NBC	Provided at Site	Remarks	
	and Fire Safety U/R 33	Requirement		MR/NMR	
1	Access to Building.		1		
	Road width	Required	9m	MR	
	Gate width	N/A	N/A	N/A	
	Width of internal road	N/A	N/A	N/A	
2	Number, width, type & arrangement of ex	its.			
	a) Number of Staircase				
15	Upper floors.	N/A	N/A	N/A	
	Basement floor.	N/A	N/A	N/A	
	b) Width of Staircase				
	> Upper floors	N/A	N/A	N/A	
	Basement floor	N/A	N/A	N/A	
	c) Protection of exits				
	Fire check door	N/A	N/A	N/A	
	Pressurization	- N/A	N/A	N/A	
	d) No. of continuous staircase to terrace	Required	One	MR	
	e) Width of corridor	N/A	N/A	N/A	
	f) Door size	2 exits	1.50 mtr each	MR	
3	Compartmentation.				
	Fire check door.	N/A	N/A	N/A	
	 Sealing of electrical shafts. 	N/A	N/A	N/A	
	 Fire rating of shaft door. 	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	Fire dampers.	N/A	N/A	N/A	
4	Smoke Management system.				
	Basement	30 ACPH	N/A	N/A	
	Upper floors	12 ACPH	N/A	N/A	
5	Fire Extinguishers.				
	Total numbers	06 Nos	06 Nos	MR	
	• Types	ABC/CO ₂	ABC & CO ₂	MR	
	ISI Marking	ISI marked	Provided Provided	MR	
6	First Aid Hose Reels.			A 1.4.4. %	
	Total numbers on each floor.	One	Provided	MR	
	 Length of hose-reel hose. 	30m	Provided	MR	
	Nozzle Diameter	5mm	Provided	MR	
7	Automatic fire detection & alarming system	m.	rever subjoint) •		

ALLS

Man 1

		•		
	Location of Main Panel	N/A	N/A	N/A
3	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System	N/A	NA	N/A
10	Automatic Sprinkler System		<u> </u>	
	Basement	N/A	N/A	N/A
	 Ground floor. 	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.			
	Size of Riser/Down-comer	100 mm	Provided	MR
	 Number of Hydrant per floor 	One	Provided	MR
	Hose box.	One	Provided	MR
12	Yard Hydrants.			10
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.			
-	Ground Level			4.7
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
	Terrace Level	1471	IVA	IV/A
	Discharge of pump.	450 LPM	Provided	
	Head of pump.	40 m	Provided	MR
	Power supply.			MR
	Auto starting of pump.	Required	Provided	MR
14		Required	Provided	MR
. 7	Captive water storage for fire fighting.	27/4	27/4	
	 Underground tank capacity. Draw-off connection. 	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	N/A	N/A	N/A
1 <i>E</i>		20,000 Ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	,		
	Pressurization of lift shaft.	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
17	Lift signage. Standby Power Species.	N/A	N/A	N/A
	Standby Power Supply	N/A	N/A	N/A
18	Refuge Area			
MR	Total area	N/A	N/A	N/A
Ata.	• Location	N/A	N/A	N/A
19	Fire Control Room.		anuit I et	
1	Detector system nanel	NI/A	NI/A	DT/A

明中中国

	A CONTRACTOR OF THE CONTRACTOR			
	Flow switch panel.	N/A	DT/A	27/4
	PA system panel.		N/A	N/A
	Battery backup.	N/A	N/A	N/A
	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the	27/4		
	Protection of special Risk, if any.	N/A	N/A	N/A

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 214 dated 13/05/2021

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

Signature of the inspection Officer

Name: Sh. Sunil Chawdhary Designation: - Dy. CFO (SZ) Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Designation: ADO (BCP)

Dolso-on beave

CFO (HQ)

As oppored, F.T. lettel er pump Jone synahise Pl.