© GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/NDZ/2021/) 3 6

FIRE SAFETY CERTIFICATE

Certified that the Open House Bar + Kitchen (A Unit of JV Café Pvt. Ltd.) located at 1st floor, Atma Ram House, C-37, Connaught Place, New Delhi comprises of Ground + 02 Upper floor, Restaurant is running at 1st floor owned/occupied by Open House Bar + Kitchen was granted FSC by this department vide letter No.F6/DFS/MS/EH/2018/NDZ/932 dated 07/05/18. The premises was re-inspected by the officer concerned of this department on 23/01/18 in the presence of Mr. Surender and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Assembly Building Group D restaurant at first floor only with effect from [-37,1,2,1].-for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued $-\frac{1}{27}\frac{7}{2}$ at New Delhi by.

(Dr. S.K. Tomar) Dy. Chief Fire officer Delhi Fire Service

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online Id no. 2021062414191 dated 24/06/2021
- 2. The Executive Engineer, NDMC, Palika Kendra, New Delhi.

3. The Manager,

Open House Bar + Kitchen (A Unit of JV Café Pvt. Ltd.) at 1st floor, Atma Ram House, C-37, Connaught Place, New Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. Any flammable material for interior decoration shall strictly prohibited.

NSPECTION REPORT

Open House Bar + Kitchen (A Unit of JV Café Pvt. 1. Name & address of the building

Ltd.) at 1st floor, Atma Ram House, C-37,

Connaught Place, New Delhi

Assembly Building Group-D 2. Type of occupancy:-

Gr. + 02 upper floors, Restaurant is running at

1st floor only

3. Type of case:-

Renewal

4. Details of previous FSC:-

F6/DFS/MS/EH/2018/NDZ/932 dated 07/05/18

5. Fire safety directives No.-

N/A

6. Date of inspection:-

09/07/21

7. Name of the inspecting officer:-

Sh. Ravinder Singh (ADO/CC)

Sh. Rajinder Atwal, DO (CD)

8. Name & designation of officer from the building side:-

Mr. Surender (Manager)

9. Year of construction:-

Old Heritage Bldg. 1927

10. Applicant's letter No:-

2021062414191 dated 24/06/2021

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR		
1.	Access to Building					
	1) Road width	09 mtr	18 mtr.	MR		
	2) Gate width	N/A	N/A	N/A		
	3)Width of internal road	N/A	N/A	N/A		
2.	Number, Width Type & Arrangement of Exits					
	A. Number of staircases					
	1. Upper floors	02 No.	02 No.	MR		
	2. Basements	N/A	N/A	N/A		
	B. Width of staircase					
	1. Upper floors	1.25 mtr. & 1 mtr.	1.25 mtr. & 1.04 mtr.	MR		
	2. Basements	N/A	N/A	N/A		
	C. Protection of exits	N/A	N/A	N/A		
	1. Fire check door	N/A	N/A	N/A		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous staircase to terrace	01	01	MR		
	E. Width of corridor	N/A	N/A	N/A		
	F. Door size	2 mtr.	2 mtr.	MR		
3.	Compartmentation					
	1) Fire check door	N/A	N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System					
	1) Basements	30 ACPH	N/A	N/A		
	2) Upper floors	12 ACPH	Exhaust fan	MR		
5.	Fire Extinguishers					
	1) Total numbers	07 Nos.	07 Nos.	MR		

	2) Types	AB	3C & CO2	AI	BC & CO2	M	R	
	3) ISI marking	Re	quired	Pr	ovided	M	R	
6.	First-Aid Hose Reel							
	1) Total number of each	01		01		M	R	
	floor	• •		0.0		3.4	D	
	2) Length of hose reel hose		mtr.	30 mtr.		MR		
	3) Nozzle diameter)5 mm		MR	
7.	Automatic Fire Detection & Alarming System 1) Type of detectors N/A N/A N/A							
	1) Type of detectors	N/		-			N/A	
	2) Location of main panel				N/A		N/A	
	3) Location of repeater panel			N/A		N/A		
	4) Alternate source of power		N/A		N/A		N/A	
	5) Hooter's Location	N/A			N/A		N/A	
8.	MOEFA	Required		-	Provided		IR .	
9.	Public Address System		N/A		N/A		N/A	
10.	Automatic Sprinkler System			1		2.7		
	1) Basement	N/			/A		/A	
	2) Upper floors	Required			Provided		MR	
	3) Sprinkler above false	N/A		N	N/A		7/A	
	ceiling			+		-		
11.	Internal Hydrants	10	0	1.	20	1	m .	
	1) Size of riser/down-comer	100 mm		100 mm		MR MR		
	2) Number of hydrants per	01		01		IVIK		
	floor	01		01		MR		
10	3) Hose box	The state of the s		01				
12.	Yard Hydrants	NI	/ ^	IN	[/^	N	Ī/A	
	1) Total number of hydrants 2) Hose box	N/A N/A			N/A N/A		I/A	
12		IN/	A	11	/A	11	//A	
13.	Pumping Arrangement 1) Ground level				1.7.1	-		
			N/A		N/A	+	N/A	
	a) Discharge of main pump							
	b) Head of main pump		N/A		N/A		N/A	
	c) Number of main pu		N/A		N/A	1	N/A	
	d) Jockey pump out pu	ıt	N/A		N/A	1	N/A	
	e) Jockey pump head		N/A		N/A		N/A	
	f) Stand by pump outp		N/A		N/A		N/A	
	g) Stand by pump head		N/A		N/A		N/A	
	h) Auto starting/Manu stopping	al	N/A		N/A		N/A	
	2) Terrace level							
	a) Discharge of pump	. 3	450 LPM		450 LPM		MR	
9	b) Head of pump		40 mtr.		40 mtr.		MR	
	c) Power supply		Required		Provided		MR	
	d) Auto starting of pur	mp	Required		Provided		MR	
14.	a) 11000 5000 500 For F							
	1) Under ground tank		N/A		N/A		N/A	
	capacity	4						



	a) Draw-off connection			
	b) Fire service inlet		N/A	N/A
	Jero por vice milet	Required	Provided	MR
	c) Access to tank d) Over head tank capacity	N/A	N/A	N/A
	- Over mead tank capacity	15,000 ltr.	15,000 ltr.	MR
15.	Exit Signage.	D		
16.	Provision of Lifts.	Required	Provided	MR
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	77/
17.	e) Lift signage	N/A	N/A	N/A
107. (1.05)	Stand by Power Supply	Required	Provided	N/A
18.	Refuge Area	N/A		MR
	Total area location		N/A	N/A
		N/A	N/A	N/A
19.	Fire Control Room	N/A		
			N/A	N/A
	panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	27/1
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A		N/A
		14/11	N/A	N/A
	e) Building floor plan	N/A	N/A	NT/A
20.	Special Fire Protection System Risk, if any:	N/A		
	Risk, if any:	N/A		
			n – 11	

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/EH/2018/NDZ/932 dated 07/05/18 renewal under rule 35 of the Delhi Fire Service

Signature of the inspecting officer

Signature of the Inspecting Officer

Name: - Rajinder Atwal Designation: - DO (CD)

Name: Ravinder Singh

Designation: ADO (CC)

As approved Pari put a