GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/GH/SZ/2021/ 2 2

Dated: 19/7/21

FIRE SAFETY CERTIFICATE

Certified that Guest House Paradise Inn located at 15A/49, WEA, Karol Bagh, New Delhi- 110005 comprised of basement (Storage), stilt floor (parking & reception), ground floor (06 guest rooms), first floor (06 guest rooms), second floor (06 guest rooms) and third floor (06 guest rooms) (total 24 guest rooms) was granted FSC by this department vide letter No. F.6/DFS/MS/GH/SZ/2017/1253 dated 22.08.2017. The premise was re-inspected by the officer concerned of this department on 07.07.2021 in presence of Sh. Bhupinder Singh, owner of the guest house. The said guest house deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class group-A, residential (guest house) for basement (storage), stilt floor (parking & front desk), ground, first, second and third floor each having 06 guest rooms (total 24 guest rooms only) with effect from 13/7/2/ for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed backside.

Issued $\frac{\sqrt{9}}{7}$ at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)

Delhi Fire Service

Copy to:-

- 1. The Owner/Occupier, Guest House Paradise Inn, 15A/49, WEA, Karol Bagh, New Delhi-
- 2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi

Following Fire Safety Directives must be adhered to: -

- 1. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 10. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.

INSPECTION REPORT 1. Name & address of the building: Guest House Paradise Inn, 15A/49, WEA, Karol Bagh, New Delhi- 110005 2. Type of Occupancy : Lodging House 3. Type of Case : Renewal 4. Details of previous NOC : F.6/DFS/MS/GH/SZ/2017/1253 dated 22.08.2017 5. Fire Safety directives letter No : N/A. 6. Date of inspection : 07.07.2021 7. Name of the Inspecting Officers: P.V. Rathee, Asstt. Div. Officer (SRD) 8. Name and designation of officers from the building side : Sh. Bhupinder Singh, owner 9. Year of Construction : 2010 10. Applicant's letter No. : Online application ID No. 2021061313808 dated 15.06.2021 The said guest house is comprised of basement, stilt, ground plus three upper floors. S. Minimum Standards on fire Requirement as Remarks Provided at site per FSC dated No. prevention and fire safety U/R 33 MR/NMR 22.08.2017 1 Access to building Road width 06 mts Provided MR Gate width 05 mts Directly accessible MR N/A N/A Width of internal road N/A 2 Number, Width, Type & Arrangement of Exits a. Number of staircases 01 Provided Upper Floors MR being old case 01 Provided Basements MR being old case b. Width of staircases Old case 1.25 mts Upper Floors MR being old case 1.27 mts, 01 emergency Old case MR being old case Basements exit c. Protection of exits date of compliance has been Fire check door Required Not Provided extended up to 30.09.2021 Pressurization N/A N/A N/A 01 01 MR e. No. of continuous staircases to terrace 1.25 mts 1.65 mts MR g. Width of Corridor Old case Provided (0.85 mt.) MR being old case h. Door Size 3 Compartmentation. Fire check door date of compliance has been Required Not Provided extended up to 30.09.2021 Sealing of electrical shafts Sealed Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4 Smoke Management System. Basements 30 a/c per hour Exhaust fan provided MR Upper floors 12 a/c per hour Natural ventilation MR Fire Extinguishers 5 Total numbers 17 Provided MR CO₂, ABC type Types Provided MR

36, 37, 38, 39,

सैक्टर-1, नीएडा 101 3

6	First-Aid Hose Reels.							
	Total numbers on each floor	01	Provided		MR			
	 Length of hose reel hose 	30 m	Provided		MR			
	Nozzle diameter	5 mm	Provided		MR			
7	Automatic fire detection and alarming system.							
	Type of detectors	Carbon Monoxide	Not Provided	exten	f compliance has been ided up to 30.09.2021			
	Location of Main Panel Location of Panel Location of Panel Location of Main Panel	Required	Not Provided '		f compliance has been ded up to 30.09.2021			
	Location of Repeater Panel	N/A	N/A		N/A			
	Alternate source of power	N/A	N/A		N/A			
	Hooters' Location	N/A	N/A		N/A			
8	MOEFA	Required	Provided		MR			
9	Public Address System.	Required	Provided		MR			
10	Automatic Sprinkler System.							
:\	Basement	N/A	Provided	Area of basement is less				
	Upper Floor	N/A	N/A		than 200 m ²			
		N/A N/A	N/A N/A		N/A			
	Sprinkler above false ceiling	IN/A	IN/A	Part of the last o	N/A			
11	Internal Hydrants							
	Size of riser/down-comer	N/A	N/A		N/A			
	Number of hydrants per floor	N/A	N/A		N/A			
	Hose Box	N/A	N/A		N/A			
12	Yard Hydrants.							
	Total number of hydrants	N/A	N/A		N/A			
	Hose Box	N/A	N/A		N/A			
13	Pumping Arrangements.							
	Ground Level			100				
	Discharge of main Pump	N/A	N/A		N/A			
	Head of Main pump	N/A	N/A	1. 1.	N/A			
	Number of main pumps	N/A	N/A		N/A			
	Jockey Pump out put	N/A	N/A		N/A			
	Jockey pump head	N/A	N/A		N/A			
5	Standby Pump out put	N/A	N/A		N/A			
	Standby Pump HeadAuto Starting/ Manual stopping	N/A	N/A		N/A			
	> Pump House Access	N/A	N/A		N/A			
	Terrace level	N/A	N/A		N/A			
	Discharge of pump	Discharge of numn		DI O				
	Head of the pump	02 x 450 LPM	Provided (02 x 450 L)	PM)	MR			
	Power Supply	30 mts each	Provided		MR			
	> Auto Starting of pump	Required Required	Provided Provided		MR			
14	Captive Water Storage for fire fightin		Flovided		MR			
	Underground tank capacity	N/A	N/A		N/A			
	> Draw-off connection	N/A N/A	N/A N/A		N/A N/A			
	Fire service inlet	N/A	N/A		N/A N/A			
	Access to tank	N/A	N/A		N/A			
	Overhead Tank capacity	5,000 lts	Provided (6000 lts)		MR being old case			
	1							

तिरित हो तो कृपया लौटाएँ :

15	Exit Si	gnage.	Required	Provided	MR				
16	Provis	ision of Lifts.							
	•	Pressurization of Lift Shaft	N/A	N/A	N/A				
	•	Pressurization of Lift lobby	N/A	N/A	N/A				
	•	Communication In lift Car	N/A	N/A	N/A				
7	•	Fireman's Grounding Switch	N/A	N/A	N/A				
	•	Lift Signage	N/A	N/A	N/A				
17	Standl	y power supply	Required	Provided (D.G. set 125 KVA)	MR				
18	Refuge	e Area.							
	>	Total Area	N/A	N/A	N/A				
	>	Location	N/A	N/A	N/A				
19	Fire C	ontrol Room							
		Detector System Panel	N/A	N/A	N/A				
		Flow Switch Panel	N/A	N/A	N/A				
	•	PA System Panel	N/A	N/A	N/A				
	•	Batter backup	N/A	N/A	N/A				
	•	Building Floor Plans	N/A	N/A	N/A				
20		Fire Protection Systems for ion of special Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect. pan	MR el				

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/GH/SZ/2017/1253 dated 22.08.2017, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

P.V. Rathee

Asstt. Div. Officer (SRD)

VAIN 917/21

D. O. (54)

tulothor

Dy coo 152)