L-103

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 2 3 4

Dated: | \?/ 7/2021

FIRE SAFETY CERTIFICATE

Certified that the Ratan Deep Guest House located at 7864/3A, J-7879, Arakashan Road, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (01 guest rooms + 01 office), 1st floor (08 guest rooms), 2nd floor (07 guest rooms), 3rd floor (07 guest rooms) and 4th floor (01 store room + open staff kitchen), total 23 guest rooms was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2018/841 dated 07/08/18. Now, The premises was re-inspected by the officers concerned of this department on 07/07/21 in the presence of Mr. Irfan and found that the said guest house building having 4th floor not in use as per affidavit dated 28.09.2019, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1, Ground floor + 1st to 3rd floor (total -01+08+07+07= 23 guest rooms) only with effect from -49-47-42-4---for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 1-9/-7/2-1---at New Delhi by.

(Dr. S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North Delhi Municipal Corporation, Civic Center, New Delhi.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no.2021062514209 dated 25.06.21
- 3. The Manager, Ratan Deep Guest House 7864/3A, J-7879, Arakashan Road, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

1124

INSPECTION REPORT

1. Name & address of the building Ratan Deep Guest House at 7864/3A, J-7879,

Arakashan Road, Pahar Ganj, New Delhi

2. Type of occupancy:- Residential, Sub Division-A-1

Gr. + 04 Upper floors (total 23 Guest rooms) Ground floor (01 guest rooms + 01 office), 1st floor (08 guest rooms), 2nd floor (07 guest rooms), 3rd floor (07 guest rooms) and 4th floor (01 store room + open staff kitchen) **having 4th floor not in use as per**

affidavit dated 28.09.2019,

3. Type of case:- Renewal

4. Details of previous FSC:- No. F6/DFS/MS/GH/NDZ/2018/841 dated

07/08/18

5. Fire safety directives No.- N/A

6. Date of inspection: 07/07/21

7. Name of the inspecting officer:- Sh. Rajinder Atwal (DO/CC) Sh. Ravinder Singh (ADO CC

8. Name & designation of officer From the building side:-

Mr. Irfan

9. Year of construction:10. Applicant's letter No:-

Online id no.2021062514209 dated 25.06.21

101	apparent b letter 110.		.2021002314207	Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	N/A	04 mtr.	N/A
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arr			
	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	0.80 mtr.	1.23 mtr. & 1.30 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits		n Tyn Ne.	
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	01	01	MR
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	01 mtr.	01 mtr.	MR
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	1) Basements	30 ACPH	N/A	N/A
	2) Upper floors	Required as	Not provided	Last dt.
		per G.N	*	30.09.21 of
		dated		compliance
		27.05.19		extended
				vide order dt.
=	Et - E - 4° 1 - 1			29.06.2021
5.	Fire Extinguishers			

4/25

	1) Total numbers	10 Nos.	10 Nos.	MR MR			
	2) 1) 500	ABC & CO2	ABC & CO2	MR			
		Required	Provided	MK			
5.	First-Aid Hose Reel	0.1	01	MR			
	1) 100011101110	01	01	MR			
	2) Bengan et meet	30 mtr.	30 mtr.	MR			
	S) I (OLLIE WINNIED OF	05 mm	05 mm	IVIK			
7.	Automatic Fire Detection & Alarming System 1) Type of detectors CO type Required as Not provided Last dt.						
		Required as per G.N dated 27.05.19		30.09.21 of compliance extended vide order dt 29.06.2021			
	2) Booteron of many	N/A	N/A	N/A			
	5) 20000000	N/A	N/A	N/A			
	1) 111001111100 00 111 1	N/A	N/A	N/A			
	5) Hooter's Location	N/A	N/A	N/A			
8.	MOEFA	N/A	N/A	N/A			
9.	Public Address System	Required	Provided	MR			
10.	Automatic Sprinkler System						
	1) Basement	N/A	N/A	N/A			
	2) Upper floors	N/A	N/A	N/A			
	3) Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
	1) Size of riser/down-comer	N/A	N/A	N/A			
	2) Number of hydrants per floor	N/A	N/A	N/A			
	3) Hose box	N/A	N/A	N/A			
12.	Yard Hydrants						
12.	1) Total number of hydrants	N/A	N/A	N/A			
	2) Hose box	N/A	N/A	N/A			
13.	Pumping Arrangement						
10.	1) Ground level	N/A	N/A	N/A			
	a) Discharge of main pump	N/A	N/A	N/A			
	b) Head of main pump	N/A	N/A	N/A			
	c) Number of main pump		N/A	N/A			
	d) Jockey pump out put	N/A	N/A	N/A			
	e) Jockey pump head	N/A	N/A	N/A			
	f) Stand by pump output	N/A	N/A	N/A			
	g) Stand by pump head	N/A	N/A	N/A			
	h) Auto starting/Manual stopping	N/A	N/A	N/A			
	2) Terrace level		AFO T DE F	MD			
	a) Discharge of pump	450 LPM	450 LPM	MR			
	b) Head of pump	30 mtr.	30 mtr.	MR			
	c) Power supply	Required	Provided	MR			
	d) Auto starting of pump Required		Provided	MR			
14.	Captive Water Storage for I	Fire Fighting		l ST/			
	Under ground tank capacity	N/A	N/A	N/A			
	a) Draw-off connection	N/A	N/A	N/A			
	b) Fire service inlet	N/A	N/A	N/A			
	The second secon	N/A	N/A	N/A			

	M)	25,00 ltr.	25,00 ltr.	MR
	d) Over head tank	25,00 III.	23,00 161.	
	capacity	Required	Provided	MR
15.	Exit Signage.	Required	TTOVICE	
16.	Provision of Lifts.		27/4	N/A
	a) Pressurization of lift shaft	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Sys	stem for Prote	ction of special	N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection:

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F6/DFS/MS/GH/NDZ/2018/841 dated 07/08/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval upto third floor.

Signature of the inspecting officer

Risk, if any:

Name: - Rajinder Atwal Designation: - DO (CD) Signature of the Inspecting Officer

Name: Ravinder Singh Designation: ADO (CC)

Appled As explorined Agri pertup for Ican Penners

And Stonglin Please.

Bis