GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6 DFS/MS/Instt./2021/SZ/ 3 1 2

Dated: 27/07/2021

FIRE SAFETY CERTIFICATE

Certified that M/s Fortune Institute of International Business located at Plot No 5, Rao Tula Rao Marg, Vasant Vihar, New Delhi 110057 comprised of Basement, Ground plus Four Upper Floors was granted Fire Safety Certificate by this department vide letter No. F6/DFS/MS/Instt./2018/719 Dated 24/07/2018. The said premises was re-inspected by officer concerned of this department on 08/07/2021 in presence of Dr. Manish Kamdar and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class "Educational Building Group – B" with effect from 29/07/2021 for a period of Three years in accordance with rule 36 unless renewed under rule37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules 2010.

Issued on 23 / 67 2021 at New Delhi by

Copy to: -

- 1. M/s Fortune Institute of International Business located at Plot No 5, Rao Tula Rao Marg, Vasant Vihar, New Delhi 110057
- 2. The Director (L&I), DDA, Building Section, Vikas Sadan, INA, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	INCDECT	ION DEPODT				
1	INSPECTION REPORT Name & Address of the Building M/s Fortune Institute of International Busin					
	Traine of Fiduress of the Dunding	The state of the s				
2	Type of Occupancy	-5, Rao Tula Ram Marg, Vasant Vihar, New Delhi -57 Educational, Group–B (School)				
3	Building Comprised of	Basement, Ground plus 04 Upper Floors.				
4	Type of Case	Renewal				
5	Details of Previous NOC	F6/DFS/MS/Instt./2018/719 Dated 24/07/2018				
6	Fire Safety Directives Letter No		2003/255 Dated 31/01/20			
7	Date of Inspection	08-07-2021	2003/233 Dated 31/01/200	0.5		
8	Name of the Inspecting Officers	Dy. CFO (SZ) & ADO (BCP) Dr. Manish Kamdar				
9	Name & Designation of Officers					
	from the building side					
10	Year of construction	2014				
11	Applicant letter No	Gmail Dated 02/07/2021				
S. No	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks		
	and Fire Safety U/R 33	requirements		MR/NMR		
1	Access to Building.					
	Road width	Required	9 mtr	MR		
	Gate width	Required	8 mtr	MR		
	 Width of internal road 	-NA-	-NA-	-NA-		
2	Number, width, type & arrangement of exits.					
	a) Number of Staircase					
	Upper floors.	02 No's	Provided	MR		
	Basement floor.	02 No's	Provided	MR		
	b) Width of Staircase			1		
	Upper floors	1.50 mtr each	1.50 mtr each	MR		
	Basement floor	1.50 mtr each	1.50 mtr each	MR		
	c) Protection of exits	1.30 IIII Cacii	1.50 mili cacii	IVIK		
	Fire check door	Required	Provided in basement	MR		
	> Pressurization	-NA-	-NA-	-NA-		
	d) No. of continuous staircase to terrace		1			
	e) Width of corridor	Required -NA-	Provided	MR		
			-NA-	-NA-		
3		1 mtr	1 mtr	MR		
3	Compartmentation. • Fire check door	D1	D 11 11 1	1.60		
	Fire check door.Sealing of electrical shafts.	Required Required	Provided in basement Provided	MR		
	Fire rating of shaft door.	-NA-	-NA-	MR		
	Water curtain	-NA-	-NA-	-NA-		
	Fire dampers.	-NA-	-NA-			
4.	Smoke Management system.	-11/7-	-INA-	-NA-		
T o	Basement	30 ACPH	Exhaust fan Provided	MD		
	Upper floors	12 ACPH	Natural ventilation	MR		
5.	Fire Extinguishers.	12 ACFI	Natural ventilation	MR		
	Total numbers	Required	24 Nos	MR		
	• Types	ABC	ABC Type			
	ISI Marking		ADC Type	MR		
	• 151 Marking	ISI mark	Provided	MR		
6.	First Aid Hose Reels.					
	Total numbers on each floor.	Two	Provided	MR		
	0 00 00 00 Mod	30 m	Provided	MR		
	• Length of hose-reel hose.					
	Nozzle Diameter	5 mm	Provided	MR		
7	Automatic fire detection & alarming system.					
	 Type of detectors 	-NA-	-NA-	-NA-		

		-NA-	-NA-	-NA-
	Location of Main Panel	-NA-	-NA-	-NA-
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	-NA-	-NA-	-NA-
	Hooter's location		Provided	MR
	DEFA	Required	Provided	MR
	blic Address System	Required	11071000	
0. Au	tomatic Sprinkler System	Derwined	Provided	MR
	Basement	Required -NA-	-NA-	-NA-
	 Upper floors 		-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-14/1-	
1. Int	ernal Hydrants.	B : 1	100 mm	MR
	 Size of Riser/Down-comer 	Required	02 No's	MR
	 Number of Hydrant per floor 	Required	02 No's	MR
	Hose box.	Required	02 140 5	17114
2. Ya	ard Hydrants.		04 No's	MR
	 Total number of hydrants. 	Required		MR
	Hose box.	Required	04 No's	IATIZ
13. Pu	ımping arrangements.			
	Ground Level		D '1 1	MR
	Discharge of main pump.	2850 LPM	Provided	MR
	Head of main pump.	70 m	Provided	MR
	Number of main pumps.	01	Provided	MR
	Jockey Pump output.	180 LPM	Provided	MR
	Jockey Pump head.	70 m	Provided	MR
	Standby Pump output.	2850 LPM	Provided	MR
	> Standby Pump head.	70 m	Provided	MR
	Auto Starting / Manual Stopping.	Required	Provided	MR
	Pump house access.	Required	Provided	IVIX
	Terrace Level		2 11	MR
	Discharge of pump.	450 LPM	Provided	MR
	➤ Head of pump.	40 mtr	Provided	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	IVIN
14.	Captive water storage for fire fighting.			MR
17.	Underground tank capacity.	1,00,000 Ltrs	Provided	MR
	Draw-off connection.	Required	Provided	
	Fire Service Inlet.	Required	Provided	MR MR
	Access to tank.	Required	Provided	MR
	Overhead tank capacity.	30,000 ltrs	30,000 ltrs	MR
15.	Exit Signage.	Required	Provided	IVIK
	Provision of Lifts.		NTA	-NA-
	 Pressurization of lift shaft. 	-NA-	-NA-	-NA-
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-
20	 Communication in lift car. 	-NA-	-NA-	MR
	Fireman's switch.	Required	Provided	MR
	Lift signage.	Required	Provided	
17.	Standby Power Supply	Required	Provided (DG Set)	MR
	Refuge Area			BTA
10.	Total area	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	• Location			-
19.	Fire Control Room.	-NA-	-NA-	-NA
	Detector system panel.		-NA-	-NA
	 Flow switch panel. 	-NA-	-1477	

Wa

-NA-	-NA-	-NA-
-NA-	-NA-	-NA-
-NA-	-NA-	-NA-
-NA-	-NA-	-NA-
	-NA- -NA-	-NANA- -NANA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/Instt./2018/719 Dated 24/07/2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is pur up for approval and signature please.

Signature of the Inspection Officer

Name: Sh. Sunil Chawdhary Designation: Dy. CFO (SZ)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

IS 7/21

Keny 15) x 15) x 15) x 15) x 15) x

As approved, F.T. Letter in pully for your signature Pl.

. Director Hotgan

MSEY