GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2021/SZ/ 536

Dated: 27 07 2021

FIRE SAFETY CERTIFICATE

Certified that the **Govt. Boys Sr. Sec. School,** Rajouri Garden (Extn.), New Delhi-110027 comprised of ground plus one upper floor, owned/occupied by Govt. of NCT of Delhi was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2017/SZ/1776 dated 08/12/2017. The school building was re- inspected by the officer concerned of this department on 12/07/2021 in the presence of Sh. Pawan Kumar (Principal) and found that the School building have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on. 27 07 2021 at New Delhi.

(SUNIL CHAWDHARY) DY.CHIEF FIRE OFFICER

Copy to:-

- The Principal, Govt. Boys Sr. Sec. School, Rajouri Garden (Extn.), New Delhi-110027
- Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

			INSPECTION REPORT						
	4.	 Name & address of the building Building is comprised of Type of Occupancy Govt. Boys Sr. Sec. School, Rajouri Garden (Extn.), New Delhi-27 							
	3.								
	Renewal : Renewal								
		Fire S	afety directives letter No	F.6/DFS/MS	/School/2017/S	Z/1776 dated 08/12	/2017		
		Date o	f inspection	- Circular No. F.:	16/Estate/CC/Fin	e Safety/2011/3298 to	3398 dated 01 03 20		
	8.	Name	of Inspecting Officer	· ADODES			3,000,01,00,20		
	9.	Name and designation of officers							
		From the building side Sh. Pawan Kumar O. Year of Construction 2014							
		rear o Annlie	ant's letter No.	2014	4				
S.	No.	Minin	mum Standards - C	: GBSSS/RGE/	GBSSS/RGE/2021 dated 05/07/2021				
		fire s	mum Standards on fire prafety U/R 33	evention and	Requiremen	nt Provided at	Remarks		
1		Acces	s to building			site	MR/NMR		
		9	Road width		Accessible 06	137.13			
		•	Gate width		4.5 m	VO III	MR		
		•	Width of internal road	A	N/A	Directly accessib	IVI/IX		
2.		Numb	<mark>er, Width</mark> , Type & Arran	COMMON CE		N/A	N/A		
				Sement of Exits					
		a. Nui	nber of staircases						
			Upper Floors		0.0				
		**	Basements		03 no.'s	04 no.'s	MR		
		1	th of staircases		N/A	N/A	N/A		
			Upper Floor				Marie and the Secretary and the secretary of the secretar		
		0	Basements		1.50 m	1.55 (03 no.'s)	MR		
					27/4	& 1.45 m			
	c	. Prote	ection of exits		N/A	N/A	N/A		
		9	Fire check door						
		89	Pressurization		N/A	N/A	N/A		
				-	N/A	N/A	N/A		
	d.	No.	of continuous staircases to				The state of the s		
		terra	ice		Required	Two	MR		
	e.		th of Corridor		1.50 m	1.75 m			
	f.	Doo	r Size		1.0 m	1.08 m (double)			
3.	-					door)	MR		
J.,		ompar	tmentation			4001)			
			iro che 1 1						
			Fire check door		N/A	N/A	N/A		
		9	Sealing of electrical shafts		N/A	N/A			
		a [Fire Rating of shaft door Water Curtain		N/A		N/A		
			ire Dampers	-		N/A	. N/A		
				-	N/A N/A	N/A	N/A		
	Sin	oke N	lanagement System		: N/A	N/A	N/A		
		• B	asements		N/A	N/A	NT/A		
			N.			1.11.2	N/A		
		e U	pper floors		Required	Natural Ventilation	MAD		
	E71	W7				provided	MR		
			guishers						
			otal numbers		25 No's	45 no.'s provided	MD		
			pes	A	ABC/CO ₂ type	Provided	MR		
	E		marking		ISI marked		MR		
	FIFS	t-Aid	Hose Reels			ISI marked	MR		
	-	n	1						
		To	tal numbers on each floor		N/A	N/A	DIA		
	0	Le No	ngth of hose reel hose		N/A	N/A	N/A		
	6	. 140	zzle diameter	17.0	TOTAL .	7 41 7 7	N/A		

7.	Automatic fire detection and alarming system						
	Type of detectors	N/A	N/A	N/A			
	 Location of Main Panel 	N/A	N/A	N/A			
	 Location of Repeater Panel 	N/A	N/A	N/A			
	 Alternate source of power 	N/A	N/A	N/A			
	 Hooters' Location 	N/A	N/A	N/A			
	MOEFA	N/A	N/A	N/A			
	Public Address System	N/A	Provided	MR			
	Automatic Sprinkler System						
	 Basement 	N/A	N/A	N/A			
	 Ground Floor 	N/A	N/A	N/A			
	 Sprinkler above false ceiling 	N/A	N/A	N/A			
1 1	Internal Hydrants						
	 Size of riser/down-comer 	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
12.	Hose Box	N/A	N/A	N/A			
8 200	Yard Hydrants	TAT / A	2.77.4	2.5.1.4			
	 Total number of hydrants Hose Box 	N/A	N/A	N/A			
13.	Pumping Arrangements	N/A	N/A	N/A			
3 4-7	Ground Level						
	Discharge of main Pump	N/A	N/A	B.I.I.A			
	➢ Head of Main pump			N/A.			
	Number of main pumps	N/A	N/A	N/A			
	 Jockey Pump out put 	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	 Standby Pump Head Auto Starting/Manual Stopping 	N/A	N/A	N/A			
	Auto Statung Wantar Stopping	N/A	N/A	N/A			
		N/A	N/A	N/A			
	➢ Pump House Access	N/A	N/A	: N/A			
	* Terrace level						
	 Discharge of pump 	N/A	N/A	N/A			
	➢ Head of the pump	N/A	N/A				
	Power Supply	N/A	N/A	N/A			
	Auto Starting of pump	N/A	N/A	N/A			
	Captive Water Storage for fire fighting						
	 Underground tank capacity 	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	N/A	N/A	N/A			
15.	Exit Signage.	N/A	N/A	N/A			
16.	Provision of Lifts.	lo Lift)					
	 Pressurization of Lift Shaft 	N/A	N/A	N/A			
	 Pressurization of Lift lobby 	N/A	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
	 Fireman's Grounding Switch 	N/A	N/A	N/A			
	Lift Signage						
		N/A	N/A	N/A			

17.0	Standl	y power supply	N/A	N/A	N/A			
18.	Refuge	Area.						
	<i>i</i>	Total Area	N/A	N/A	N/A			
	AST.	Location	N/A	N/A	N/A			
19.	Fire Control Room							
	- 6	Detector System Panel	N/A	N/A	N/A			
	0	Flow Switch Panel	N/A	N/A	N/A			
	9	PA System Panel	N/A	N/A	N/A			
	0	Building Floor Plans	N/A	N/A	N/A			
	*		N/A	N/A	N/A			
20.		Fire Protection System for Protection of Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the decimed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2017/SZ/1776 dated 08/12/2017 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting 3 21 28 1

Name: - R.K. Yadav

Designation: - Asstt. Divisional Officer

Divisional Officer (South West)

Dy cho (52)

F.t. plees

ADO/OMP)

-T Letter 15 put uf

for signature Mo

Kleista