c-217

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/Hotel/2021/SZ/ 2 2

Dated: 26(7)21

FIRE SAFETY CERTIFICATE

Certified that the M/S Piccadily Hotels Pvt. Ltd., Janak Puri District Centre, New Delhi-110058, comprised of Lower Basement & Upper Basement, Service floor, Ground plus eleven upper floors, was issued FSC by this department vide letter F6/DFS/MS/Hotel/2018/SZ/761 dated 20/04/2018, owned/occupied by M/S Piccadily Hotels Pvt. Ltd. was re-inspected by the officers concerned of this department on 13/07/2021 in the presence of Sh. Prakash Singh Badal and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class "Residential" w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed below.

DIRECTOR
DELHI FIRE SERVICE

Copy to:-

- 1. The Authorized Signatory, M/S Piccadily Hotels Pvt. Ltd., Janak Puri District Centre, New Delhi-110058.
- 2. The Addl. Commissioner of Police (Lic.) 1st Floor, Defence Colony Police Station, New Delhi.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Piccadily Hotels Pvt. Ltd., Janak Puri District Centre, New Delhi-58. Name & address of the building: Residential Type of Occupancy Renewal Type of Case F6/DFS/MS/Hotel/2018/SZ/761 dated 20/04/2018 Details of Previous NOC F6/MS/DFS/BP/2003/621 dated 25.03.2003 Fire Safety directives letter No 13/07/21 Date of inspection Dy. Sunil Chawdhary & A.D.O. R.K. Yadav Name of Inspecting Officers Name and designation of officers Sh. Prakash Singh Badal From the building side 2008-2009. Year of Construction No. Nil dated 30/06/2021 10. Applicant's letter No. Remarks Provided at site NBC/ BBL Minimum Standards on fire prevention and MR/NMR Requirement fire safety U/R 33 Access to building M/R 12 mtrs 12 mtrs. Road width M/R 6.0 & 6.0 mtr 06 mtrs. Gate width M/R 06 mtrs 06 mtrs. Width of internal road Number, Width, Type & Arrangement of Exits a. Number of staircases M/R 05 No's 05 No's Upper Floors M/R 05 No's & 01 No. Basements 05 No's & 01 No. Ramp Ramp b. Width of staircases Upper Floor 1.18,1.48,1.48,1.40 M/R, Old case 1.25/1.50 m each & 1.18 m Basements 1.18, 1.48, 1.48, 1.40 M/R, Old case 1.25/1.50 m each & 1.18 m c. Protection of exits M/R Required Fire check door M/R Required Pressurization M/R Provided d. No of continuous staircases to Required M/R terrace 1.60.1.75& 1.85 m 1.5 m e. Width of Corridor M/R. Old case 85 m x 2.0 m 01 m f. Door Size Compartmentation M/R Required Fire check door M/R Sealing of electrical shafts Required Fire Rating of shaft door M/R Provided Required Water Curtain N/A N/A N/A Fire Dampers M/R Required Smoke Management System M/R Provided Required Basements M/R Provided Required Upper floors Fire Extinguishers M/R Provided 150 No's Total numbers M/R Provided ABC/CO2/WCO2 Types M/R ISI marked Provided IS marking First-Aid Hose Reels M/R Provided Three Total numbers on each floor M/R Provided 30 mtrs Length of hose reel hose BEID

INSPECTION REPORT

	Automatic fire detection and alarming system			8
	Type of detectors	Smoke & Heat	Provided	M/R
A CONTRACTOR OF THE CONTRACTOR	 Location of Main Panel 	Required	Upper Basement	M/R, Old Case
	 Location of Repeater Panel 	N/A	N/A	N/A
				M/R
	Hooters Location	A	Near exits	M/R
	MOEFA		The state of the s	M/R
	The same of the sa	M/R		
0		Required	Provided	M/R
		The state of the s	Provided	M/R
			Provided	M/R
		1 100		
,	The same of the sa	150mm	Provided	M/R
			Provided	M/R
			Provided	M/R
2.		<u> </u>		:
	· ·	Required	Provided	M/R
	Hose Box	Required	Provided	M/R
}.				
	Ground Level			
	 Discharge of main Pump 	2850 LPM	Provided	M/R
	Head of Main pump	100 mtrs	Provided	M/R
200	Number of main pumps	Two	Provided	M/R
	➢ Jockey Pump out put	220 LPM (two)	Provided	M/R
	Jockey pump head		Provided	M/R
			Provided .	M/R
				M/R
	and the second s			M/R
	7 mile starting/militari bropping			
	Pump House Access	Required	Provided	M/R
	 Discharge of pump 	N/A		N/A
	Head of the pump	THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAME		N/A
		The second secon		N/A
	Auto Starting of pump	N/A	N/A	NAK.
4.	• Alternate source of power • Hooters Location **MOEFA** **Public Address System **Provided Required Provided Provided Required Provided Required Provided Provided Required Provided Provided Required Provided Provided Provided Required Provided Provided Provided Provided Provided Provided Provided Required Provided			
	A STATE OF THE STA	2,50,000 ltrs	Provided	M/R
		Required	Provided	M/R
			Provided	M/R
		A	Provided	M/R
	Overhead Lank capacity		Provided	M/R
41	Exit Signage.		Provided	M/R
6.				3 0
J.,		Required	Provided	M/R
				M/R
				M/R
				M/R
		-		M/R
	Lift Signage			
17.	Standby power supply	Required	Provided	M/R
18.	Retuge Area.			M/R

Comprised of Lower Basement, Upper Basement, Ser	vice Floor, Ground plus Elev	on oppor		
		Provided	M/R	
19. Fire Control Room	Required	Provided	M/R	
Detector System Panel Flow Switch Panel	Required	Provided	M/R	
PA System Panel	Required	Provided	M/R	
 Battery backup 	Required	Provided	M/R	
Building Floor Plans	Required	Provided	179	
20. Special Fire Protection System for Protection of special Risks, if any:	Required CO ₂ /clean agent Flooding in electronic equipment rooms in upper basement		dea	
The fire protection systems provided in the inspection. In view the deemed compliance of measures as required under the rules, the FSC 20/04/2018, renewal under rule 37 of the Delh	Signature of Insparers Sunil Ch	MS/Hotel.	2018/SZ/761 dated	
Name:-R.K. Yadav Designation:- Asstt. Divisional Officer C.F.O. (HQ) SM Designation:- Asstt. Divisional Officer	Designation: - Design	110	np for	
01 P/S2	A Majo	1/20	nre plant	