C-82

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 255

Dated: 2.7. 1.../2021

## FIRE SAFETY CERTIFICATE

Issued on ... 2.7./........ at New Delhi by.

(Dr. S.K. Tomar) Dr. Chief Fire Officer Delhi Fire Service

72/2/2/21

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID no. 2021061113776 dated 12.06.21
- 2. The Commissioner, North MCD, Civic Centre, New Delhi
- 3. The Manager,

Amba Dx. Guest House 3437, Dariba Pan, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT						
1. Name & address of the building Amba Dx. Guest House at 3437, Dariba						
1.1\2	line & address of the building	Pan, Pahar Ganj, New Delhi				
э т	Type of occupancy:-	Residential, Sub Division-A-1				
2. 1	2. Type of occupancy. $G_r + \Omega_r^{th}$ floors (15 Guest rooms)					
	Ground floor (03 guest rooms + reception),  1 <sup>st</sup> floor to 3rd floor (04 guest rooms at each floor)					
		fourth floor not	in use as per affidavid	dated		
		07.10.2019				
2	Renewal					
4.	Details of previous FSC:-	F6/DFS/MS/C	GH/2018/NDZ/177	2 dated		
т.	4. Details of previous 1 Se. 31/07/2018.					
5	5. Fire safety directives No N/A					
6.	Date of inspection:-	13/07/21				
7.	Name of the inspecting officer:-	Sh. Ravinder	Singh (ADO/CC)			
Sh. Rajinder Atwal DO (CD)						
8.	Name & designation of officer	~1 ~	() (1000000)			
	From the building side:-	Sh. Davende	er (Manager)			
9.	Year of construction:-	1992	C dated 12 06 21	old case		
10.	Applicant's letter No:-		6 dated 12.06.21 .  Provided at site	Remarks		
S.No.	Minimum Standards on fire	Requirement/	Provided at site	MR/NMR		
	Prevention and fire safety U/R	Existing fire safety		500		
	33	arrangements				
4	Access to Building	arrangemens				
1.		N/A	02 mter	MR		
	1) Road width	N/A	N/A	N/A		
	2) Gate width	100 000	N/A	N/A		
	3)Width of internal road	N/A				
2.	Number, Width Type & Arra	angement of Ex	115			
	A. Number of staircases	01 No.	01 No.	MR		
	1. Upper floors		N/A	N/A		
	2. Basements	N/A	INIZI			
	B. Width of staircase	0.80 mtr.	0.80 to 0.92 mtr.	MR		
	1. Upper floors	Existing old case	0.00 to 5.5			
	2. December	N/A	N/A	N/A		
×	2. Basements C. Protection of exits	1772				
	1. Fire check door	N/A	N/A	N/A		
		N/A	N/A	N/A		
	2. Pressurization D. No. of continuous	01	01	MR		
	Staircase to terrace		1 1/1	2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		
	E. Width of corridor	N/A	N/A	N/A		
	F. Door size	1 mtr.	1 mtr.	MR		
	Compartmentation					
3.		N/A	N/A	N/A		
	1) Fire check door		N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers					
4.	Smoke Management System	NA NA	N/A	N/A		
	1) Basements	147.7				



1		
4	138	
	1	

	1			
	2) Upper floors	Required as	Not provided	Last dt.
	2) Opper ficois	per G.N dated		30.09.21 of
		27.05.19		compliance
			1.	extended vide
				order dt.
				29.06.2021
	Fire Extinguishers	1031	10 Nos.	MR
	1) Total numbers	10 Nos.	ABC & CO2	MR
	2) Types	ABC & CO2	Provided Provided	MR
	3) ISI marking	Required	Provided	
	First-Aid Hose Reel		01	MR
	1) Total number of eachfloor	01	30 mtr.	MR
	2) Length of hose reel hose	30 mtr.		MR
	3) Nozzle diameter	05 mm	05 mm	IVIIC
•	Automatic Fire Detection & A	Alarming System	m	Last dt. 30.09.21
•	1) Type of detectors Co type	Required as	Not provided	of compliance
	1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1	per G.N dated		extended vide
		27.05.19		order dt.
				29.06.2021
			- 71:	N/A
	2) Location of main panel	N/A	N/A	
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
0	MOEFA	Required	Provided	MR
8.	Public Address System	N/A	N/A	N/A
9.	Automatic Sprinkler System	1		
10.	1) Basement	N/A	N/A	N/A
	1) Basement	N/A	N/A	N/A
	<ul><li>2) Upper floors</li><li>3) Sprinkler above false</li></ul>	N/A	N/A	N/A
			,	
	ceiling			2.5
11.	Internal Hydrants	N/A	N/A	N/A
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	1 1/1 1		
	floor	N/A	N/A	N/A
	3) Hose box	1 1/1 2		1,3
12.	Yard Hydrants	N/A	N/A	N/A
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	14/17		1
13.	Pumping Arrangement	NI/A	N/A	N/A
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main	N/A	14/71	
	pump	> T / A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pu	mp N/A	N/A	N/A
	d) Jockey pump out pr	ut N/A		N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump out	put N/A	N/A	N/A
	g) Stand by pump hea	d N/A	N/A	N/A
	h) Auto starting/Manu	ial N/A	N/A	IN/ FX

	gtonning	1		The second secon
	stopping			
	2) Terrace level	450 I DN 4	450 I D) 4	) (D
	a) Discharge of pump	450 LPM	450 LPM	MR.
	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
14	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for Fi		27/4	137/4
	1) Under ground tank	N/A	N/A	N/A
	capacity	21/4	27/4	27/4
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
N.	c) Access to tank	N/A	N/A	N/A
	d) Over head tank	5000 ltr.	5000 ltr.	MR
1.7	capacity	D 1 1	2	1.00
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
-	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
10.				
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
×	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System any:	n for Protection	of special Risk, if	NA

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/NDZ/1772 dated 31/07/2018, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name: - Rajinder Atwal Designation: - DO (CD)

Name: - Rayinder Singh Designation: - ADO (CC)

approved FT 4 put up forkers formul