L43

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 257

Dated: 27./.7./2021

FIRE SAFETY CERTIFICATE

Certified that the Radha Krishna Guest House located at 8913/2, Multani Dhanda, Pahar Ganj, New Delhi comprised of Ground (Reception), 1st floor (05 guest rooms), 2nd floor (05 guest rooms) and 3rd floor (05 guest rooms + kitchen for staff), total 15 guest rooms owned/occupied by Radha Krishna Guest House was granted FSC by this department vide letter No.F6/DFS/MS/GH/2018/NDZ/1675 dated 17/07/18. Now, The premise was re-inspected by the officer concerned of this department on 22/07/21 in the presence of Sh. Rahul (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground (Reception), 1st floor to 3rd floor (05 guest rooms at each floor) total 15 guest rooms up to third floor with effect from -2-7-12-1-12-1-for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued $\frac{27}{7}$ at New Delhi by.

(**Dr. S.K.Tomar**) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi.ID No 2021062314135 dated 25.06.21
- 2. The Manager, Radha Krishna Guest House 8913/2

Radha Krishna Guest House 8913/2, Multani Dhanda, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

M-18

INSPECTION REPORT

Radha Krishna Guest House at 8913/2, 1. Name & address of the building

Multani Dhanda, Pahar Ganj, New Delhi

Residential, Sub Division-A-1 2. Type of occupancy:-

Gr. + 03 Upper floors (total 15 Guest rooms) Ground (Reception), 1st floor (05 guest rooms), 2nd floor (05 guest rooms) and 3rd floor (05 guest

rooms + kitchen for staff)

3. Type of case:-

4. Details of previous FSC:-

No. F6/DFS/MS/GH/2018/NDZ/1675 dated

22/07/21

Renewal

5. Fire safety directives No.-

6. Date of inspection:-

7. Name of the inspecting officer:-

8. Name & designation of officer From the building side:-

9. Year of construction:-10. Applicant's letter No:-

Sh. Ravinder Singh (ADO/CC)

Sh. Rahul (Manager)

2008

N/A

2021062314135 dated 25.06.21 .

	1.1			Old Case	
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building				
-	1) Road width	N/A	04 mtr.	N/A	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arr.	angement of Ex	its	. 14 14124	
	A. Number of staircases				
	1. Upper floors	01 Nos.	01 Nos.	MR	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase		1		
	1. Upper floors	0.80 mtr.	1.25 mtr.	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits				
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	01	01	MR	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	1.0 mtr.	1.0 mtr.	MR	
3.	Compartmentation		1,7	1	
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	30 ACPH	N/A	N/A	
	2) Upper floors	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance extended vide order dt. 29.06.2021	
5.	Fire Extinguishers		10.71	MD	
	1) Total numbers	10 Nos.	10 Nos.	MR	
	2) Types	ABC & CO2	ABC & CO2	MR	



	3) ISI marking	Required	Provided	MD
6.	First-Aid Hose Reel	Required	riovided	MR O
0.	1) Total number of eachfloor	01	01	MD
	2) Length of hose reel hose	30 m	30 m	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &	Alarming Syst	OS IIIII	MR
_	1) Type of detectors ((b)	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance extended vide order dt. 29.06.2021
4	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System		TTOTACC	IVIIC
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling			14/71
11.	Internal Hydrants	I		
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor		2	
	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants		. 1	17.12
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main pump	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	2) Terrace level			
		150 I D) 1	450 LPM	MR
	a) Discharge of pump	450 LPM	TJU LI IVI	
	b) Head of pump	30 mtr.	30 mtr.	MR
	b) Head of pump c) Power supply	30 mtr. Required		
	b) Head of pumpc) Power supplyd) Auto starting of pump	30 mtr. Required Required	30 mtr.	MR
14.	b) Head of pumpc) Power supplyd) Auto starting of pumpCaptive Water Storage for Figure 1	30 mtr. Required Required ire Fighting	30 mtr. Provided Provided	MR MR
14.	b) Head of pumpc) Power supplyd) Auto starting of pump	30 mtr. Required Required	30 mtr. Provided	MR MR

	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire required under the rules the FSC issued vide letter no. measures as safety F6/DFS/MS/GH/2018/NDZ/1675 dated 17/07/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended up to third floor only.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

F. M. pl.

and Sepossim Please.