GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001 .F6/DFS/MS/GH/NDZ/2021/ 2 5 2 Dated. 2.7. /.7..../2021

No.F6/DFS/MS/GH/NDZ/2021/ 2 52

FIRE SAFETY CERTIFICATE

Certified that the Sahil Dx. Guest House located at 8216, Arakashan Road, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (reception), 1st floor (04 guest rooms), 2nd floor (03 guest rooms), 3rd floor (03 guest rooms) and 4th floor (kitchen for staff) total 10 guest rooms owned/occupied by Sahil Dx. Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/EH/2018/NDZ/1398 dated 14/06/18. Now, the premises was re-inspected by the officer concerned of this department on 20/07/21 in the presence of Sh. Sunny Arora and found that the said guest house building having fourth floor(kitchen & staff room) not in use as per affidavit dated 19.11.2019, have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (reception), 1st floor (04 guest rooms), 2nd floor (03 guest rooms), 3rd floor (03 guest rooms) total 10 guest accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 27/7/21-at New Delhi by.

0210mer 26/7/21

(Dr. S.K. Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

1. The Commissioner, North MCD, Civic Centre, New Delhi

- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID 2021062114090 dated 23.06.21.
- 3. The Manager,

Sahil Dx. Guest House 8216, Arakashan Road, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1. Name & address of the building Sahil Dx. Guest House at 8216/6, Arakashan Road, Pahar Ganj, New Delhi. Gr. + 04 Upper floors,) total 10 guest rooms Ground floor (reception), 1st floor (04 guest rooms), 2nd floor (03 guest rooms), 3rd floor (03 guest rooms) and 4th floor (kitchen for staff) not in use as per affidavit dated 19.11.2019 3. Type of case:-Renewal 4. Details of previous FSC:-No. F6/DFS/MS/EH/2018/NDZ/1398 dated 14/06/18. 5. Fire safety directives No.-N/A 6. Date of inspection:-20/07/21 7. Name of the inspecting officer:-Sh. Ravinder Singh (ADO/CC) 8. Name & designation of officer From the building side:-Sh. Sunny Arora 9. Year of construction:-Before 2007 10. Applicant's letter No:-ID 2021062114090 dated 23.06.21. Old Case S.No. Minimum Standards on fire Provided at site Requirement/ Remarks Prevention and fire safety Existing fire MR/NMR U/R 33 safety arrangements 1. Access to Building 1) Road width N/A N/A 06 mtr. 2) Gate width N/A N/A N/A 3) Width of internal road N/A N/A N/A Number, Width Type & Arrangement of Exits 2. A. Number of staircases 1. Upper floors 01 Nos. 01 Nos. MR 2. Basements N/A N/A N/A B. Width of staircase 1. Upper floors 1.10 Mtr. MR 0.80 mtr. 2. Basements N/A N/A N/A C. Protection of exits 1. Fire check door N/A N/A N/A 2. Pressurization N/A N/A N/A D. No. of continuous 01 01 MR staircase to terrace E. Width of corridor N/A N/A N/A F. Door size 01 mtr. 01 mtr. MR 3. Compartmentation 1) Fire check door N/A N/A N/A 2) Sealing of electrical shafts N/A N/A N/A N/A N/A N/A 3) Fire rating of shaft door N/A 4) Water curtain N/A N/A N/A N/A N/A 5) Fire Dampers Smoke Management System 4. Provided MR 1) Basements 30 ACPH Required as Not provided Last dt. 2) Upper floors 30.09.21 of per G.N dated 27.05.19 compliance



extended vide

M/ sm

5.	Fire Extinguishers				
	1) Total numbers	10	10	MR	
	2) Types	ABC & CO2	ABC & CO2	MR	
	3) ISI marking	Required	Provided	MR	
6.	First-Aid Hose Reel				
	1) Total number of eachfloor	01	01	MR	
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR	
	3) Nozzle diameter	05 mm	05 mm	MR	
7.	Automatic Fire Detection &				
	1) Type of detectors CO Type	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance extended vide order dt. 29.06.2021	
	2) Location of main panel	N/A	N/A	N/A	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	N/A	N/A	N/A	
	5) Hooter's Location	N/A	N/A	N/A	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	Required	Provided	MR	
10.	Automatic Sprinkler System				
	1) Basement	N/A	N/A	N/A	
	2) Upper floors	N/A	N/A	N/A	
	3) Sprinkler above false	N/A	N/A	N/A	
	ceiling	ë			
11.	Internal Hydrants		4		
	1) Size of riser/down-comer	N/A	N/A	N/A	
	2) Number of hydrants per	N/A	N/A	N/A	
	floor				
	3) Hose box	N/A	N/A	N/A	
12.	Yard Hydrants				
	1) Total number of hydrants	N/A	N/A	N/A	
	2) Hose box	N/A	N/A	N/A	
13.	Pumping Arrangement				
	1) Ground level	N/A	N/A	N/A	
	a) Discharge of main pump	N/A	N/A	N/A	
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pump		N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output	N/A	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual stopping	N/A	N/A	N/A	
	2) Terrace level				
	Z I TELIACE IEVEL		1	11	
		225 LPM	225 LPM	MR	
	a) Discharge of pump b) Head of pump	225 LPM 18 mtr.	225 LPM 18 mtr.	MR MR	

4/25

	d) Auto starting of pump	Required	Provided	MR	
14.	Captive Water Storage for Fire Fighting				
	Under ground tank capacity	N/A	N/A	N/A	
	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	c) Access to tank	N/A	N/A	N/A	
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.				
	a) Pressurization of lift shaft	N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	N/A	N/A	N/A	
17.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
	Total area location	N/A	N/A	N/A	
19.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
	d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A	
20.	Special Fire Protection System for Protection of special Risk, if any: ABC & CO ₂			MR	

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/EH/2018/NDZ/1398 dated 14/06/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended up to third floor.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

DO(CD)

23/7/21

F. A. p'

KJ0mm/

son Deuten for (ca)