(83

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/GH/2021/SZ/ 2 3

Dated: 26.../ 7.../2021

FIRE SAFETY CERTIFICATE

Certified that M/s Silver Ferns Hotel, (A Unit of Krishna Continental Ltd.) 31-32, Community Centre, Saket, New Delhi-110017 comprised of 2 tier Basement, ground plus three upper floors & structure at terrace (Sealed with Brick Wall), owned occupied by (A Unit of Krishna Continental Ltd.) with total 49 Guest Rooms was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/GH/2017/SZ/825 dated 08/06/2017 for 2 tier basement, ground plus three upper floors. The premise was re-inspected by the officer concerned of this department on 17/07/2021 in the presence of Mr. Santosh Jha (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, (Hotel) Group-A" (for ground plus three upper floor only) as above with effect from 26/7 /2021 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on $\frac{26}{7}$ /2021 at New Delhi by

(SUNIL CHAWDHARY)
DY. CHIEF FIRE OFFICER (SZ)

Copy to: -

- 1. The Manager M/s Silver Ferns Hotel, (A Unit of Krishna Continental Ltd.) 31-32, Community Centre, Saket, New Delhi-110017
- 2. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049

Conditions for the validity of Fire Safety Certificate: -

1. This FSC is valid for ground plus three upper floors only.

2. All the means of escape/entry/exit shall be kept free from any obstruction.

- 3. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of fire fighting system.
- 5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."
- 8. The provision's under clause 7.31 of UBBL-2016 shall be done in the building on or before 30/09/2021 in compliance to the notification dated 27/05/2019 an as approved and now have

	·						
		INSPECTION REPORT					
1	Name & Address of the Building			Hotel, (A Unit of Kris			
		Continental Ltd.) 31-32, Community Centre, Saket, New Delhi-110017					
2	Type of Occupancy	Residential & Lodging, "Group-A" (Guest House)					
3	Building Comprised of	2, Tier Basements, Ground + 03 upper floor (Structure at terrace (Sealed with Brick Wall)					
4	Type of Case	Renewal					
5	Details of Previous NOC	F6/DFS/MS/GH/2018/SZ/825 dated 08/06/2017					
6	Fire Safety Directives Letter No	F6/DFS/MS/90/(Hotel)/1768 Dated 05/10/1990					
7	Date of Inspection	17/07/2021					
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)					
9	Name & Designation of Officers	Sh. Santosh Jha (Manger)					
	from the building side						
10	Year of construction	1991 Basement, GF (13 Room), 18 Rooms at Second flo					
11	A 1' (1 () N			floor each Total 49 G/ Rooms.			
11	Applicant letter No.	-		09/07/2021	*		
S. No.	Minimum standards on Fire Prevention	NBC/BBL		Provided at Site	Remarks		
4	and Fire Safety U/R 33	requii	ements		MR/NMR		
1	Access to Building.			10	7.55		
	Road width	-	mtr	12 mtr	MR		
	Gate width		IA-	-NA-	-NA-		
	Width of internal road	-1	IA-	-NA-	-NA-		
2	Number, width, type & arrangement of exits.						
	g) Number of Staircase						
	Upper floors.	02 Nos		02 Nos	MR		
	Basement floor.	02 Nos		02 Nos	MR		
	h) Width of Staircase						
	Upper floors	1.50 m	& 0.90 m	1.10 m & 0.90 m	MR		
	Basement floor	mtr			(old case)		
			& 0.90 m	1.10 m	NMR		
		I	ntr	1.10 111			
	i) Protection of exits						
	Fire check door	Required		Provided	MR		
	Pressurization	-1	IA-	-NA-	-NA-		
	j) No. of continuous staircase to terrace	One		Two	MR		
	k) Width of corridor	1.5 m		1.4 m	MR(Old		
		lm		1.4 111	Case)		
	l) Door size			0.84 m	MR(Old		
3	Compartmentation.				Case)		
	Fire check door.	Rec	uired	Provided	MR		
	Sealing of electrical shafts.	The state of the s	VA-	-NA-	-NA-		
	Fire rating of shaft door.		NA-	-NA-	-NA-		
	Water curtain		NA-	-NA-	-NA-		
		-	NA-	-NA-	-NA-		
1	Fire dampers. Smoke Management system.	-1	1/7-	-11/7-	-IV/A-		
4	Smoke Management system.	30 ACPH		E-1	3.00		
	Basement			Exhaust fan Provided	MR		
	Upper floors	12 a/c per hour		Natural ventilation	MR		
5	Fire Extinguishers.						
	Total numbers	24	Nos	Provided	MR		
	 Types 	ICIA	Marked	ABC- 20, CO2 -04 &	MR		
	ISI Marking	101 1	rai KCU	W.CO2 -04			
y ,				Provided	MR		

6	First Aid Hose Reels.				
	 Total numbers on each floor. 	One	Provided	MR	
	 Length of hose-reel hose. 	30 mtr	Provided	MR	
	Nozzle Diameter	5 mm	Provided	MR	
7	Automatic fire detection & alarming system.	(Circular dated 29/06/2021 amendment / modifin (UBBL-2016)			
	Type of detectors	Smoke & Heat	Provided	MR	
	Location of Main Panel	Required	Provided	MR	
	Location of Repeater Panel	NA	N/A	N/A	
	Alternate source of power	Required	Provided	MR	
	Hooter's location	Required	Provided	MR	
8	MOEFA	Required	Provided	MR	
9	Public Address System	NA	Provided	NA NA	
10	Automatic Sprinkler System	1471	TTOVIGEG	INA	
The second secon	Basement	Required	Provided	MR	
	Upper floors.	-NA-	-NA-	-NA-	
	Sprinkler above false ceiling	-NA-	-NA-	-NA-	
11	Internal Hydrants.	1471	-1/17-	-INA-	
·	Size of Riser/Down-comer	100 mm	Provided	MR	
	Number of Hydrant per floor	01	Provided	MR	
	Hose box.	01	Provided		
12	Yard Hydrants.		riovided	MR	
	Total number of hydrants.	-NA-	-NA-	NIA	
	Hose box.	-NA-	-NA-	-NA-	
13	Pumping arrangements.	-IAV-	-IVA-	-NA-	
	Ground Level				
	Discharge of main pump.	-NA-	1000 I DM	D.T.A.	
	Head of main pump.	-NA-	1080 LPM 38m	-NA-	
	Number of main pumps.	-NA-	01	-NA-	
	Jockey Pump output.	-NA-		-NA-	
	Jockey Pump head.	-NA-	180 LPM 38 m	-NA-	
	Standby Pump output.	-NA-	NA NA	-NA-	
	Standby Pump head.	-NA-	NA NA	-NA-	
	Auto Starting/Manual Stopping.	-NA-	Provided	-NA-	
	Pump house access.	-NA-	Provided	-NA-	
	Terrace Level	TASE	Tiovided	-IVA-	
	Discharge of pump.	450 LPM	Provided	MR	
	Head of pump.			MR	
	Power supply.	40m	39 Provided	(old case	
		Required	Provided	MR	
	Auto starting of pump.	Required	Provided	MR	
14	Captive water storage for fire fighting.			IVIIX	
- The Street and the	Underground tank capacity.	Required	1,00,000 ltr	MR	
	Draw-off connection.	Required	Provided	MR	
	Fire Service Inlet.	Required	Provided	MR	
	Access to tank.	Required	Provided	MR	
	 Overhead tank capacity. 	Required	20,000 Ltr	Marine Street Control of the Control	
15	Exit Signage.	A		MR	
-	Provision of Lifts.	Required	Provided	MR	
6	TIOVISION OF LIIES.				
6	Proceurization of LA -1 -0	NTA	N.T.A.	**	
16	Pressurization of lift shaft.Pressurization of lift lobby.	-NA-	-NA-	-NA-	

1	Communication in lift car.	-NA-	-NA-	-NA-
4	• Fireman's switch.	-NA-	-NA-	-NA-
Lift signage.		Required	Provided (DG Set)	MR
17	Standby Power Supply	1		
18	Refuge Area Total area Location	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
19	Fire Control Room.	DIA	-NA-	-NA-
	 Detector system panel. Flow switch panel. PA system panel. Battery backup. Building floor plan. Special Fire Protection System for the I	-NA- -NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA
		D / / - Campaig	I Diel if any	-NA

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 17 dated 18/03/2021

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/GH/2018/SZ/825 dated 08/06/2017, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer
Name: - Rajesh Kumar
Designation: - ADO/BCP

DO (8D)

efolsz)

A

Fit, plee

ADO(B(P)

As approved, F.T. Letter in pulp to your synature !!

Dychols2 b