FORM 'H' FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No.F6/DFS/MS/Hotel/SZ/2021/ 24

Dated: 28 7/2/

FIRE SAFETY CERTIFICATE

Certified that the M/s Hyacinth Hotels Pvt. Ltd. (Hotel Lemon Tree & Red Fox) situated at Asset No.-6, Hospitality District, IGI Airport, New Delhi-110037, comprised of Three tier Basement, Ground, Six Upper Floors & Terrace Floor owned / occupied by M/s Hyacinth Hotels Pvt. Ltd. (Hotel Lemon Tree & Red Fox), was granted Fire Safety Certificate by this department vide letter No. F6/DFS/MS/Hotel/SZ/2018/2556 dated 26/11/2018. The premises was reinspected by the officer concerned of this department on 03/07/2021 in the presence of Sh. Sh. Umashankar, A.M. (Engg.) and observed that all the Fire prevention and Fire Safety arrangements provided in the premises found in good working condition. The premises have therefore, deemed complied with rule 33 of the Delhi Fire Service rules, 2010 and that the building / premises is fit for occupancy Class Residential "Hotel" (Group-A) with effect from \(\setminus / 7 \) /2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions under 38 of the Delhi Fire Service rules, 2010.

Issued on ... 28 ... 1. 2. ... at New Delhi by.

DIRECTOR.

Copy to:-

- 1. Authorized Signatory, M/s Hyacinth Hotels Pvt. Ltd. (Hotel Lemon Tree & Red Fox), Asset No.-6, Hospitality District, IGI Airport, New Delhi-110037.
- 2. Joint Commissioner of Police (Lic.), 1st Floor, Police Station, Defence Colony, New Delhi-110024.

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape / entry / exit shall be kept free from any obstruction.
- All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
- Any loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of fire fighting system.
- This Fire Safety Certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3. of UBBL-2016), if any.
- This certificate cannot be treated in any case for regularizations of unauthorized construction.
- "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
- The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on WWW.dfs.Delhigovt.nic.in.

1. Name & address of the building: M/s Hyacinth Hotels Pvt. Ltd. (Hotel Lemon Tree & Red Fox), Asset No.-6, Hospitality District, IGI Airport, New Delhi-37. 2. Type of Occupancy : Residential "Hotel" 3. Type of Case: Renewal (3tier Basement, Ground, 6 Upper Floors & Terrace Floor) 4. Details of previous NOC :F6/DFS/MS/Hotel/SZ/2018/2556 dated 26/11/2018 5. Fire Safety directives Letter No.: F6/DFS/MS/BP/2010/2588 dated 06/09/2010. 6. Date of inspection : 03/07/2021 7. Name of the Inspecting Officers: A.D.O. (S.J.) 8. Name and designation of Officer from the building side : Sh. Umashankar, A.M. (Engg.) 9. Year of Construction :2012 10. Applicant's letter received through MHA portal ID-2021052413531dated 24/05/2021 Minimum standards on fire S NFPA /Old NOC Provided at Remarks prevention and fire safety No Requirements site MR/NMR U/R 33 1. Access of building Road width 12m Provided MR Gate width 4.5m Provided MR Width of internal road 6m Provided MR Number, width, Type & Arrangements of exits 2. Number of staircases Upper floors 6 Provided MR Basements B3 to GF-1 Provided MR B3 to B2-6 B2 to B1-6 B1 to GF-6 Width of staircases Upper floors 1.50 m Provided MR Basements 1.50 m B3 to GF-1.2m & MR (Old Rest are of 1.5m Case) Protection of exits Fire check door Required Provided MR Pressurization Required in Provided MR Basement d. No of continuous 6 Provided MR staircase to terrace Width Of Corridor Required 1.50m MR f. Door Size 1m Provided (Final Exit) MR 3. Compartmentation Fire check door Required Provided MR Sealing of electrical Required Provided MR shafts Fire Rating of shaft door Required Provided MR Water Curtain Required Provided MR Fire Dampers Required Provided MR Smoke managements System 4. Basements 30ACPH M.V. Provided MR Upper floors 12 ACPH M.V. Provided MR 5. Fire Extinguishers Total numbers Required 242 MR Types ABC/CO₂/WCO₂ 110/110/20/02 MR ISI marking ISI Provided MR

473 First - Aid Hose Reels MR Provided Total numbers on 6 each floor Length of hose reel 30 Mtr. 30 Mtr. MR hose 5 mm MR Nozzle diameter 5 mm 7. Automatic fire detection and alarming system Smoke & Heat Provided MR Type of detector Ground Floor Provided Location of Main MR Panel Location of Repeater NA Security Room NA Panel Required Provided Alternate source of MR power Hooters' Location Required All Areas MR MOEFA 8. Required Provided MR 9. Public Address System Required Provided MR Automatic Sprinkler System 10. Required Provided MR Basements Required Provided MR Upper Floor Sprinkler above false Required Provided MR ceiling Internal Hydrants 11. Provided Size of riser/down-100 mm MR comer Number of hydrants Provided MR per floor 6 Provided MR Hose Box 12. Yard Hydrants Total number of Required 12 MR hydrants Required 12 Hose Box MR **Pumping Arrangements** 13. Ground Level 2850 LPM Provided Discharge of main pump MR > Head of main pump 80 m Provided MR Number of main pumps 2+1(WC) Provided MR > Jockey pump out put 180 LPM Provided MR Jockey pump head Provided 80m MR Standby Pump out put 2850 LPM Provided MR Standby Pump Head 80m Provided MR Auto Staring/Manual Provided Required MR stopping Pump House Access Required Provided MR Terrace level • Discharge of pump 900 LPM Provided MR Provided MR > Head of the pump 40 m Power supply Required Provided MR Auto starting of pump Required Provided MR

		NL24			
14	Captive water Storage for fire fighting				
	 Under Ground tank capacity 	1,50,000 ltr	7	Provided	MR
	Draw of connection	Required Required		Provided	MR
	Fire service inlet			Provided	MR
	Access to tank	Required		Provided	MR
1.5	Overhead Tank capacity	20,000 ltr		Provided	MR
15	Exit Signage	Required		Provided	MR
16.		ovision of Lifts			
	Pressurization of Lift Shaft	Required Provided		MR	
	Pressurization of lift lobby	Required	Provided		MR
	Communication in lift	Required	Provided Provided		MR
	Fireman's Grounding Switch	Required			MR
17	➤ Lift Signage	Required Provid		ovided	MR
17.	Standby power supply	Required	Pr	ovided	MR
18.	Refuge Area				
	Total area	Required	100m2		MR
	Location	6 th Floor	Pro	ovided in	MR
			COI	nformity with	
19.	Fire control		completion drawing		
17.	Fire control room				
-	Detector system panelFlow Switch Panel	Required		Provided	MR
-	- The street I dilet	Required		Provided	MR
+	TIT Dystelli I allei	Required		Provided	MR
•	Duckup	Required		Provided	MR
20.	- and fig 1 foot 1 falls	Required		Provided	MR
	Special Fire Protection Systems for Protection	CO2 flooding system provided in LT Panels.		Provided	MR
	Systems for Protection of special Risks, if any;				

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter no. F6/DFS/MS/Hotel/SZ/2018/2556 dated 26/11/2018 renewal under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Defoly Perolph

Signature of the Inspecting Officer Name : Ashok Kumar Jaiswal

Designation: A.D.O. (S.J.)