GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2021/ 278

Dated: 3 | 8 | 2 |

FIRE SAFETY CERTIFICATE

Delhi- 110005 comprised of basement, ground plus three upper floors, using basement as storage, ground floor as reception & office, first, second and third floor each having 08 guest rooms respectively (total 24 guest rooms) and two staff rooms in temporary shed on terrace floor, was granted FSC by this department vide letter No. F6/DFS/MS/GH/SZ/2018/937 dated 07.05.2018. The premises was re-inspected by the officer concerned of this department on 20/04/2018 in presence of Sh. Mayank, Leaser, and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for basement (storage), ground floor (reception & office), first, second & third floor each having 08 guest rooms respectively (total 24 guest rooms only) with effect from 3/8/21 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued on 3 8 2 at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to:-

- 1. The Owner, Hotel Sun City Deluxe, 11A/34, WEA, Karol Bagh, New Delhi- 110005.
- 2. The Joint, C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

Following Fire Safety Directives must be adhered to: -

- The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 10. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.

INSPECTION REPORT

1. Name & address of the building

: M/s. Hotel Sun City Deluxe, 11A/34, WEA, Karol

Bagh, New Delhi- 110005.

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: F.6/DFS/MS/GH/SZ/2018/937 dated 07.05.2018

5. Fire Safety directives letter No

: Nil

6. Date of inspection

: 27.07.2021

7. Name of the Inspecting Officers

: P.V. Rathee, Asstt. Div. Officer (SRD

8. Name and designation of officers

from the building side

: Sh. Mayank, Leaser

9. Year of Construction

: 2000-01

10. Applicant's letter No.

: Online Application Id 2021070714807 dated 16.07.2021

The said guest house is comprised of basement, ground plus three upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Fire safety arrangements as FSC dt. 07.05.20	l at site	Remarks MR/NMR				
1	Access to building				1.60			
	Road width	06 mts	Provided	MR				
	• Gate width	4.5 mts	Directly accessi	ble	MR			
	Width of internal road	N/A	N/A		N/A			
2	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases	-	<u>-</u>					
	• Upper Floors	01	01		MR			
	Basements	01	01	MRI	being old case			
	b. Width of staircases	- 1			-			
	Upper Floors	Old Case	1.25 mts		being old case			
	Basements	Old Case	1.30 mts	MR	being old case			
	c. Protection of exits	-	-					
	• Fire check door	Required	Not Provided		ompliance has beer d up to 30.09.2021			
	Pressurization	N/A	N/A		N/A			
	e. No. of continuous staircases to	01	01		MR			
	terrace	1.5 mts.	1.70, 1.12 mts.		MR			
	g. Width of Corridor			MD	haire ald cose			
	h. Door Size	Old case	0.82 mts	MIK	being old case			
3	Compartmentation.			date of	compliance has bee			
	Fire check door	Required	Not Provided		ed up to 30.09.2021			
	Sealing of electrical shafts	N/A	Sealed		and the same			
	Fire Rating of shaft door	N/A	N/A		N/A			
	Water Curtain	N/A	N/A		N/A			
	• Fire Dampers	N/A	N/A		N/A			
4	Smoke Management System.							
	Basements	30 a/c per hou			MR			
	• Upper floors	Jpper floors 12 a/c per hour Exhaust fan prod		MR				

	5	Fire Extinguishers						
		Total numbers		12		Provided	d	MR
		• Types		CO ₂ , ABC,		Provided	d	MR
		IS marking		ISI marked		Provided		MR
6	5	First-Aid Hose Reels.	- 00					
		Total numbers on each floor		01		Provided	d	MR
		 Length of hose reel hose 		30 n	n	Provided		MR
-		Nozzle diameter		5 mr	n	Provide	d	MR
7	7	Automatic fire detection and alarmi	ing	system.				
				Carbon	N	I-4 D 1 1	date of c	compliance has been
		Type of detectors	N	Monoxide	IN.	lot Provided	extende	ed up to 30.09.2021
		Location of Main Panel	R	Lequired	N	lot Provided		compliance has been
		• Location of Repeater Panel		N/A		N/A	extende	N/A
		Alternate source of power	R	Lequired		Provided		MR
		Hooters' Location		N/A		N/A		N/A
8		MOEFA	R	equired		Provided		MR
9		Public Address System.		equired		Provided		MR
1	0	Automatic Sprinkler System.						
	***********	Basement		Requir	red	Provided	1	MR
		Upper Floor		N/A		N/A		N/A
Table State		Sprinkler above false ceiling		N/A		N/A		N/A
1	1	Internal Hydrants			4			
		Size of riser/down-comer		N/A		100 mm		
		Number of hydrants per floor		N/A		01 No.		AND MICH DISK
		Hose Box		N/A		01 No.		
1	2	Yard Hydrants.						
		Total number of hydrants		N/A	N/A N/A			N/A
		Hose Box		N/A		N/A		N/A
1	3	Pumping Arrangements.						
		Ground Level				,,		
		Discharge of main Pump		N	I/A	N/A		N/A
		Head of Main pump		N	/A	N/A		N/A
		Number of main pumps			/A	N/A		N/A
		Jockey Pump out put			/A	N/A		N/A
		Jockey pump head			/A	N/A		N/A
		Standby Pump out put Standby Pump Head			/A	N/A		N/A
			Standby Pump Head Auto Starting/ Manual stopping		/A	N/A		N/A
		B. T. T. Brook	Pump House Access Terrace level Discharge of pump Head of the pump		/A	N/A		N/A
		Touse Heess			/A	N/A		N/A
		Ierrace level						
	-	Discharge of pump			LPM	900 LPM		MR
		Head of the pump			mts	30 mts		MR
		Power Supply			uired	Provided		MR
A CONTRACTOR OF THE CONTRACTOR		Auto Starting of pump		Req	uired	Provided		MR
14	4	Captive Water Storage for fire fighti	no			,		
-	- 1	Underground tank capacity	ug	· N/A		N/A		NT/A
		> Draw-off connection		N/A				N/A
		Fire service inlet		N/A		N/A Provided		N/A
		Access to tank		N/A		N/A		N/A
		Overhead Tark associty		10.000	1.	11/71		IN/A

1 1	90
M	-0x 8

15	Exit Signage.	Required	Provided	MR				
16	Provision of Lifts.							
	Pressurization of Lift Shaft	N/A	N/A	N/A				
	 Pressurization of Lift lobby 	N/A	N/A	N/A				
	 Communication In lift Car 	Required	Provided	MR				
	• Fireman's Grounding Switch	Required	Provided	MR				
	• Lift Signage	Required	Provided	MR				
17	Standby power supply	Required	Provided	MR				
18	Refuge Area.							
	Total Area	N/A	N/A	N/A				
	Location	N/A	N/A	N/A				
19	Fire Control Room							
	Detector System Panel	N/A	N/A	N/A				
	• Flow Switch Panel	N/A	N/A	N/A				
	 PA System Panel 	N/A	N/A	N/A				
	Battery backup	Required	Provided	MR				
	Building Floor Plans	N/A	N/A	N/A				
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A				

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09 .2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/GH/SZ/2018/937 dated 07.05,2018, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer P.V. Rathee

Asstt. Div. Officer (SRD)