GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/283

Dated: 0.4.0.8./2021

FIRE SAFETY CERTIFICATE

Certified that the Indo Continental Guest House located at 8490-91, Arya Nagar, Pahar Ganj, New Delhi comprised of Basement + Ground + 04 Upper floors, Basement (storage), Ground floor (01 guest rooms + reception + 01 office), 1st floor to 4th floor (05 guest rooms at each floor), total 21 guest rooms was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2018/1835 dated 07.08.2018. Now, The premise was inspected by the officers concerned of this department on 29/07/2021 in the presence of (Manager) and found that the said guest house building having 4th floor not in use as per affidavit dated 30.12.2019, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1, Ground floor (01 guest room), 1st floor to 3rd floor (05 guest rooms at each floor), total 16 guest rooms from ist to third floor only with effect from O.H. 28, 20.21. for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

(**Dr. S.K.Tomar**) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Commissioner, North MCD, Civic Centre, and New Delhi: to ensure not to use any floor above third floor for any purpose.
- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no. 2021061914031 dated. 19.06.2021
- 3. The Manager,

Indo Continental Guest House 8490-91, Arya Nagar, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- 1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

4/24

INSPECTION REPORT

Indo Continental Guest House at 8490-91, 1. Name & address of the building Arya Nagar, Pahar Ganj, New Delhi.

2. Type of occupancy:-Residential, Sub Division-A-1

B + Gr. + 04 Upper floors (total 16 Guest rooms) Basement (storage), Ground floor (01 guest rooms + reception + 01 office), 1st floor to 3rd floor (05 guest rooms at each floor) not in use any floor above third floor as per affidavit Dated 05.12 2019

3. Type of case:-Renewal

4. Details of previous FSC:-No.F6/DFS/MS/GH/NDZ/2018/1835

dated: 07.08.2018

5. Fire safety directives No.-

6. Date of inspection:-

7. Name of the inspecting officer:-

8. Name & designation of officer From the building side:-

9. Year of construction:-

10. Applicant's letter No:-

N/A 29/07/2021

Sh. Ravinder Singh (ADO/CC)

(Manager)

2001

2021061914031 dated. 19.06.2021

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	N/A	03 mtr.	N/A
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arr	angement of Ex	tits	
	A. Number of staircases			
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	01 Nos.	01 Nos.	MR
	B. Width of staircase		* .	
	1. Upper floors	0.80 mtr.	1.20 mtr.	MR
	2. Basements	0.80 mtr.	1.0 mtr.	MR
	C. Protection of exits		org High y	
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	01	01	01
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	01 mtr.	01 mtr.	MR
3.	Compartmentation			*
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	1) Basements	30 ACPH	Provided	MR
	2) Upper floors	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance extended
		2		vide order dt 29.06.2021

- 4128

5.	Fire Extinguishers	172				
	1) 77 (1	1				
	1) Total numbers	10 Nos.	10 Nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	Required	Provided	MR		
6.	First-Aid Hose Reel					
	1) Total number of eachfloor	01	01	MR		
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR		
	3) Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic Fire Detection & Alarming System					
	1) Type of detectors CO type	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance extended vide order dt. 29.06.2021		
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	N/A	N/A		
	5) Hooter's Location	N/A	N/A	N/A		
8.	MOEFA	Required	600 KI 60			
9.	Public Address System	N/A	Provided	MR		
10.	Automatic Sprinkler System	IN/A	N/A	N/A		
10.	1) Basement	Required	Duanidad) (D)		
	2) Upper floors	N/A	Provided N/A	MR		
	3) Sprinkler above false	N/A		N/A		
	ceiling	N/A	N/A	N/A		
11.	Internal Hydrants		2			
	1) Size of riser/down-comer	N/A	N/A	N/A		
	2) Number of hydrants per	N/A	N/A	N/A		
	floor	- 1/1-1		IVA		
	3) Hose box	N/A	N/A	N/A		
12.	Yard Hydrants		1777	14/71		
	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	N/A	N/A	N/A		
13.	Pumping Arrangement		1071	IVI		
	1) Ground level	N/A	N/A	N/A		
	a) Discharge of main	N/A	N/A	N/A		
	pump	1771	11/11	IVA		
	b) Head of main pump	N/A	N/A	N/A		
	c) Number of main pump	N/A	N/A	N/A		
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output	N/A	N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
	stopping	14/17	14/11	11/1		
	2) Terrace level					
	a) Discharge of pump	450 LPM	450 LPM	MR		
	b) Head of pump	30 mtr.	30 mtr.	MR		
	o) Hour of pullip	Jo mu.	JO IIIII.	IVIIX		

20.	Risk, if any:	IV/A				
20.	Special Fire Protection System			N/A		
	e) Building floor plan	N/A	N/A	N/A		
	d) Battery backup	N/A	N/A	N/A		
	c) PA system panel	N/A	N/A	N/A		
	b) Flow switch panel	N/A	N/A	N/A		
	a) Detector system panel	N/A	N/A	N/A		
19.	Fire Control Room	N/A	N/A	N/A		
	Total area location	N/A	N/A	N/A		
18.	Refuge Area	N/A	N/A	N/A		
17.	Stand by Power Supply	Required	Provided	MR		
4 89	e) Lift signage	N/A	N/A	N/A		
	d) Fireman's switch	N/A	N/A	N/A		
	c) Communication in lift car	N/A	N/A	N/A		
	b) Pressurization of lift lobby	N/A	N/A	N/A		
	a) Pressurization of lift shaft	N/A	N/A	N/A		
16.	Provision of Lifts.					
15.	Exit Signage.	Required	Provided	MR		
	d) Over head tank capacity	5000 ltr.	5000 ltr.	MR		
	c) Access to tank	N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	a) Draw-off connection	N/A	N/A	N/A		
	Under ground tank capacity	N/A	N/A	N/A		
14.	Captive Water Storage for Fire Fighting					
	d) Auto starting of pump	Required	Provided	MR		
	c) Power supply	Required	Provided	MR		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. No.F6/DFS/MS/GH/NDZ/2018/1835 dated: 07.08.2018 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval up to third floor only.

Signature of the Inspecting Officer

Name: - Ravinder Singh

Designation: - ADO (CC)

As apported Pti patup for 1cm ferry

2 21008/mi Pli