

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**

No. F.6/DFS/MS/EH/2021/SZ/ 168

Dated: 04/08/2021

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of **M/s Mamagota (A Unit of Azure Hospitality) at 305-306, Second Floor, DLF Promenade Mall, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070** owner occupied by (A Unit of Azure Hospitality Pvt. Ltd.) have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 30/07/2021 in the presence of Sh. Ravinder Singh (Manager) and that the premises is fit for occupancy class "**Group-D Assembly**) with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 04/08/2021 at New Delhi by


(ATUL GARG)
DIRECTOR

Copy to: -

1. The Dy. Health Officer, SDMC, Public Health Department, Green Park, Aurobindo Marg, New Delhi - 110016. (Ref. MHA Portal ID NO - 20020022102837)
2. The Joint Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049.
3. M/s Mamagota (A Unit of Azure Hospitality) at 305-306, Second Floor, DLF Promenade Mall, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070.

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire-fighting system.
4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT

1	Name & Address of the Building	M/s Mamagota (A unit of Azure Hospitality) at 305-306, SF, DLF Promenade Mall, -3, Nelson Mandela Marg, Vasant Kunj, New Delhi-110070		
2	Type of Occupancy	Assembly Building "Group-D" Restaurant		
3	Building Comprised of	Two tier Basement, LGF, UGF, 1 st Floor + Projection		
4	Type of Case	New		
5	Details of Previous NOC	Nil		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	30/07/2021		
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Naveen Kapoor (Manager)		
10	Year of construction	2012	Restaurant running at 2 nd Floor in DLF Promenade Mall building.	
11	Applicant letter No.	Online MHA Portal ID NO - 20020022102837		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Requirement/ Existing Fire Protection	Provided at Site	Remarks MR/NMR
1	Access to Building. FSC No.F.6/DFS/MS/Mall/2020/SZ/58 Dated 22/01/2020 of DLF Promenade Mall			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	Restaurant within Mall	As above	MR
			As above	N/A
			As above	N/A
2	Number, width, type and arrangements of exits.			
	g. Number of Staircase	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> • Upper floors • Basement floor 	02 Nos N/A	As above As above	MR N/A
	h. Width of Staircase	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> • Upper floors • Basement floor 	Required N/A	As above As above	MR N/A
	i. Protection of exits	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	Required N/A	As above As above	MR N/A
	j. No. of continuous staircase to terrace	Required	As above	MR
	k. Width of corridor	N/A	N/A	N/A
	l. Door size	2 Exits 1.50 m each	1.50 mtr x 2	MR
3	Compartmentation.	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> • Fire check door. • Sealing of electrical shafts. • Fire rating of shaft door. • Water curtain • Fire dampers. 	Required N/A N/A N/A N/A	As above As above N/A N/A N/A	MR N/A N/A N/A N/A
4.	Smoke Management system.	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> • Basement • Upper floors 	N/A Required	As above Exhaust fans provided	N/A MR
5.	Fire Extinguishers.			
	<ul style="list-style-type: none"> • Total numbers • Types • ISI Marking 	06 Nos ISI marked	06 Nos. ABC-04, W.CO ₂ -02 Provided	MR MR MR
6.	First Aid Hose Reels.	Provided & Maintained by DLF Promenade Mall		
	<ul style="list-style-type: none"> • Total numbers on each floor. • Length of hose-reel hose. • Nozzle Diameter 	Hose Reel	One in Restaurant 30m 5mm	MR MR MR

7	Automatic Fire Detection and Alarming system. (Provided & Maintained by DLF Promenade Mall			
	• Type of detectors	Required	Smoke & Heat	MR
	• Location of Main Panel	Required	As above	MR
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	Required	As above	MR
	• Hooter's location	Required	As above	MR
8.	MOEFA	Required	As above	MR
9.	Public Address System	Required	As above	MR
10.	Automatic Sprinkler System			
	Provided & Maintained by DLF Promenade Mall			
	• Basement	Required	As above	MR
	• Upper floors	Required	Provided in Restt.	MR
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.			
	Provided & Maintained by DLF Promenade Mall			
	• Size of Riser/Down-comer	Required	As above	MR
	• Number of Hydrant per floor	Required	As above	MR
	• Hose box.	Required	As above	MR
12.	Yard Hydrants.			
	Provided & Maintained by DLF Promenade Mall			
	• Total number of hydrants.	N/A	As above	N/A
	• 2. Hose box.	N/A	As above	N/A
13.	Pumping arrangements.			
	Provided & Maintained by DLF Promenade Mall			
	• Ground Level	Provided & Maintained by DLF Promenade Mall		
	➤ Discharge of main pump.	4500 LPM	As above	MR
	➤ Head of main pump.	70 mtrs	As above	MR
	➤ Number of main pumps.	Two	As above	MR
	➤ Jockey Pump output.	450 LPM	As above	MR
	➤ Jockey Pump head.	70 mtrs	As above	MR
	➤ Standby Pump output.	4500 LPM	As above	MR
	➤ Standby Pump head.	70 mtrs	As above	MR
	➤ Auto Starting / Manual Stopping.	Required	As above	MR
	➤ Access to pump house	Required	As above	MR
	• Terrace Level	Provided & Maintained by DLF Promenade Mall		
	➤ Discharge of pump.	N/A	N/A	N/A
	➤ Head of pump.	N/A	N/A	N/A
	➤ Power supply.	N/A	N/A	N/A
	➤ Auto starting of pump.	N/A	N/A	N/A
14.	Captive water storage for Fire Fighting.			
	Provided & Maintained by DLF Promenade Mall			
	• Underground tank capacity.	5,00,000 Ltrs	As above	MR
	➤ Draw-off connection.	Required	As above	MR
	➤ Fire Service Inlet.	Required	As above	MR
	➤ Access to tank.	Required	As above	MR
	• Overhead tank capacity.	20,000 Ltrs	As above	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	Provided & Maintained by DLF Promenade Mall			
	• Pressurization of lift shaft.	N/A	N/A	N/A
	• Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided (DG Set)	MR
18.	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A

19.	Fire Control Room.	Provided & Maintained by DLF Promenade Mall		
	• Detector System Panel.	N/A	As above	N/A
	• Flow Switch Panel.	N/A	As above	N/A
	• PA system Panel.	N/A	As above	N/A
	• Battery backup	N/A	As above	N/A
	• Building floor plan	N/A	As above	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any :	N/A	As above	N/A

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 254 dated 28/06/2021.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly, DFA is put up for approval and signature please.

14/30/21

Signature of the Inspecting Officer
 Name: Rajesh Kumar
 Designation: ADO / BCP

20/5/21

*diry
28/06/21*

DEFO (5/2)

*14
30/7*

C.F.O. (can diry off)

*Director of Fire
2/8/2021*

ADY MID

As approved, F.T. letter is put up for your

Signature of

14

14