GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/GH/NDZ/2021/ **2**80

Dated: 0.4. 0.8.../2021

FIRE SAFETY CERTIFICATE

Certified that the Sun Flower Inn Guest House located at 962, Gali Kumharan, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (Reception + 03 guest rooms), 1st floor to 2nd floor (06 guest rooms at each floor), 3rd floor & 4th floor (Owner residence), total 15 guest rooms owned/occupied by Sun Flower Inn Guest House was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/2018/NDZ/2172 dated 20/09/18. Now ,The premise was re-inspected by the officer concerned of this department on 27/07/21 in the presence of Mr. Sorabh and found that the said guest house building having affidavit dated 26.11.2019 not to use any floor above third floor, has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception + 03 guest rooms), 1st floor to 2nd floor (06 guest rooms at each floor) total -15 guest rooms only with effect from -----64-68-2021 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 04/08/2021 at New Delhi by.

(Dr. S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

1. The Commissioner, North MCD, Civic Centre, New Delhi

- 2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. ID No. 2021061213785 dated 12.06.21
- 3. The Manager, Sun Flower Inn Guest House 962, Gali Kumharan, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT Sun Flower Inn Guest House at 962, Gali 1. Name & address of the building Kumharan, Pahar Ganj, New Delhi Residential, Sub Division-A-1 2. Type of occupancy:-Gr. + 04 Upper floors (total 15 Guest rooms) Ground floor (Reception + 03 guest rooms), 1st floor to 2nd floor (06 guest rooms at each floor), 3rd floor & 4th floor (Owner residence) and having affidavit dated 26.11.2019 not to use any floor above third floor Renewal 3. Type of case:-No. F6/DFS/MS/GH/2018/NDZ/2172 dated 4. Details of previous FSC:-20/09/18. 5. Fire safety directives No.-N/A 27/07/21 6. Date of inspection:-Sh. Ravinder Singh (ADO/CC) 7. Name of the inspecting officer:-Sh. Rajinder Atwal DO / CD) 8. Name & designation of officer Mr. Sourabh From the building side:-2007 9. Year of construction:-ID No. 2021061213785 dated 12.06.21. 10. Applicant's letter No:-Old Case

				Old Case			
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR			
1.	Access to Building						
	1) Road width	N/A	02 mtr.	MR			
	2) Gate width	N/A	N/A	N/A			
	3)Width of internal road	N/A	N/A	N/A			
2.	Number, Width Type & Arra	angement of Ex	its				
2.	A. Number of staircases	· · · · · · · · · · · · · · · · · · ·					
	1. Upper floors	01 Nos.	01 Nos.	MR			
	2. Basements	N/A	N/A	N/A			
	B. Width of staircase						
	1. Upper floors	0.80 mtr.	1.0 mtr.	MR			
	2. Basements	N/A	N/A	N/A			
	C. Protection of exits						
	1. Fire check door	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance extended vide order dt. 29.06.2021			
1.	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous	01	01	MR			
* .	staircase to terrace						
	E. Width of corridor	N/A	N/A	N/A			
	F. Door size	1.0 mtr.	1.0 mtr.	MR			
3.	Compartmentation						
J.	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System						
	1) Basements	30 ACPH	N/A	N/A			
	2) Upper floors	Required as per G.N dated 27.05.19	Not provided	Last dt. 30.09.21 of compliance extended vide order 29.06.2021			



N/20

5.	Fire Extinguishers	2.0	N	10	Noc	MR O
	1) Total numbers		Nos.	Consultant Control	Nos. 3C & CO2	MR
	2) Types					MR
	3) ISI marking	Required		Provided		IVII
5.	First-Aid Hose Reel					1100
	1) Total number of eachfloor	01		01		MR
	2) Length of hose reel hose		mtr.	-	mtr.	MR
	3) Nozzle diameter	05 mm		05 mm		MR
7.	Automatic Fire Detection &	.0 \$ 9	Last dt. 30.09.21			
	1) Type of detectors CO type	Required as per G.N dated 27.05.19		Not provided		of compliance extended vide order dt. 29.06.2021
	2) Location of main panel	N/	A	N/A		N/A
	3) Location of repeater panel	N/		N/A		N/A
	4) Alternate source of power	N/A			/A	N/A
	5) Hooter's Location	N/A		N	/A	N/A
8.	MOEFA	N/		N	I/A	N/A
9.	Public Address System		quired		rovided	MR
10.	Automatic Sprinkler System					
10.	1) Basement	N/A		N	I/A	N/A
	2) Upper floors	N/		N/A		N/A
	3) Sprinkler above false		N/A		J/A	N/A
	ceiling					
11.	Internal Hydrants					
	1) Size of riser/down-comer	N	/A		I/A	N/A
	2) Number of hydrants per	N/A		N/A		N/A
	floor					
	3) Hose box	N/A		N/A		N/A
12.	Yard Hydrants					
	1) Total number of hydrants	N/A		N/A		N/A
	2) Hose box	N	/A	1	V/A	N/A
13.	Pumping Arrangement					
	1) Ground level		N/A		N/A	N/A
	a) Discharge of main pu	ımp	N/A		N/A	N/A
	b) Head of main pump		N/A		N/A	N/A
	c) Number of main pum	ıp	N/A		N/A	N/A
	d) Jockey pump out put		N/A		N/A	N/A
	e) Jockey pump head		N/A		N/A	N/A
	f) Stand by pump output		N/A		N/A	N/A N/A
	g) Stand by pump head		N/A N/A		N/A	N/A N/A
	h) Auto starting/Manua stopping			0	N/A	IN/A
	2) Terrace level					
	a) Discharge of pump		180 LPM		180 LPM	MR
	b) Head of pump		30 mtr.		30 mtr.	MR
	c) Power supply	Required		Provided	MR	
	d) Auto starting of pump		Required		Provided	MR
14.	Captive Water Storage for	r Fir	e Fighting			
11.	Under ground tank capacity		N/A		N/A	N/A



	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	2,500 ltr.	2,500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
10.	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Systems, if any:	stem for Prote	ection of special	N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2018/NDZ/2172 dated 20/09/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended for approval.

Signature of the inspecting officer

Name: - Rajinder Atwal

Designation: - DO (CD)

Signature of the Inspecting Officer

Name: Ravinder Singh

Designation: ADO (CC)

Do(co)

As apportued pour pertup for 1000