c-24

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2021 / 174

Dated: 9 / 8 /2021

FIRE SAFETY CERTIFICATE

Certified that the M/s Dilli Sweets located at Ground Floor, Property no. A-10, Sarai Pipal Thala, Extension, Adarsh Nagar, Delhi-110033 in a building comprised of ground + 02 upper floors owned/occupied by M/s Dilli Sweets have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules,2010 and verified by the officer concerned of Fire Service on 27.07.2021 in the presence of Sh. Anuj Gupta (Owner) and that the building/ premise is fit for occupancy Class Assembly (Restaurant) at ground floor only with effect from 9/8/2/ for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 9.18.12.1..... at New Delhi by

Director Ph-011-23414000

Copy to:-

- 1. M/s Dilli Sweets at A-16, Saria Pipal Thala, Extension, Adarsh Nagar, Delhi- 110033,
- 2. The Dy. Health Officer, (Civil Line Zone), North Delhi Muncipal Corporation 16, Rajpura Road, Delhi-110054.
- 3. The Joint Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049.

Conditions for the validity of Fire Safety Certificate:

- This Fire Safety Certificate is valid only for restaurant at ground floor for assembly occupancy only. In case of any violation, this FSC will be treated as null & void.
- 2 All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4 All the staff members must know the correct method of operation of firefighting system.
- The owner / occupier shall submit a declaration **every year** in **Form "K"** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of rule 37] along with a copy of this Certificate, **six months** prior to its expiry".

INSPECTION REPORT 1. Name & address of the building : M/s Dilli Sweets at A-16, Saria Pipal Thala, Extension, Adarsh Nagar, Delhi- 110033, Type of Occupancy 2. : Restaurant (Assembly) Restaurant running at Ground Floor only 3. Type of Case : New Case (G + 02 upper floor only) Second floor- Vacant Details of previous NOC 4. Third floor- Vacant : Nil 5. Fire Safety directives letter No : Nil Date of inspection : 27.07.2021 7. Name of the Inspecting Officers : ADO (RN) Name and designation of officers from the building side : Sh. Anuj Gupta (Owner) 9. Year of Construction/conversion : 2017 10. Applicant's letter No. : Online Portal I. D. no. 2021040912597 dated 14.04.2021 Plot Area-160sqm Minimum Standards on fire prevention and UBBL/NBC Provided at site Remarks fire safety U/R 33 requirements MR/NMR 1 Access to building Road width 06m 06m MR Gate width NA NA NA Width of internal road NA NA NA 2 Number, Width, Type & Arrangement of Exits (Restaurant at GF only) a. Number of staircases NA NA NA Upper Floors NA NA NA Basements b. Width of staircases NA NA NA Upper Floors NA NA NA Basements c. Protection of exits NA NA NA Fire check door NA NA Pressurization NA d. No. of continuous staircases to terrace NA NA NA e. Width of Corridor NA NA NA f. Door Size Denist 1.50m Las MR 2.0m &1.50m 3 Compartmentation. Fire check door NA NA NA NA NA NA Sealing of electrical shafts NA NA NA Fire Rating of shaft door NA NA Water Curtain NA NA NA NA Fire Dampers 4 Smoke Management System. Basements 12 a/c per hour NA NA Upper floors 12 a/c per hour Natural Ventilation MR 5 Fire Extinguishers Total numbers 05nos 06nos MR ABC/Co2 ABC-4 /Co2-02 MR Types Yes Yes ISI marking MR 6 First-Aid Hose Reels.

	Total numbers on each floor	01	Provided	MR		
	Length of hose reel hose	30m	Provided	MR		
	Nozzle diameter	5mm	Provided	MR		
7 A1	utomatic fire detection and alarming system.					
1		NA	Provided	NA		
	Type of detectors	NA	NA	NA		
	Location of Main Panel	NA	NA	NA		
	Location of Repeater Panel	NA	NA	NA		
	Alternate source of power		NA	NA		
	Hooters' Location	NA				
-	OEFA	Required NA	Provided NA	MR		
	Public Address System.					
10 Au	Automatic Sprinkler System. NA NA NA					
	Basement	NA	NA	NA NA		
	Upper Floor(Ground floor)	NA		·		
	Sprinkler above false ceiling	NA	NA	NA		
11 In	ternal Hydrants			MD		
	Size of riser/down-comer	100mm	Provided Provided	MR MR		
	Number of hydrants per floor	01	Provided	MR		
10 **	Hose Box And Made and Control of the Control	01	Flovided	TVIIC		
12 Y	ard Hydrants.	NA	NA	NA		
	Total number of hydrants	NA	NA	NA		
	Hose Box	IVA	112			
13 P	Pumping Arrangements.					
	Ground Level			NI/A		
	Discharge of main Pump	N/A	N/A	N/A		
	➤ Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	> Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A N/A	N/A N/A	N/A N/A		
	Standby Pump out put		N/A	N/A		
	Standby Pump Head	N/A		A.M. J. Santa		
~	> Auto Starting/ Manual stopping	N/A	N/A	N/A		
	Pump House Access	N/A	N/A	N/A		
	Terrace level					
	Discharge of pump	450lpm	Provided	MR		
	➤ Head of the pump	40m	Provided	MR		
		Required	Provided	MR		
	Power SupplyAuto Starting of pump	Required	Provided	MR		
		,				
14	Captive Water Storage for fire fighting.	NA	NA	NA		
	Underground tank capacity	NA	NA	NA		
	> Draw-off connection	NA NA	NA NA	NA		
	> Fire service inlet	NA	NA	NA		
	> Access to tank	20,000ltr	20,000ltr	MR		
	Overhead Tank capacity			MR		
	Exit Signage.	Required	Provided	IVIK		
16	Provision of Lifts. Pressurization of Lift Shaft	N/A	N/A	N/A		

50							
	•	Pressurization of Lift lobby	N/A	N/A	N/A		
	•	Communication In lift Car	NA	NA	NA		
	•	Fireman's Grounding Switch	NA	NA	NA		
	•	Lift Signage	NA	NA	NA		
17	Standl	y power supply	N/A	N/A	N/A		
18	Refuge	Refuge Area.					
	>	Total Area	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
19	Fire Control Room						
		Detector System Panel	N/A	N/A	N/A		
		Flow Switch Panel	N/A	N/A	N/A		
		PA System Panel	N/A	N/A	N/A		
		Batter backup	. N/A	N/A	N/A		
		Building Floor Plans	N/A	N/A	N/A		
20		Fire Protection Systems for ion of special Risks, if any:	NA	NA	NA		

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection. The observations/ shortcomings issued and communicated vide this department letter of even no. 669 dated 15.07.2020 have been compiled by the management.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name: - C.L. Meena Designation: - ADO/RN

Ground Flor area as per mansion in MHA Portial see c/21 is 160 sq. mfr. No. of person is 160/118 that is equal 88 ferson.