C-105

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2021/ 293

## FIRE SAFETY CERTIFICATE

Certified that the "J" Joy Guest House located at 3<sup>rd</sup> floor, 16/67-68, Faiz Road, Karol Bagh, New Delhi comprised of Basement + Ground + 04 Upper floors, Basement & 1<sup>ST</sup> floor is vacant & locked, Ground floor (Bank), 2<sup>nd</sup> floor (Studio), 3<sup>rd</sup> floor (Reception + 16 guest rooms) and 4<sup>th</sup> floor (staff kitchen + 01 store room), total 16 guest rooms owned/occupied by "J" Joy Guest House was earlier granted FSC by this department vide letter No. F6/DFS/MS/GH/NDZ/2018/976 dated 09/05/18. Now The premise was reinspected by the officer concerned of this department on 02/08/21 in the presence of Mr. Bablu and found that the said guest house building having affidavit dated 28.02.2020 regarding not to use any floor above third floor has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1, 3rd floor (Reception + 16 guest rooms) total 16 guest rooms. with effect from .6.1.8.1.2.1..... for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued -6-8-12-1---at New Delhi by.

(Dr. S.K.Tomar) Dy. Chief Fire Officer Delhi Fire Service

## Copy to:-

1. The Commissioner, North MCD, Civic Centre, New Delhi

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id. 2021042213143 Nil dated 22/04/21

3. The Manager,

"J" Joy Guest House 3rd floor, 16/67-68, Faiz Road, Karol Bagh, New Delhi.

Condition for the validity of fire safety certificate

1. This clearance/ FSC shall stand canceled if guest house owner/occupier fails to comply all other conditions mentioned in the gazette notification dated 27.05.2019 & clarification issued on dated 29.06.2021 latest by 30.09.2021

2. All the fire safety arrangements provided therein shall be maintained in good working conditions at

all times.

3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

**INSPECTION REPORT** 

1. Name & address of the building: "J" Joy Guest House at 16/67-68,2<sup>nd</sup> floor, Faiz Road, Karol Bagh, New Delhi - 05.

2. Type of occupancy:-

B+ Gr. + 04 Upper floors (total 16 Guest rooms)

Basement & 1<sup>ST</sup> floor is vacant & locked, Ground floor
(Bank), 2<sup>nd</sup> floor (Studio), 3<sup>rd</sup> floor (Reception + 16
guest rooms) and having affidavit dated 28.02.2020 regarding not to use any floor above third floor

3. Type of case:-

No. F6/DFS/MS/GH/NDZ/2018/976 dated 4. Details of previous NOC:-09/05/18.

5. Fire safety directives No.-N/A 02/08/21 6. Date of inspection:-

Sh. Ravinder Singh (ADO/CC) 7. Name of the inspecting officer:-Sh. Rajinder Atwal (DO/CD)

8. Name & designation of officer From the building side:-

Mr. Babbar 2008 9. Year of construction:-

Online id. 2021042213143 Nil dated 22/04/21 10. Applicant's letter No:-

10.	Applicant's letter No:-	Offinite fair 2022		Old Case
.No.		Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR
	Access to Building			NI/A
	1) Road width	N/A	06 mtr.	N/A
	2) Gate width	N/A	N/A	N/A
	3) Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arra	angement of Ex	its	
4.	A. Number of staircases			1.00
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	01 Nos.	01 Nos.	MR
	B. Width of staircase			- m ( 11
	1. Upper floors	1.25 mtr.	1.22 to 1.30 Mtr.	MR( old
	п. Оррег			case)
	2. Basements	N/A	N/A	N/A N/A
	C. Protection of exits	N/A	N/A	Last dt.
	1. Fire check door	Required as per G.N dated 27.05.19		30.09.21 of compliance extended vide order dt 29.06.2021
	2. Pressurization	N/A	N/A	N/A
-	D. No. of continuous staircase to terrace	01	01	MR
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	01 mtr.	01 mtr.	MR
2	Compartmentation			
3.	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts		N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
	Smoke Management System			
4.	1) Basements	N/A	N/A	N/A
	2) Upper floors	12 ACPH	Natural/exhaust fa	in MR



		MMI			
5.	Fire Extinguishers				
	1) Total numbers	08	10	MR	
	2) Types	ABC & CO2	ABC & CO2	MR	
	3) ISI marking	Required	Provided	MR	
6.	First-Aid Hose Reel				
=	1) Total number of each	01	01	MR	
	floor				
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR	
	3) Nozzle diameter	05 mm	05 mm	MR	
7.	Automatic Fire Detection &				
	1) Type of detectors CO type detector	Required	Provided	MR	
	2) Location of main panel	At third floor	Provided	MR	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	Required	Provided	MR	
	5) Hooter's Location	At staircase	Provided	MR	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System	Required	Provided	MR	
10.	Automatic Sprinkler System				
10.	1) Basement	N/A	N/A	N/A	
	2) Upper floors	N/A	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11.	Internal Hydrants				
11.	1) Size of riser/down-comer	N/A	N/A	N/A	
	2) Number of hydrants per	N/A	N/A	N/A	
	floor	1 1/1 1		8	
	3) Hose box	N/A	N/A	N/A	
12.	Yard Hydrants	1.1.1.2			
14.	1) Total number of hydrants	N/A	N/A	N/A	
	2) Hose box	N/A	N/A	N/A	
13.	Pumping Arrangement				
13.	1) Ground level	N/A	N/A	N/A	
	a) Discharge of main pump	N/A	N/A	N/A	
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pump		N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output		N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual stopping	N/A	N/A	N/A	
	2) Terrace level				
	a) Discharge of pump	450 LPM	450 LPM	MR	
				11	
			30 mtr.	MR	
	b) Head of pump c) Power supply	30 mtr. Required	30 mtr. Provided	MR MR	



14.	Captive Water Storage for F	ire Fighting		
	Under ground tank     capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	Required	Provided	MR
	d) Over head tank capacity	5000 ltr.	5000 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			NA

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2018/976 dated 09/05/18, renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended upto third floor only.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name: - Rajinder Atwal

Designation: - DO (CD)

Name: - Ravinder Singh Designation: - ADO (CC)

Resuser and Seportion Pleaser,