

C-37

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**

No. F.6/DFS/MS/EH/2021/SZ/ 170

Dated: 5 / 8 /2021

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of **M/s SLY GRANNY CAFÉ (A Unit of Azure Hospitality Pvt. Ltd.)**, located at **Shop No S-14, 2nd floor, Select City Walk, Saket, New Delhi- 110017** owner occupied by **(A Unit of Azure Hospitality Pvt. Ltd.)** have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 29/07/2021 in the presence of Sh. Rakshak Singh (Manager) and that the premises is fit for occupancy class **“Group-D Assembly” (Restaurant running at S-14, 2nd floor only)** with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 5 / 8 /2021 at New Delhi by


(ATUL GARG)
DIRECTOR


Copy to: -

1. The Dy. Health Officer, SDMC, Public Health Department, Green Park, Aurobindo Marg, New Delhi – 110016. (Ref. MHA Portal ID 2021061914023 dated 01.07.2021)
2. The Joint Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049.
3. M/s SLY GRANNY CAFÉ (Azure Hospitality Pvt. Ltd.), located at Shop no S-14, 2nd floor, Select City Walk, Saket, New Delhi- 110017.

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire-fighting system.
4. The owner/occupier shall submit a declaration every year in Form ‘K’ provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. “The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form ‘J’ [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.”

INSPECTION REPORT

1. Name & address of the building : M/s SLY GRANNY CAFÉ (Azure Hospitality Pvt. Ltd.)
S-14 2nd floor, Select City Walk, Saket, New Delhi- 17.
2. Type of Occupancy : Assembly (second floor only)
3. Type of Case : New Case
4. Details of previous NOC : Nil
5. Fire Safety directives letter No : Nil
6. Date of inspection : 29.07.2021
7. Name of the Inspecting Officers : ADO (BCP)
8. Name and designation of officers
9. from the building side : Sh. Rakshak Singh (Manager)
9. Year of Construction/conversion : 2008
10. Applicant's letter No. : MHA Portal ID 2021061914023 dated 01.07.2021

	Minimum Standards on fire prevention and fire safety U/R 33	UBBL/NBC-2016 requirements	Provided at site	Remarks MR/NMR
1	Access to building (Select City Walk Mall - F.6/DFS/MS/Mall/2021SZ/171 Dt. 15/03/2021)			
	Road width	09m	12m approx...	MR
	Gate width	NA	NA	NA
	Width of internal road	NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	Provided & Maintained by Mall		
	Upper Floors	NA	Restt. at Upper GF	NA
	Basements	N/A	As above	N/A
	b. Width of staircases	Provided & Maintained by Mall		
	Upper Floors	NA	Restt. at Upper GF	NA
	Basements	N/A	As above	N/A
	c. Protection of exits	Provided & Maintained by Mall		
	Fire check door	N/A	N/A	N/A
	Pressurization	N/A	N/A	N/A
	d. No. of continuous staircases to terrace	Required	One	MR
	e. Width of Corridor	N/A	N/A	N/A
	f. Door Size	2 exits (1.50 m x 2)	Provided	MR
3	Compartmentation.			
	Fire check door	NA	NA	NA
	Sealing of electrical shafts	NA	NA	NA
	Fire Rating of shaft door	NA	NA	NA
	Water Curtain	NA	NA	NA
	Fire Dampers	NA	NA	NA
4	Smoke Management System.			
	Basements	30 a/c per hour	NA	NA
	Upper floors (Ground Floor)	12 a/c per hour	Provided	MR
5	Fire Extinguishers			
	Provided & Maintained by Mall			
	Total numbers	04nos	5nos	MR

	Types ISI marking	ABC/Co2	ABC-4 Co2-1	MR
		Yes	Yes	MR
6	First-Aid Hose Reels.Common with Mall			
	Total numbers on each floor	01	Provided	MR
	Length of hose reel hose	30m	Provided	MR
	Nozzle diameter	5mm	Provided	MR
7	Automatic fire detection and alarming system.			
	Type of detectors	NA	NA	NA
	Location of Main Panel	NA	NA	NA
	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	NA	NA	NA
	Hooters' Location	NA	NA	NA
8	MOEFA	Required	Provided	MR
9	Public Address System.	NA	NA	NA
10	Automatic Sprinkler System.			
	Basement	NA	NA	NA
	Upper Floor(Ground floor)	NA	NA	NA
	Sprinkler above false ceiling	NA	NA	NA
11	Internal Hydrants Provided & Maintained by Mall			
	Size of riser/down-comer	100 mm	Provided	MR
	Number of hydrants per floor	01	Provided	MR
	Hose Box	01	Provided	MR
12	Yard Hydrants.			
	Total number of hydrants	NA	NA	NA
	Hose Box	NA	NA	NA
13	Pumping Arrangements.Common with Mall			
	Provided & Maintained by Mall			
	Discharge of main Pump	4500 lpm	4500 lpm	MR
	Head of Main pump	88m	88m	MR
	Number of main pumps	02	02	MR
	Jockey Pump out put	180 lpm	180 lpm	MR
	Jockey pump head	88m	88m	MR
	Standby Pump out put	4500 lpm	4500 lpm	MR
	Standby Pump Head	88m	88m	MR
	Auto Starting/ Manual stopping	Required	Provided	MR
	Pump House Access	Required	Provided	MR
	Terrace level			
	Discharge of pump			
	Head of the pump	N/A	N/A	N/A
	Power Supply	N/A	N/A	N/A
	Auto Starting of pump	N/A	N/A	N/A
		N/A	N/A	N/A
14	Captive Water Storage for fire fighting.			
	Common with Mall			

	Underground tank capacity	5,00,000ltr.	Provided	MR
	Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	30,000 ltr	Provided	MR
5	Exit Signage.	Required	Provided	MR
6	Provision of Lifts.			
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	NA	NA	NA
	Fireman's Grounding Switch	NA	NA	NA
	Lift Signage	NA	NA	NA
7	Standby power supply	N/A	N/A	N/A
8	Refuge Area.			
	Total Area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
9	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
0	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 315 dated 21/12/2020.

Keeping in view of the substantially satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 (3) of the Delhi Fire Service Rules, 2010

Accordingly DFA is put up for approval and signature please.

RK
30/11/20

Signature of the Inspecting Officer
Name: - Rajesh Kumar
Designation: - ADO/BCP

DO (SD)

DO
30/10/20

DeFO (SD)

DO
30/11/20

C.R.A. (an) New delhi