c-60

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2021/ 296

Dated: 10/8/21

## FIRE SAFETY CERTIFICATE

Certified that M/s. Hotel Laxmi Palace located at 6/65, WEA, Gurudwara Road, Karol Bagh, New Delhi- 110005, comprised of basement, ground plus four upper floors, using basement as hall/storage, ground floor as reception & shops, first, second & third floor each having 09 guest rooms respectively (total 27 guest rooms) and a staff kitchen with one staff room on terrace floor was granted FSC by this department vide letter No. F.6/DFS/MS/GH/SZ/2018/845 dated 25.04.2018. The premises was re-inspected by the officer concerned of this department on 29.07.2021 in presence of Mr. Murli Mani (Owner) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for basement (storage), ground floor (reception), first, second & third floor each having 09 guest rooms respectively (total 27 guest rooms only) with effect from 10/2/2/2 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued on 10/8/2/ at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to:-

- 1. Sh. Murli Mani (Owner), M/s. Hotel Laxmi Palace, 6/65, WEA, Gurudwara Road, Karol Bagh, New Delhi-110005.
- 2. The Joint. C.P. (Lic.), Police Station, Defence Colony, 1<sup>st</sup> floor, New Delhi.

## Following Fire Safety Directives must be adhered to: -

- The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.

1. Name & address of the building : M/s. Hotel Laxmi Palace, 6/65, WEA, Gurudwara Road, Karol Bagh, New Delhi- 110005. 2. Type of Occupancy : Lodging House 3. Type of Case : Renewal 4. Details of previous NOC : F.6/DFS/MS/GH/SZ/2018/845 dated 25.04.2018. 5. Fire Safety directives letter No : Nil 6. Date of inspection : 29.07.2021 7. Name of the Inspecting Officers : P.V. Rathee, Asstt. Div. Officer (SRD) 8. Name and designation of officers from the building side : Mr. Murli Mani (owner) 9. Year of Construction : 1993 10. Applicant's letter No. : Online Application Id 2021071015020 dated 16.07.2021 The said guest house is comprised of basement, ground plus four upper floors. S. Minimum Standards on fire Fire safety Provided at site Remarks No. prevention and fire safety U/R 33 arrangements as per MR/NMR FSC dt. 25.04.2018 1 Access to building Road width 06 mts Provided MR Gate width 4.5 mts Directly accessible MR Width of internal road N/A N/A N/A Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 01 Old Case MR being old case Basements 01 Old Case MR being old case b. Width of staircases Upper Floors 1.25 mts MR 1.25 mts Basements 1.16 mts MR being old case 1.25 mts c. Protection of exits Fire check door date of compliance has been Required Not Provided extended up to 30.09.2021 Pressurization N/A N/A N/A e. No. of continuous staircases to terrace 01 01 MR g. Width of Corridor Old case 1.17 mts MR h. Door Size Old case 0.87 mts MR being old case Compartmentation. Fire check door Required date of compliance has been Not Provided Sealing of electrical shafts extended up to 30.09.2021 N/A Sealed Fire Rating of shaft door N/A N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System. Basements 30 a/c per hour Exhaust Fan provided MR Upper floor 12 a/c per hour Exhaust Fan provided MR Fire Extinguishers Total numbers 12 Provided MR Types CO<sub>2</sub>, ABC, WCO<sub>2</sub> Provided MR ISI marked IS marking Provided MR

3

4

5

	Total numbers on each moor	UI	Flovided	1	IVIN		
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided		MR		
	Nozzle diameter	5 mm	Provided		MR		
7	Automatic fire detection and alarming system.						
	Type of detectors	Carbon Monoxide	Not Provided	Not Provided date of co			
	Location of Main Panel	Required	NOT PROVIDED		ompliance has been d up to 30.09.2021		
	• Location of Repeater Panel	N/A	N/A		N/A		
	Alternate source of power	Required	D.G. set 25 KVA	1.	MR		
	Hooters' Location	N/A	N/A		N/A		
8	MOEFA	Required	Provided		MR		
9	Public Address System.	Required	Provided		MR		
10							
	• Basement	Required	Provided	d	MR		
	Upper Floor	N/A	N/A		N/A		
	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A		N/A		
11	Internal Hydrants						
	Size of riser/down-comer	N/A	N/A		N/A		
	<ul> <li>Number of hydrants per floor</li> </ul>	N/A	N/A		N/A		
	Hose Box	N/A	N/A		N/A		
12	Yard Hydrants.						
	<ul> <li>Total number of hydrants</li> </ul>	N/A	N/A		N/A		
	Hose Box	N/A	N/A		N/A		
13	13 Pumping Arrangements.						
	Ground Level						
	Discharge of main Pump	N/A	N/A		N/A		
	Head of Main pump	N/A	N/A		N/A		
	<ul><li>Number of main pumps</li><li>Jockey Pump out put</li></ul>	N/A	N/A		N/A		
		N/A	N/A		N/A		
	<ul><li>Jockey pump head</li><li>Standby Pump out put</li></ul>	N/A	N/A	Ł.	N/A		
	Standby Pump Head	N/A	N/A		N/A		
	Auto Starting/ Manual stopping	N/A	N/A		N/A		
	Pump House Access	N/A	N/A		N/A		
	r ump House Access	N/A	N/A		N/A		
	Terrace level				NO CO TO THE REAL PROPERTY.		
	Discharge of pump	450 LPM	Provided		MR		
	Head of the pump	30 mts	Provided		MR		
	Power Supply	Required	Provided		MR		
	Auto Starting of pump	N/A	N/A		N/A		
14	Captive Water Storage for fire fighting.						
	Underground tank capacity	N/A	N/A		N/A		
	> Draw-off connection	N/A	N/A	Zaka i	N/A		
	Fire service inlet	N/A	Provided		MR		
	Access to tank	N/A	N/A		N/A		
	Overhead Tank capacity	7,000 lts	7,000 lts		MR		

		N/35						
16	Provision of Lifts.	rovision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A				
	Pressurization of Lift lobby	N/A	N/A	N/A				
1	Communication In lift Car	Required	Provided	MR				
	• Fireman's Grounding Switch	Required	Provided	MR				
	Lift Signage	Required	Provided	MR				
17	Standby power supply	Required	Provided	MR				
18	Refuge Area.							
	> Total Area	N/A	N/A	N/A				
	Location	N/A	N/A	N/A				
19	Fire Control Room	Control Room						
-	Detector System Panel	N/A	N/A	N/A				
	• Flow Switch Panel	N/A	N/A	N/A				
	PA System Panel	N/A	N/A	N/A				
	Battery backup	Required	Provided	MR				
	Building Floor Plans	N/A	N/A	N/A				
20	Special Fire Protection Systems for	N/A	N/A	N/A				
	Protection of special Risks, if any:			11/11				

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09 .2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/GH/SZ/2018/845 dated 25.04.2018, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer P.V. Rathee

Asstt. Div. Officer (SRD)

m/02/08/2021

cho (12)

F.t. p-lease.