

C-27

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001



No. F.6 /DFS /MS /2021/ S/W2/609

Dated: 12/8 /2021

FIRE SAFETY CERTIFICATE

Certified that the **Sarvodaya Bal Vidyalaya (I.D-1207012)** located at Timar Pur, Delhi-110054 comprised of **Single Block (Ground + 03upper Floor and One Hall Only)** owned/occupied by **Sarvodaya Bal Vidyalaya** was issued Fire Safety Certificated vide this office letter no. **F-6/DFS/MS/School/2013/WZ/792** dated **26.08.2013**. (**02 blocks, G+03 & Ground floor only**) the premise was re-inspected by the officer concerned of this department on **04.08.2021** in the presence of **Dr. P.K. Mundra (Principal)** and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under **Educational "Group B"** with effect from 12/8/21 for a period of **three years** in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on 12/8/21 at New Delhi by


(Dharampal Bhardwaj)
Dy.Chief Fire Officer
Ph:-011-25156707


Copy to : -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.
2. The Principal, Sarvodaya Bal Vidyalaya, Timar Pur, Delhi-110054.

Conditions for the validity of Fire Safety Certificate:

- 1 All the means of escape/entry/exit shall be kept free from any obstruction.
- 2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3 All the staff members must know the correct method of operation of firefighting system.
- 4 The owner / occupier shall submit a declaration **every year** in **Form "K"** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <http://delhi.gov.in/wps/wcm/connect/doit/fire/FIRE/Home/Forms>.
- 5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBI.-2016), if any.
- 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of rule 37] along with a copy of this Certificate, **six months** prior to its expiry".

INSPECTION REPORT

1. Name & address of the building : Sarvodaya Bal Vidyalaya, Timar Pur, Delhi-110054. (I.D. 1207012)
 2. Type of Occupancy : Educational
 3. Type of Case : Renewal (Ground + 03 upper floors & One Hall)
 4. Details of previous NOC : F6/DFS/MS/School/2013/WZ/792 Dated:26.08.2013 (02 blocks, G+03 & Ground floor only)
 5. Fire Safety directives letter No : Director of Education Circular dated 01.03.2011
 6. Date of inspection : 04.08.2021
 7. Name of the Inspecting Officers : ADO (RN)
 8. Name and designation of officers from the building side : Dr. P.K. Mundra (Principal)
 9. Year of Construction : 1940
 10. Applicant's letter No. : Online E-Mail I.D dated: 27.07.2021

	Minimum Standards on fire prevention and fire safety U/R 33	Director of Education	Provided at site	Remarks MR/NMR
--	---	-----------------------	------------------	----------------

1	Access to building			
	<ul style="list-style-type: none"> Road width 	06m	09m	MR
	<ul style="list-style-type: none"> Gate width Width of internal road 	4.5m	06m	MR
		NA	NA	NA

2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> Upper Floors Basements 	01	01	MR
	b. Width of staircases			
	<ul style="list-style-type: none"> Upper Floors Basements 	1.50m	2.10m	MR
	c. Protection of exits			
	<ul style="list-style-type: none"> Fire check door Pressurization 	NA	NA	NA
	d. No. of continuous staircases to terrace	NA	NA	NA
	e. Width of Corridor	01	01	MR
	f. Door Size	1.5m	3.63m	MR

3	Compartmentation.			
	<ul style="list-style-type: none"> Fire check door 	1 m	1.03m double door	MR
	<ul style="list-style-type: none"> Sealing of electrical shafts 	NA	NA	NA
	<ul style="list-style-type: none"> Fire Rating of shaft door 	NA	NA	NA
	<ul style="list-style-type: none"> Water Curtain 	NA	NA	NA
	<ul style="list-style-type: none"> Fire Dampers 	NA	NA	NA

4	Smoke Management System.			
	<ul style="list-style-type: none"> Basements 	12 a/c per hour	NA	NA
	<ul style="list-style-type: none"> Upper floors 	12 a/c per hour	Natural Ventilation	MR

5	Fire Extinguishers			
	<ul style="list-style-type: none"> Total numbers 	23nos	38nos	MR
	<ul style="list-style-type: none"> Types 	ABC/Co2	ABC-28/Co2-10	MR
	<ul style="list-style-type: none"> ISI marking 	ISI Marked	Provided	MR

6	First-Aid Hose Reels.			
	• Total numbers on each floor	01	01	MR
	• Length of hose reel hose	30m	30m	MR
	• Nozzle diameter	5mm	5mm	MR
7	Automatic fire detection and alarming system.			
	• Type of detectors	NA	NA	NA
	• Location of Main Panel	NA	NA	NA
	• Location of Repeater Panel	NA	NA	NA
	• Alternate source of power	NA	NA	NA
	• Hooters' Location	NA	NA	NA
8	MOEFA			
9	Public Address System.			
10	Automatic Sprinkler System.			
	• Basement	NA	NA	NA
	• Upper Floor	NA	NA	NA
	• Sprinkler above false ceiling	NA	NA	NA
11	Internal Hydrants			
	• Size of riser/down-comer	NA	100mm	NA
	• Number of hydrants per floor	NA	01	NA
	• Hose Box	NA	01	NA
12	Yard Hydrants.			
	• Total number of hydrants	NA	NA	NA
	• Hose Box	NA	NA	NA
13	Pumping Arrangements.			
	• Ground Level			
	➤ Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey Pump out put	NA	NA	NA
	➤ Jockey pump head	NA	NA	NA
	➤ Standby Pump out put	NA	NA	NA
	➤ Standby Pump Head	N/A	N/A	N/A
	➤ Auto Starting/ Manual stopping	N/A	N/A	N/A
	➤ Pump House Access	N/A	N/A	N/A
	• Terrace level			
	➤ Discharge of pump	450lpm	450lpm	MR
	➤ Head of the pump	40m	40m	MR
	➤ Power Supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for fire fighting.			
	• Underground tank capacity	NA	NA	NA
	➤ Draw-off connection	NA	NA	NA
	➤ Fire service inlet	NA	NA	NA
	➤ Access to tank	NA	NA	NA

	<ul style="list-style-type: none"> Overhead Tank capacity 	10,000ltr	10,000ltr.	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	<ul style="list-style-type: none"> Pressurization of Lift Shaft 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Pressurization of Lift lobby 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Communication In lift Car 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Fireman's Grounding Switch 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Lift Signage 	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire Control Room			
	<ul style="list-style-type: none"> Detector System Panel 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Flow Switch Panel 	N/A	N/A	N/A
	<ul style="list-style-type: none"> PA System Panel 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Batter backup 	N/A	N/A	N/A
	<ul style="list-style-type: none"> Building Floor Plans 	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

Note:- One hall having area 200m² and two exits doors width of 1.70m & 1.78m provided. (Multipurpose without Fixed seating)

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 2166 dated 18.05.2018.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in Director of Education issued vide letter of even no.792 dated 26.08.2013 (02 blocks, G+03 & Ground floor only) renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended

DO (W)

05/08/2021

Dy CEO (W2)

9/8/2021

Signature of the Inspecting Officer
 Name :- C.L. Meena
 Designation :- ADO/RN

~~ADO/RN~~

As approved, F.T. letter is put up for your signature

Dy CEO (W2)

11/8/2021

10/08/2021