## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2021/ 298

Dated: 11/8/2/

## FIRE SAFETY CERTIFICATE

Certified that M/s. Hotel Marble Arch located at 8/6, W.E.A, Pusa Lane, Karol Bagh, New Delhi- 110005 comprised of basement, ground plus two upper floors, using basement as hall, ground floor as reception, pantry, offices & 05 rooms for personal use, first & second floor each having 11 guest rooms respectively (total 22 guest rooms) was granted FSC by this department vide letter No. F.6/DFS/MS/GH/SZ/2018/1183 dated 23.05.2018. The premises was re-inspected by the officer concerned of this department on 02.08.2021 in presence of Sh. Dashrath Goswami, manager of the guest house and found that the guest house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for basement (storage), ground floor (reception, office and 05 rooms for personal use), first and second floor each having 11 guest rooms respectively (total 22 guest rooms only) with effect from III guest for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed back side.

Issued 11/8/2/ at New Delhi by.

(Sunil Chaudhary)

Dy. Chief Fire Officer (SZ)

OC. Delhi Fire Service

Copy to:-

- 1. The Owner, M/s. Hotel Marble Arch, 8/6, W.E.A, Pusa Lane, Karol Bagh, New Delhi-110005.
- 2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

Following Fire Safety Directives must be adhered to: -

- 1. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09.2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void
- 2. No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/Occupier
- 3. All the means of escape shall be kept free of all type of obstruction all the time.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 6. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 7. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 8. All comments / directions of licensing department shall always be permitted and followed.
- 9. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 10. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 11. Basement shall be used as per BBL.
- 12. No temporary shed is allowed on terrace.
- 13. The Fire Safety Certificate is only for Guest Rooms.

## **INSPECTION REPORT**

1. Name & address of the building

: M/s. Hotel Marble Arch, 8/6, W.E.A, Pusa Lane, Karol

Bagh, New Delhi- 05

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: F.6/DFS/MS/GH/SZ/2018/1183 dated 23.05.2018.

5. Fire Safety directives letter No

: Nil

6. Date of inspection

: 02.08.2021

7. Name of the Inspecting Officers

: P.V. Rathee, Asstt. Div. Officer (SRD)

8. Name and designation of officers

from the building side

: Sh. Dashrath Goswami, manger

9. Year of Construction

: 2009-10

10. Applicant's letter No.

: Online Application Id 2021071315113 dated 22.07.2021

The said guest house is comprised of basement, ground plus two upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Fire safet arrangements FSC dt. 23.05	as per		at sit	Remarks MR/NMR	
1	Access to building						
	Road width	06 mts	06 mts			MR	
	Gate width		D	irectly accessi	ble	MR	
	<ul> <li>Width of internal road</li> </ul>	N/A	N/A			N/A	
2 Number, Width, Type & Arrangement of Exits							
	a. Number of staircases	-		-		-	
	• Upper Floors	02		02		MR	
	Basements	02		02		MR	
	b. Width of staircases	-		1.48, 0.92 mts (iron made) 1.42, 1.60 mts.		-	
	• Upper Floors	Old case	1.48, 0.			MR being old case	
	Basements	Old case	1.4			MR being old case	
	c. Protection of exits		-		_		
	• Fire check door	Required	Not	Provided		of compliance has been ended up to 30.09.2021	
	• Pressurization	N/A		N/A		N/A	
	e. No. of continuous staircases to terrace	01	02		MR		
	g. Width of Corridor	N/A		N/A		N/A	
- P	h. Door Size	Old case		0.80 mts		MR being old case	
3	Compartmentation.						
	Fire check door	Required	Not	Provided		of compliance has been ended up to 30.09.2021	
	Sealing of electrical shafts	N/A		Sealed	- CALL		
	• Fire Rating of shaft door	N/A	N/A		N/A		
	Water Curtain	N/A		N/A		N/A	
	• Fire Dampers	N/A		N/A		N/A	
4	Smoke Management System.						
	Basements	30 a/c per hou		haust fan provi		MR	
	• Upper floors	12 a/c per hou	ur Na	tural Ventilat	ion	MR	

	<ul><li>Types</li></ul>	CO <sub>2</sub> , ABC, WCO <sub>2</sub>	Provided	i	MR
***************************************	• IS marking	ISI marked	Provided		MR ·
6	First-Aid Hose Reels.		*		
	Total numbers on each floor	01	Provide	d	MR
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provide	d	MR
	Nozzle diameter	5 mm	Provide	d	MR
7	Automatic fire detection and alarming	system.			
	Type of detectors	Carbon Monoxide	Not Provided	extende	compliance has been ed up to 30.09.2021
	<ul> <li>Location of Main Panel</li> </ul>	Required	Not Provided	1 2	compliance has been ed up to 30.09.2021
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A		N/A
	Alternate source of power	Required	D.G. set 200 KVA		MR
	<ul> <li>Hooters' Location</li> </ul>	N/A	N/A		N/A
8	MOEFA	Required	Provided		MR
9	Public Address System.	Required	Provided		MR
10	Automatic Sprinkler System.				
	Basement	Required	Provide	d	MR
	Upper Floor	N/A	N/A		N/A
	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A		N/A
1.1	Internal Hydrants				
	Size of riser/down-comer	N/A	N/A		N/A
	<ul> <li>Number of hydrants per floor</li> </ul>	N/A	N/A		N/A
	Hose Box	N/A	N/A		N/A
12	Yard Hydrants.		2		
	Total number of hydrants	N/A	N/A		N/A
	Hose Box	N/A	N/A		N/A
13	Pumping Arrangements.		7		
	Ground Level		;;		NO 305 NO
	Discharge of main Pump	N/A	N/A		N/A
	Head of Main pump	N/A	N/A		N/A
	Number of main pumps	N/A	N/A		N/A
	Jockey Pump out put	N/A	N/A		N/A
	Jockey pump head	N/A	N/A		N/A
	Standby Pump out put	N/A	N/A		N/A
	Standby Pump Head	N/A	N/A		N/A
	Auto Starting/ Manual stopping	N/A	N/A		N/A
	Pump House Access	N/A	N/A		N/A
The same of the sa	Terrace level		000 MA ADM 400 MG 600 CD		mail this talk part time may find \$-14
	<ul> <li>Discharge of pump</li> </ul>	900 LPM	Provide		MR
	Head of the pump	30 mts	Provide		MR
	Power Supply	Required	Provide		MR
	Auto Starting of pump	Required	Provide	d	MR
14	Captive Water Storage for fire fighting	g.			
	Underground tank capacity	N/A	N/A		N/A
	Draw-off connection	N/A	N/A		N/A
	Fire service inlet	N/A	N/A		N/A
	Access to tank	N/A	N/A		N/A
	Overhead Tank capacity	10,000 lts	10,000 1	ts	MR
15	Exit Signage.	Required	Provide	d	MR
16	Provision of Lifts.				

			N 122						
		Pressurization of Lift Shaft	N/A	N/A	N/A				
	•	Pressurization of Lift lobby	N/A	N/A	N/A				
		Communication In lift Car	Required	Provided	MR				
		Fireman's Grounding Switch	Required	Provided	MR				
	9	Lift Signage	Required	Provided	MR				
17	Stan	dby power supply	Required	Provided	MR				
18 Refuge Area.									
	7	Total Area	N/A	N/A	N/A				
		Location	N/A	N/A	N/A				
19	Fire	re Control Room							
		Detector System Panel	N/A	N/A	N/A				
		<ul> <li>Flow Switch Panel</li> </ul>	N/A	N/A	N/A				
		<ul> <li>PA System Panel</li> </ul>	N/A	N/A	N/A				
		Battery backup	Required	Provided	MR				
		<ul> <li>Building Floor Plans</li> </ul>	N/A	N/A	N/A				
20	1	cial Fire Protection Systems for ection of special Risks, if any:	N/A	N/A	N/A				

The fire protection systems provided in the building were checked and found functional at the time of inspection.

The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-65 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/359-374 dated 29.06.2021 in respect of existing building (copy enclosed) shall be implemented by 30.09 .2021 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/GH/SZ/2018/1183 dated 23.05.2018, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer

P.V. Rathee

Asstt. Div. Officer (SRD)

09/08/2021

Sy uso 1/2)

Anosped