

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001


No F 6 / DFS / MS / 2021 / WZ/ 390

Dated 13/08/2021

FIRE SAFETY CERTIFICATE

Certified that **Amber by Eleven Course** located at **Kh. No. 14/26,15/8,15/9,15/10, & 15/26, Village- Singhola, Delhi-110040** comprised of **basement (storage), ground 02 banquet hall and 01 upper floors 14 guest rooms** owned/ occupied by **Amber by Eleven Course** was issued fire safety certificate vide letter no. **F6./DFS/MS/2018/WZ/2037** dated **06/09/2018**. The premise was inspected by the officer concerned of this department on **28.07.2021** in the presence of **Sh. Parvesh Tara** and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy “ **Mixed (assembly+residential)** ” with effect from**13/08/2021**... for a period of **three years** in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on**13/08/2021**... at New Delhi by


(Dharampal Bhardwaj)
Dy. Chief Fire Officer
West Zone

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry”.
7. The owner / occupier shall submit a declaration every year in form “K” provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in
8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

Copy to:-

1. The Manager , Amber By Eleven Course, Kh. No. 14/26,15/8,15/9,15/10, & 15/26, Village-Singhola, Delhi-110040.

INSPECTION REPORT

1. Name & address of the building : Amber by Eleven Course, located at Kh. No. 14/26,15/8,15/9,15/10 & 15/26, Village- Singhola, Delhi-110040.
2. Type of Occupancy : Assembly
3. Building Comprised : Basement+ Ground & One upper floor
4. Type of Case : Renewal
5. Details of previous NOC : F6/DFS/MS/2018/WZ/2037 dated 06/09/2018
6. Fire Safety directives letter No : F6/DFS/MS/BP/2012/2906 dated 09/08/2012
7. Date of inspection :28.07.2021
8. Name of the Inspecting Officers : ADO R.K Sinha
9. Name and designation of officers
from the building side : Sh. Parvesh Tara (Manager)
9. Year of Construction : 2011-12
10. Applicant's letter No. : E mail id dated 26.07.2021

	Minimum Standards on fire prevention and fire safety U/R 33	NBC/ BBL Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	09m	09m	MR
	• Gate width	06m	06m	MR
	• Width of internal road	NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	03	03	MR
	• Basements	03	03	MR
	b. Width of staircases			
	• Upper Floors	1.50 m, 1.80m & 1.52m	1.50 m, 1.80m & 1.52m	MR
	• Basements	1.50 m, 1.80m & 1.52m	1.50 m, 1.80m & 1.52m	MR
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	NA	NA	NA
	d. No. of continuous staircases to terrace	Required	03	MR
	e. Width of Corridor	Required	Provided	MR
	f. Door Size	2.00m	2.80 m	MR

AKS

3	Compartmentation.			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	Required	Provided	MR
		Required	Provided	MR
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
4	Smoke Management System.			
	<ul style="list-style-type: none"> • Basements • Upper floors 	30 a/c per hour	Exhaust fan	MR
		12 a/c per hour	Natural Ventilated	MR
5	Fire Extinguishers			
	<ul style="list-style-type: none"> • Total numbers • Types • ISI marking 	16nos	22 nos	MR
		ABC & Co2	ABC-12 & Co2-10	MR
		Yes	Yes	MR
6	First-Aid Hose Reels.			
	<ul style="list-style-type: none"> • Total numbers on each floor • Length of hose reel hose • Nozzle diameter 	03	03	MR
		30m	30m	MR
		5mm	5mm	MR
	Automatic fire detection and alarming system.			
	<ul style="list-style-type: none"> • Type of detectors • Location of Main Panel • Location of Repeater Panel • Alternate source of power • Hooters' Location 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
8	MOEFA	Required	Provided	MR
9	Public Address System.	NA	Provided	NA
10	Automatic Sprinkler System.			
	<ul style="list-style-type: none"> • Basement • Upper Floor • Sprinkler above false ceiling 	Required	Provided	MR
		NA	Provided	NA
		NA	NA	NA
11	Internal Hydrants			

	<ul style="list-style-type: none"> • Size of riser/down-comer • Number of hydrants per floor • Hose Box 	100mm	Provided	MR
		03	Provided	MR
		03	Provided	MR
12	Yard Hydrants.			
	<ul style="list-style-type: none"> • Total number of hydrants • Hose Box 	Required	Provided	MR
		Required	Provided	MR
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> • Ground Level <ul style="list-style-type: none"> ➤ Discharge of main Pump ➤ Head of Main pump ➤ Number of main pumps ➤ Jockey Pump out put ➤ Jockey pump head ➤ Standby Pump out put ➤ Standby Pump Head ➤ Auto Starting/ Manual stopping ➤ Pump House Access • Terrace level <ul style="list-style-type: none"> ➤ Discharge of pump ➤ Head of the pump ➤ Power Supply ➤ Auto Starting of pump 			
		NA	1620 lpm	NA
		NA	60m	NA
		NA	Provided	NA
		NA	Provided	NA
		NA	Provided	NA
		NA	2280 lpm	NA
		NA	60m	NA
		NA	Provided	NA
		900 lpm	Provided	MR
		40m	40m	MR
		Required	Provided	MR
		NA	NA	NA
14	Captive Water Storage for fire fighting.			
	<ul style="list-style-type: none"> • Underground tank capacity <ul style="list-style-type: none"> ➤ Draw-off connection ➤ Fire service inlet ➤ Access to tank • Overhead Tank capacity 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		20,000 ltr	20,000 ltr.	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA

a

	<ul style="list-style-type: none"> • Fireman's Grounding Switch • Lift Signage 	NA	NA	NA
		NA	NA	NA
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	➤ Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19	Fire Control Room			
	<ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Batter backup • Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were tested/ checked randomly and found in good working conditions.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F.6/DFS/MS/2018/WZ/2037 dated 06.09.2018 renewal under rule 35 of the Delhi Fire Service Rules, 2010 is recommended.

ADDO(BW)
3/8/21

Signature of the Inspecting Officer
Name: - Rajeev Kumar Sinha
Designation:- ADO/BW

DO (BW)
K Sinha
04/08/2021

Detail floor wise acceptance

ADDO(BW)
9/8/2021

DO (BW)
ADDO (BW)
Depto (WZ)
K Sinha
10/08/2021
ADDO (BW)
11/8/2021

put up for compliance