C-35

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/SZ/2021/ 180

Dated.[..3./.g../2021

FIRE SAFETY CERTIFICATE

Certified that the Eating house in the name & Style of M/s Delhi Club House, (A unit of Magique Hospitality Pvt Ltd) at G-03, GF, Sangam Courtyard Mall, (Mini Cinema cum commercial Complex) Plot No 9, Sector 9, R.K Puram, New Delhi 110022. The restaurant is running at ground floor only was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/EH/SZ/2018/1714 dated 23/07/2018. The restaurant premise was re-inspected by the officer concerned of this department on 03/08/2021 in the presence of Sh. Badri Nath Mishra (Manager) and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" Restaurant as above with effect from 1.3.1.2.1/2021 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 12/2021 at New Delhi by

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ) DELHI FIRE SERVICE

Copy to: -

1. The Dy. Health Officer, Public Health Department, South Zone, Green Park, Delhi-110016 (Ref. MHA Portal ID No. 2021071715405 dated 22/07/2021)

 M/s Delhi Club House, (A unit of Magique Hospitality Pvt Ltd) at G-03, GF, Sangam Courtyard Mall, (Mini Cinema cum commercial Complex) Plot No 9, Sector 9, R.K Puram, New Delhi 110022

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

	V	10	
/	1	1	

		INCDECTO				
	1	Name & Address of the Building	ON REPORT			
		of radioss of the Building	M/s Delhi	Club House, (A uni	it of Magique	
			Hospitality	Pvt Ltd) at G-03	GF Sangam	
,			Courtyard,	Plot No 9. Sector 9	, R.K Puram.	
2) -	Type of Occupancy	New Delhi	110022		
3		Building Comprised of	Group-D As	ssembly Building. (Eatin	g house)	
4		Type of Case	3 tier basem	ent, ground plus two upp	per floors	
5		Details of Previous NOC	Renewal			
6		Gire Safety Directions I. (1)	F.6/DFS/MS	S/EH/SZ/2018/1714 date	d 23/07/2018	
7		Fire Safety Directives Letter No Date of Inspection	NII	*		
8		Name of the Inspecting Officers	03/08/2021			
9		Name & Designation of Officers	Sh. Rajesh K	Lumar ADO (BCP)		
	f	rom the building side	Sh. Badri Na	th Mishra (Manager)	and the second s	
10) Y	ear of construction	2015			
11		applicant letter No.	2015 R	estt. located at ground fl	oor only	
			Online No. 2	020022002831 dated 18	/11/2020	
S. N	100000	Iinimum standards on Fire Prevention	OLD NO	C Provided at Site		
	a	nd Fire Safety U/R 33	Requireme			
1	A	ccess to Building.	F6/DFS/MS/	2020/Cinema/508 date	MR/NMR	
		Road width			1 0 //12/2020	
		Gate width	Restt. withi	1 13 000 VC	MR	
		Width of internal road	Iviaii	As above	N/A	
				As above	N/A	
2	N	umber, width, type & arrangement of ex	its.		IV/A	
	a)			11 10 75		
		> Upper floors.	Pro	vided & Maintained by l	Mall	
		Basement floor.	NA N/A	Restt. at Upper GF	NA	
	b)			As above	N/A	
		Upper floors	NA NA	vided & Maintained by I	& Maintained by Mall	
		> Basement floor	N/A	Restt. at Upper GF	NA	
	c)	The state of the states		As above	N/A	
		Fire check door	N/A	rided & Maintained by		
		Pressurization	N/A	N/A N/A	N/A	
	d)	No. of continuous staircase to terrace	Required	One	N/A	
	<u>e)</u>	Width of corridor	N/A	N/A	MR	
3	<u>f)</u>	Door size	2 exits	2.29m & 2.40 m	N/A MR (old case)	
3	Co	mpartmentation.	Prov	rided & Maintained by N	Mall	
		Fire check door.	N/A	N/A		
		 Sealing of electrical shafts. 	N/A	N/A	N/A	
		• Fire rating of shaft door.	N/A	N/A	N/A N/A	
		Water curtain	N/A	N/A	N/A	
		• Fire dampers.	N/A	N/A	N/A	
4	Sm	oke Management system.	Prov	ided & Maintained by M	IN/A	
		Basement		The section of the se	iaii	
		• Upper floors	30 ACPH	As above	MR	
5	Fir	e Extinguishers.	12 ACPH	Exhaust Fans Provided	l MR	
		Total numbers		10 Nos	MR	
		• Types	ABC/CO ₂	ABC-07 & CO ₂ -03	MR	
-		ISI Marking	ISI marked	Provided	MR	
6	1	st Aid Hose Reels.	Provided & Ma	intained by Mall	IVII	
		Total numbers on each floor.	Two	Provided	MR	
		• Length of hose-reel hose.	30m	Provided	MR	
my		Nozzle Diameter	5mm	D '1 1	MR	
7	Aut	omatic fire detection & alarming system	Provided & N	laintained by Mall	1411/	
		1 ype of detectors	N/A	As above	N/A	
		Location of Main Panel	N/A	As above	N/A N/A	
		Location of Repeater Panel	N/A	As above	N/A N/A	
		Alternate source of power	N/A	As above	N/A	
		Hooter's location	N/A	As above	N/A	
				10070	IVIT	

V		,	1	

8	MOEFA	Required	Provided	MR
9	Public Address System	N/A	N/A	N/A
10	Automatic Sprinkler System		& Maintained by M	-
	Basement	N/A	N/A	N/A
	Ground floor.	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.		d & Maintained by N	
	Size of Riser/Down-comer	N/A	N/A	N/A
	 Number of Hydrant per floor 	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
12	Yard Hydrants.			-
	 Total number of hydrants. 	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13	Pumping arrangements.	_		
	Ground Level	Provide	d & Maintained by I	Mall
	Discharge of main pump.	2850 LPM	Provided	MR
	Head of main pump.	70 m	Provided	MR
	Number of main pumps.	02	Provided	MR
	Jockey Pump output.	180 LPM	Provided	MR
	Jockey Pump head.	70 m	Provided	MR
	Standby Pump output.	2850 LPM	Provided	MR
	Standby Pump head.	70 m	Provided	MR
	Auto Starting/Manual Stopping.	Required	Provided	MR
	Pump house access.	Required	Provided	MR
	Terrace Level	Provide	d & Maintained by	Mall
	Discharge of pump.	N/A	As above	N/A
	Head of pump.	N/A	As above	N/A
	Power supply.	N/A	As above	N/A
	Auto starting of pump.	N/A	As above	N/A
14	Captive water storage for fire fighting.	Provide	d & Maintained by	Mall
	Underground tank capacity.	2,00,000 ltrs	Provided	MR
	Draw-off connection.	Required	Provided	MR
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	Required	Provided	MR
	 Overhead tank capacity. 	20,000 ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Provide	ed & Maintained by	Mall
	Pressurization of lift shaft.	Required	As above	MR
	 Pressurization of lift lobby. 	Required	As above	MR
	Communication in lift car.	Required	As above	MR
	• Fireman's switch.	Required	As above	MR
	 Lift signage. 	Required	As above	MR
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	Total area	N/A	N/A	N/A
	 Location 	N/A	N/A	N/A
19	Fire Control Room.	Provide	ed & Maintained by	Mall
*/	Detector system panel.	Required	As above	MR
	Flow switch panel.	Required	As above	MR
	PA system panel.	Required	As above	MR
	Battery backup.	Required	As above	MR
	Building floor plan.	Required	As above	MR
20	Special Fire Protection System for the			
A U	Protection of special Risk, if any.	N/A	N/A	N/A

The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/EH/SZ/2018/1714 dated 23/07/2018, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar **Designation: ADO (BCP)**

approved, F.t. tettel is po a synature of